

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

NOV 10 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
concordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1631936319 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: JR'S HORZ FEDERAL #001	Facility Type: SWD	
Surface Owner: Federal	Mineral Owner:	API No. 30-015-33066

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	10	26S	29E	380'	North	330'	West	Eddy

Latitude 32.0632515 Longitude -103.9792099

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 625 bbls PW	Volume Recovered: 624 bbls PW
Source of Release: Alarm Malfunction	Date and Hour of Occurrence: 11/6/2016 unknown	Date and Hour of Discovery: 11/6/2016 11:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson - NMOCD / Shelly Tucker - BLM	
By Whom? Dakota Neel	Date and Hour: 11/8/2016 10:02 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused when an alarm malfunctioned due to loss of electricity causing the tank to overflow. Vacuum trucks were immediately dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release was contained within a falcon lined facility. Vacuum trucks were dispatched to recover all standing fluids. The liner and equipment were pressure washed. Concho will have the spill site inspected to determine if any possible contamination occurred from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel		Approved by Environmental Specialist: 	
Title: Environmental Coordinator		Approval Date: 11/14/16	Expiration Date: N/A
E-mail Address: dneel2@concho.com		Conditions of Approval:	
Date: 11/11/2016 Phone: 575-748-6933		Attached <input checked="" type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-3987