Submit 3 Copies To Appropriate District	State of New M	evico	Form C-103
Office District I	Energy, Minerals and Nat		June 19, 200
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-005-63348 /
1301 W. Grand Ave., Artesia, NM 882100 BBS Off CONSERVATION DIVISION District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 NOV 0 2 2016 Santa Fe, NM 87505		N DIVISION .ncis Dr.	5. Indicate Type of Lease
		STATE FEE 6. State Oil & Gas Lease No.	
		25891	
SUNDRY NOTICESTAND, REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (FORM C-101) F	OR SUCH	Willow Spring "33"
PROPOSALS.) I. Type of Well: Oil Well Gas Well Other		8. Well Number #3	
2. Name of Operator			9. OGRID Number
	e Energy Inc.	1	149441 10. Pool name or Wildcat
3. Address of Operator 300 N. Marienfield, Ste 400, Midland TX 79701		79701	Pecos Slope Abo
4. Well Location		· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
Unit LetterD:	_660feet from theNorth	line and	660feet from theWestline
Section 33	Township 4S	Range 25S	NMPM County Lea
	11. Elevation (Show whether-DF	R, RKB, RT, GR, etc.)	
12. Check A	ppropriate Box to Indicate Na	ature of Notice, R	Report or Other Data
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS. 🔲 🛛 P AND A 👘 🕔 🛛
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	ГЈОВ 🔲
· · · · ·	П	OTHER:	
OTHER:	eted operations. (Clearly state all p	OTHER: pertinent details, and	give pertinent dates, including estimated dat
OTHER: 13. Describe proposed or comple of starting any proposed wor		pertinent details, and	
OTHER: 13. Describe proposed or comple		pertinent details, and	
OTHER: 13. Describe proposed or comple of starting any proposed wor		pertinent details, and	
OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion.	k). SEE RULE 1103. For Multipl	pertinent details, and	
OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 0-10-16 Notified OCD of move in ar 0-11-16 Spot 38 sx @ 4736'-3015'.	k). SEE RULE 1103. For Multipl	ertinent details, and e Completions: Atta	ich wellbore diagram of proposed completio
OTHER: 13. Describe proposed or completion of starting any proposed wor or recompletion. 0-10-16 Notified OCD of move in an 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of	k). SEE RULE 1103. For Multipl nd rig up. ² 2-7/8" csg. Notified Robert Byrd	oertinent details, and e Completions: Atta of OCD. Perforate 2-	ch wellbore diagram of proposed completio
OTHER: 13. Describe proposed or completed of starting any proposed wor or recompletion. 0-10-16 Notified OCD of move in an 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of ate. With the permission of Robert B	k). SEE RULE 1103. For Multiple nd rig up. 2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate	of OCD. Perforate 2- ed 2-7/8" csg @ 2014	rch wellbore diagram of proposed completio , -7/8" csg @ 3005'. Unable to get an injectio 4'. Unable to get an injection rate into those
OTHER: 13. Describe proposed or completed of starting any proposed worr or recompletion. 10-10-16 Notified OCD of move in and 10-11-16 Spot 38 sx @ 4736'-3015'. 10-12-16 Tag TOC @ 3115' inside of the area with the permission of Robert B perforations either. Notified Robert B	k). SEE RULE 1103. For Multipl nd rig up. ² 2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spot	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen	-7/8" csg @ 3005'. Unable to get an injectio 4'. Unable to get an injection rate into those hent at 3055'-1430', CTOC. WOC overnight
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 0-10-16 Notified OCD of move in an 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of ate. With the permission of Robert B perforations either. Notified Robert B 0-13-16 Tag TOC @ 2016'. Notified cement into perfs @ 2014' and displa	k). SEE RULE 1103. For Multipl nd rig up. 22-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spot d OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen	-7/8" csg @ 3005'. Unable to get an injectio 4'. Unable to get an injection rate into those hent at 3055'-1430', CTOC. WOC overnight
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 0-10-16 Notified OCD of move in and 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of ate. With the permission of Robert B beerforations either. Notified Robert B 0-13-16 Tag TOC @ 2016'. Notified comment into perfs @ 2014' and displa FOC @ 656'. Perforate and circulate	 k). SEE RULE 1103. For Multiple ²2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spotte OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. 	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen	-7/8" csg @ 3005'. Unable to get an injectio 4'. Unable to get an injection rate into those hent at 3055'-1430', CTOC. WOC overnight
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 0-10-16 Notified OCD of move in and 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of ate. With the permission of Robert B beerforations either. Notified Robert B 0-13-16 Tag TOC @ 2016'. Notified comment into perfs @ 2014' and displa FOC @ 656'. Perforate and circulate	 k). SEE RULE 1103. For Multiple ²2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spotte OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. 	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen	-7/8" csg @ 3005'. Unable to get an injection 4'. Unable to get an injection rate into those nent at 3055'-1430', CTOC. WOC overnight
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 0-10-16 Notified OCD of move in and 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of ate. With the permission of Robert B beerforations either. Notified Robert B 0-13-16 Tag TOC @ 2016'. Notified comment into perfs @ 2014' and displa FOC @ 656'. Perforate and circulate	 k). SEE RULE 1103. For Multiple ²2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spotte OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. 	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen	-7/8" csg @ 3005'. Unable to get an injection 4'. Unable to get an injection rate into those nent at 3055'-1430', CTOC. WOC overnight
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 0-10-16 Notified OCD of move in and 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of ate. With the permission of Robert B 0-13-16 Tag TOC @ 2016'. Notified ement into perfs @ 2014' and displa TOC @ 656'. Perforate and circulate 0-14-16 Rig down and move out well	 k). SEE RULE 1103. For Multiple ²2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spotte OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. 	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen	-7/8" csg @ 3005'. Unable to get an injectio 4'. Unable to get an injection rate into those hent at 3055'-1430', CTOC. WOC overnight
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 0-10-16 Notified OCD of move in and 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of ate. With the permission of Robert B 0-13-16 Tag TOC @ 2016'. Notified ement into perfs @ 2014' and displa TOC @ 656'. Perforate and circulate 0-14-16 Rig down and move out well	k). SEE RULE 1103. For Multipl nd rig up. ² 2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spott d OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. Il service unit and P&A equipment	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen	-7/8" csg @ 3005'. Unable to get an injection 4'. Unable to get an injection rate into those nent at 3055'-1430', CTOC. WOC overnight
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 10-10-16 Notified OCD of move in and 10-11-16 Spot 38 sx @ 4736'-3015'. 10-12-16 Tag TOC @ 3115' inside of a term with the permission of Robert B berforations either. Notified Robert B 10-13-16 Tag TOC @ 2016'. Notified comment into perfs @ 2014' and displa FOC @ 656'. Perforate and circulate 10-14-16 Rig down and move out well spud Date:	k). SEE RULE 1103. For Multipl nd rig up. 22-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spott to OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. Il service unit and P&A equipment Rig Release Da	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen ion rate into perforate 726'. Perforated and 726'. Perforated and ter Approved for Physics ter Approved for	-7/8" csg @ 3005'. Unable to get an injection 4'. Unable to get an injection rate into those ment at 3055'-1430', CTOC. WOC overnight tions at 2014'. Squeezed 60 sx Class C I squeeze 50 sx @ 943'-732'. WOC. Tag of well bore only. at conservation of well provention of well provention creatined pending receipt of well provention at conservation creatined pending receipt at conservation of well provention at conservation at a conservation of a conservation at a conservation bore only. At the pending receipt at a conservation at a c
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 0-10-16 Notified OCD of move in and 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of a term with the permission of Robert B berforations either. Notified Robert B 10-13-16 Tag TOC @ 2016'. Notified comment into perfs @ 2014' and displa TOC @ 656'. Perforate and circulate 0-14-16 Rig down and move out well Spud Date:	k). SEE RULE 1103. For Multipl nd rig up. 22-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spott to OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. Il service unit and P&A equipment Rig Release Da	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen ion rate into perforate 726'. Perforated and 726'. Perforated and ter Approved for Physics ter Approved for	-7/8" csg @ 3005'. Unable to get an injection 4'. Unable to get an injection rate into those tions at 2014'. Squeezed 60 sx Class C I squeeze 50 sx @ 943'-732'. WOC. Tag of well bore only. at conservation of well provention creatined pending receipt of well provention at conservation ARTESIA DISTRICT NOV 1 6 2016 DECEIVED
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 0-10-16 Notified OCD of move in and 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of ate. With the permission of Robert B 0-13-16 Tag TOC @ 2016'. Notified Robert B 0-13-16 Tag TOC @ 2016'. Notified comment into perfs @ 2014' and displa FOC @ 656'. Perforate and circulate 0-14-16 Rig down and move out well Spud Date:	k). SEE RULE 1103. For Multipl nd rig up. 22-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spott to OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. Il service unit and P&A equipment Rig Release Da	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen ion rate into perforate 726'. Perforated and 726'. Perforated and ter Approved for Physics ter Approved for	-7/8" csg @ 3005'. Unable to get an injection 4'. Unable to get an injection rate into those ment at 3055'-1430', CTOC. WOC overnight tions at 2014'. Squeezed 60 sx Class C I squeeze 50 sx @ 943'-732'. WOC. Tag of well bore only. Sof well provention of well provention of well provention of well provention creatined pending receipt of well pend
OTHER: 13. Describe proposed or complete of starting any proposed wor or recompletion. 0-10-16 Notified OCD of move in an 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of ate. With the permission of Robert B 10-13-16 Tag TOC @ 2016'. Notified cement into perfs @ 2014' and displa FOC @ 656'. Perforate and circulate 0-14-16 Rig down and move out well Spud Date: hereby certify that the information a	k). SEE RULE 1103. For Multiplend rig up. ² 2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spotter to OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. Il service unit and P&A equipment Rig Release Da	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen ion rate into perforate 726'. Perforated and 726'. Perforated and ter Approved for Physics ter Approved for	-7/8" csg @ 3005'. Unable to get an injection 4'. Unable to get an injection rate into those ment at 3055'-1430', CTOC. WOC overnight tions at 2014'. Squeezed 60 sx Class C I squeeze 50 sx @ 943'-732'. WOC. Tag of well bore only. Sof well provention of well provention of well provention of well provention creatined pending receipt of well pend
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 10-10-16 Notified OCD of move in and 10-11-16 Spot 38 sx @ 4736'-3015'. 10-12-16 Tag TOC @ 3115' inside of rate. With the permission of Robert B boerforations either. Notified Robert B 10-13-16 Tag TOC @ 2016'. Notified comment into perfs @ 2014' and displa FOC @ 656'. Perforate and circulate 10-14-16 Rig down and move out well solutions and move out well solutions and move out well solutions are stignature.	k). SEE RULE 1103. For Multiple nd rig up. ² 2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spott H OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. Il service unit and P&A equipment Rig Release Da bove is true and complete to the be	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen tion rate into perforate 726'. Perforated and ter Approved int bender ter Approved int bender ter Approved int bender tion into perforate and to compare the sender tion into the sender ter ter ter ter ter ter ter ter ter ter	and belief. DATE <u>11/1/2016</u>
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 0-10-16 Notified OCD of move in and 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of ate. With the permission of Robert B berforations either. Notified Robert B 10-13-16 Tag TOC @ 2016'. Notified complete into perfs @ 2014' and displa TOC @ 656'. Perforate and circulate 0-14-16 Rig down and move out well spud Date: Spud Date: hereby certify that the information a SIGNATURE Coursey.	k). SEE RULE 1103. For Multiple nd rig up. ² 2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforate yrd. With OCD's permission, spott H OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. Il service unit and P&A equipment Rig Release Da bove is true and complete to the be	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cent ion rate into perforate 726'. Perforated and ter Arreved int Philosena ter Arreved	-7/8" csg @ 3005'. Unable to get an injection 4'. Unable to get an injection rate into those ment at 3055'-1430', CTOC. WOC overnight tions at 2014'. Squeezed 60 sx Class C I squeeze 50 sx @ 943'-732'. WOC. Tag of woll bore only. squeeze 50 sx @ 943'-732'. WOC. Tag of woll bore only. at commentation of the state of the state of woll bore only. ARTESIA DISTRICT NOV 1 6 2016 Assueementation of the state and belief. DATE <u>11/1/2016</u>
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 0-10-16 Notified OCD of move in and 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of ate. With the permission of Robert B 0-13-16 Tag TOC @ 2016'. Notified Robert B 0-13-16 Tag TOC @ 2014' and displa FOC @ 656'. Perforate and circulate 0-14-16 Rig down and move out well spud Date: Spud Date: hereby certify that the information a SIGNATURE Course Trace Coursey	k). SEE RULE 1103. For Multiple nd rig up. ² 2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforator yrd. With OCD's permission, spott 1 OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. Il service unit and P&A equipment Rig Release Da bove is true and complete to the be TITLEE- E-mail address:	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen cion rate into perforate 726'. Perforated and te: Nerforated and set of my chose very which may be composed set of my chowledge	-7/8" csg @ 3005'. Unable to get an injection 4'. Unable to get an injection rate into those hent at 3055'-1430', CTOC. WOC overnight tions at 2014'. Squeezed 60 sx Class C 1 squeeze 50 sy @ 913'-732'. WOC. Tag of wall bore only greecipt of wall bore only greecipt of wall bore only greecipt ARTESIA DISTRICT ARTESIA DISTRICT NOV 1 6 2016 and belief. DATE <u>11/1/2016</u> PHONE: <u>432-683-4816</u>
OTHER: 13. Describe proposed or completed of starting any proposed word or recompletion. 0-10-16 Notified OCD of move in and 0-11-16 Spot 38 sx @ 4736'-3015'. 0-12-16 Tag TOC @ 3115' inside of a term with the permission of Robert B berforations either. Notified Robert B 10-13-16 Tag TOC @ 2016'. Notified comment into perfs @ 2014' and displa TOC @ 656'. Perforate and circulate 0-14-16 Rig down and move out well solutions are started by the the information a signature of the informatic of the information a signature of	k). SEE RULE 1103. For Multiple nd rig up. ² 2-7/8" csg. Notified Robert Byrd yrd of OCD, immediately perforator yrd. With OCD's permission, spott 1 OCD of tag. Established an inject ced TOC to 1762'. WOC. Tag @ 1 60 sx cement from 60' to surface. Il service unit and P&A equipment Rig Release Da bove is true and complete to the be TITLEE- E-mail address:	of OCD. Perforate 2- ed 2-7/8" csg @ 2014 ted 40 sx class C cen cion rate into perforate 726'. Perforated and te: Nerforated and set of my chose very which may be composed set of my chowledge	-7/8" csg @ 3005'. Unable to get an injection 4'. Unable to get an injection rate into those ment at 3055'-1430', CTOC. WOC overnight tions at 2014'. Squeezed 60 sx Class C I squeeze 50 sx @ 943'-732'. WOC. Tag of woll bore only. squeeze 50 sx @ 943'-732'. WOC. Tag of woll bore only. at commentation of the state of the state of woll bore only. ARTESIA DISTRICT NOV 1 6 2016 Assueementation of the state and belief. DATE <u>11/1/2016</u>

-