Form 3160-5 (June 2015)

#### **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM0275360  6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well					8. Well Name and No. HOLLYWOOD 28 33 W2IP FED COM 1H		
Name of Operator Contact: JACKIE LATHAN     MEWBOURNE OIL COMPANY E-Mail: jlathan@mewbourne.com					9. API Well No. 30-015-43893-00-X1		
3a. Address P O BOX 5270 HOBBS, NM 88241  3b. Phone No. (include area code) Ph: 575-393-5905					10. Field and Pool or Exploratory Area FOREHAND RANCH		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 28 T23S R27E NESE 245	55FSL 450FEL				EDDY COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTI	IER DATA	
TYPE OF SUBMISSION			ТҮРЕ О	ACTION			
☐ Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Producti	ion (Start/Resume)	☐ Water Shut-Off	
	Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclama	ation	☐ Well Integrity	
Subsequent Report     ■	☐ Casing Repair	□ Nev	Construction	☐ Recomp	olete	<b>⊠</b> Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon	□ Temporarily Abandon		Drilling Operations	
	☐ Convert to Injection	tion Plug Back		☐ Water D	Disposal		
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the won following completion of the involved testing has been completed. Final At determined that the site is ready for fi	ally or recomplete horizontally, it will be performed or provide operations. If the operation re bandonment Notices must be fil inal inspection.	give subsurface the Bond No. or sults in a multipl led only after all	locations and measu if file with BLM/BIA e completion or reco requirements, includ	red and true ve  Required sub  mpletion in a re	rtical depths of all pertin osequent reports must be new interval, a Form 316	ent markers and zones. filed within 30 days 0-4 must be filed once	
11/20/16 TD 8 ?" hole @ 102	40'. <b>"</b> Ran 10229' of 7" 26#	F110 LT&C	csg.				
11/21/16 Cmt 1st stage w/475 Tail w/400 sks Class H w/addi Plug down @ 7:00 A.M. 11/21 Tested csg to 7500#, held OK Dropped bomb & opened DV t	tives. Mixed @ 15.6#/g v /16. Set ECP w/4000#.	w/1.18 yd.	_	9#/g w/2.47	, WW O	IL CONSERVATION	
			21 100			DEC 27 2016	
Cmt 2nd stage w/250 sks Class C Neat. Mixed 14.8#/g w/1.32 yd. Plug down @ 9:15 a.m. 11/21/16. Did not circ cmt. Lift pressure 560# @ 3 BPM. Closed DV tool w/5000# for 10 min, held OK. Set mandrel hanger through BOPE w/245k#. Tested BOPE to 5000# & Annular to 2500#. Est TOC @ 1800?							
						)	
14. I hereby certify that the foregoing is	Electronic Submission #	RNE OIL COM	PAÑY, sent to the	carisbad/	'\		
Name (Printed/Typed) JACKIE L		Jg 27 2220	Title REGUL	1		/	
Signature (Electronic S					ED FOR REC	ORD	
	THIS SPACE FO	OR FEDERA					
				10	EC 1/3/16/		
_Approved By			Title		NIV	Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	iitable title to those rights in the	not warrant or e subject lease	Office	BUREAU CAR	OF LAND MALES LISBAD FIELD OFFICE	ENT	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.


(Instructions on page 2) \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*


# Additional data for EC transaction #359170 that would not fit on the form


### 32. Additional remarks, continued


At 10:30 A.M. 11/22/16, tested csg to 5000# for 30 minutes, held OK. Drilled out with 6 1/8" bit.


Chart & Schematic attached.














# MAN WELDING SERVICES, W.

Company Mc ( bown Date 11-31-2016
Lease Hollywood 28/33 wasp Sedeen Founty Jeddy
Drilling Contractor Patterson 243 Plug & Drill Pipe Size X439
Accumulator Pressure: 3000 Manifold Pressure: 1600 Annular Pressure: 1000
Accumulator Function Test - OO&GO#2
To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)
<ul> <li>Make sure all rams and annular are open and if applicable HCR is closed.</li> <li>Ensure accumulator is pumped up to working pressure! (Shut off all pumps)</li> </ul>
1. Open HCR Valve. (If applicable) HCL, 2500.  2. Close annular. Applicable: 23500  3. Close all pipe rams. Open it at this time and close HCR.  1. Open one set of the pipe rams to simulate closing the blind ram.  5. For 3 ram stacks, open the annular to achieve the 50+% safety factor. (5M and greater systems).  6. Record remaining pressure 1800 psi, Test Fails if pressure is lower than required.  a. (950 psi for a 1500 psi system) b. (1200 psi for a 2000 & 3000 psi system)  7. If annular is closed, open it at this time and close HCR.  Recharge: 1220
To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)
<ul> <li>Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:</li> <li>a. {800 psi for a 1500 psi system}</li> <li>b. {1100 psi for 2000 and 3000 psi system}</li> </ul>
<ol> <li>Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)</li> <li>Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.</li> <li>Record pressure drop /(XX) psi. Test fails if pressure drops below minimum.</li> <li>Minimum: a. [700 psi for a 1500 psi system] b. [900 psi for a 2000 &amp; 3000 psi system]</li> </ol>
To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)
<ul> <li>Isolate the accumulator bottles or spherical from the pumps &amp; manifold.</li> <li>Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.</li> </ul>
Open the HCR valve, {if applicable}     Close annular
3. With pumps only, time how long it takes to regain the required manifold pressure.  4. Record elapsed time Test fails if it takes over 2 minutes.  a (950 psi for a 1500 psi system) b (1200 psi for a 2000 & 3000 psi system)

Airl 50 500 Electus 1102



## WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

Lovington, NM • 575-396-4540

Pg.	of	
	 $\sim$	 

Company: MCC 10C1M	D	ate: 11-	21-2016	_Invoice #	B\$3618
Lease: 110/14wood 28/3	WAIP! D	rilling Contractor:_	Parteson	7Rig #	1775
Plug Size &Type:	Drill Pipe Size	X + 39	Tester:	<u>Leddo F</u>	roly a. E
Required BOP:		Installed BOP:			
*Appropriate Casing Valve Must Be Open During BOP Test *			* Check Valve Mu	t Be Open/Disable	d To Test Kill Line Valves
Annular #15  Pipe Rams #12  Blind Rams #13  #11 #10 #9 #7 #8  Pipe Rams #14	#1 ( Mu	# 2 7 #6 \$10 60 #88 #88 #8 d Gauge Valve	Kelly/ Top Drive #17 Vlanual IBOP #16 Pur	10 10 H2	Dart Valve #19 sand Pipe Valve #24  TINW Valve #18  Inp Valve #21

TEST #	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	REMARKS
.1	19	10/10	250	500	Test Pass
	18	10/10	20	5000	Test Pass
3	9.12,88.34,5	10110	250	8000°	Test Pass
4	10.12,8	10/10	250	5000	Test Pass
Ľ,	10,12,7	10110	250	sm	Test Pass
6	14	10110	250	5000	135+ Pass
7	10,15,7	10110	350	3500	Test Pers
Ġ	1413,1,2,6,27	10110	250	5000	Test Pass
4	1413, 26,25,22.6	Desp		Sac	Test Russ
10	20.21.22,33	10110	250	5000	Test Pass
11	2.4	10/10	250	5000	Test Pass
12	17	10110	250	5000	Test Pass
13	16	10/10	350	5000	Test 12,55
		·			