Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

|--|

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Expires: January 31, 20
5. Lease Serial No.
NMLC065478B

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM70945X		
I. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Oth		8. Well Name and No. EMPIRE ABO UNIT 11A					
2. Name of Operator APACHE CORP	Contact: ISABEL HUDSON E-Mail: lsabel.Hudson@apachecorp.com				9. API Well No. 30-015-00748		
3a. Address 303 VETERANS AIRPARK LA MIDLAND, TX 79705	3b. Phone No Ph: 432.81	6. (include area code) 8.1142	ode) 10. Field and Pool or Exploratory Area EMPIRE; ABO (22040)				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 3 T18S R27E 2310FNL 1650FEL					EDDY COUNTY, NM		
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☑ Notice of Intent	☐ Acidize	☐ Dee	epen	☐ Production (Start/Resume)		☐ Water Shut-Off	
_	☐ Alter Casing	□ Ну	draulic Fracturing	Reclam	Reclamation		
☐ Subsequent Report	☐ Casing Repair	☐ Ne	w Construction	Recom	plete	Other	
☐ Final Abandonment Notice	☐ Change Plans	🗖 Plu	g and Abandon	<b>⊠</b> Tempor	rarily Abandon		
ļ	☐ Convert to Injection	🗖 Plu	g Back	□ Water I	Disposal		
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi Apache would like to perform 1 Producing Interval: 5,492-548' Production Casing: 4-1/2? 9.50 Objective: TA wellbore. Currer require time to gather and ana Procedure:  1. POOH with rods and pump  2. Release TAC and POOH so 3. MIRU wireline	operations. If the operation reandonment Notices must be file and inspection.  the following work. Please 7; 5,620-64?  # @ 5,735?  Intly evaluating the upper all yze reservoir data in the canning the and mark juni	sults in a multiped only after all e see attache  ABO for re-c field.	le completion or recorequirements, includents.  ments.  ompletion in the a	area. We	new interval, a Form 316 on, have been completed a Mile City Co ARTEGI FEE	0.4 must be filed once and the operator has  ONSERVATION A DISTRICT  1.3. 201.	
, , , ,	Electronic Submission #	ACHE CORP,	sent to the Carls	bad	•		
Name (Printed/Typed) ISABEL H	UDSON		Title REGUL	ATORY AN	IALYST	<del></del>	
Signature (Electronic S			Date 11/21/2				
<del></del>	THIS SPACE FO	OR FEDERA	AL OR STATE	OFFICE U	SE		
Approved By Ames			Title 52	ET	·	Z- 7-1 Date	
Conditions of approval if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to conduction	itable title to those rights in the ct operations thereon.	subject lease		10			
Title 18 U.S.C. Section 1001 and Title 43 U.S. States any false, fictitious or fraudulent s				willfully to m	ake to any department or	agency of the United	

### Additional data for EC transaction #358548 that would not fit on the form

#### 32. Additional remarks, continued

- 4. RIH with CIBP and set @ 5,488? w/ 35? of cmt
  5. Circulate fluid in the well
  6. Pressure test casing to 500 psi
  7. Record chart and submit for approval

November 18, 2016

Empire ABO Unit # J-11 API # 30-015-00748

Legal Name: Empire ABO Unit #011A

Eddy County, NM

Producing Interval: **5,492-548'**; **5,620-64'** Production Casing: 4-1/2" 9.5# @ 5,735'

<u>**Objective**</u>: TA wellbore. Currently evaluating the upper ABO for re-completion in the area. We require time to gather and analyze reservoir data in the field.

#### Procedure:

- 1. POOH with rods and pump
- 2. Release TAC and POOH scanning tbg and mark junk pipe
- 3. MIRU wireline
- 4. RIH with CIBP and set @ 5,488' w/35' of cmt
- 5. Circulate fluid in the well
- 6. Pressure test casing to 500 psi
- 7. Record chart and submit for approval

## Apache Corp. Actual

LEASE/UNIT:

**Empire Abo Unit** 

WELL:

#J-11A (#011A)

API NUMBER:

30-015-00748

LEGAL DESCRIPTION:

Sec 3, T18S, R27E

FIELD:

Empire (BP)

DATE:

Nov. 08, 2016

BY:

HJG

**COUNTY: Eddy** 

STATE:

**New Mexico** 


Spud: 8/4/59

Rig Release: 8/24/59

KB = 3565'

GL =

12 1/4"



7-7/8"

4-1/2" 9.5# J-55 Set @ 5735' CMT W/ 850 SX TOC @ ??? 6/77: Bradenhead to surface

2 3/8 TBG TAC @ 5437' SN @ 5630'

ABO (3/96)

Perf: 5492-5548' (2 SPF; 112 holes)

ABO (8/59)

Perf: 5620-64' (2 SPF)

3/96: Az w/ 2000 gal 50/50 & BS

TD = 5720'

PBTD = 5685'

Formation Tops:

Queen -

Grayburg -San Andres - 1610

Glorieta - 3020

Abo - 5360

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

# Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if bailed) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.