Form 3160-5 (June 2015)

#### **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

Artesia

FORM APPROVED OMB NO. 1004-0137

Expires: January	
Lease Serial No.	

SUNDRY N	OTICES AND REPORTS ON WELLS
	form for proposals to drill or to re-enter an
abandoned well.	Use form 3160-3 (APD) for such proposals

'''''
6. If Indian, Allottee or Tribe Name
7. If Unit or CA/Agreement, Name and/or No.
 8. Well Name and No. FULLER 14 23 B2LM FED COM 1H
9. API Well No. 30-015-43858-00-X1
10. Field and Pool or Exploratory Area WILDCAT Orral Canyon, BSG / 3354
11. County or Parish, State with.

SUBMIT IN 1	TRIPLICATE - Other inst	ructions on na	nge 2		7. If Unit or CA/Agree	ment, Name and/or No.
	THE POWER WAS		W750 4 TV			
1. Type of Well				8. Well Name and No. FULLER 14 23 B2LM FED COM 1H		
2. Name of Operator MEWBOURNE OIL COMPAN	Contact: , Y E-Mail: jlathan@me	JACKIE LATHA ewbourne.com	AN		9. API Well No. 30-015-43858-0	0-X1
3a. Address P O BOX 5270 HOBBS, NM 88241		3b. Phone No. (i Ph: 575-393-	nclude area code; 5905		10. Field and Pool or E WILDCAT Orral Canyon	BSG /3354
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)				11. County or Parish, S	State South.
Sec 14 T26S R29E SWNW 24	150FNL 330FWL				EDDY COUNTY	′, NM
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICATI	E NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION			TYPE O	F ACTION		
☐ Notice of Intent	☐ Acidize	□ Deepe	n	☐ Product	ion (Start/Resume)	■ Water Shut-Off
_	☐ Alter Casing	☐ Hydra	ulic Fracturing	☐ Reclama	ation	■ Well Integrity
Subsequent Report	Casing Repair	□ New C	Construction	☐ Recomp	lete	Other
☐ Final Abandonment Notice	☐ Change Plans	Plug a	nd Abandon	□ Tempor	arily Abandon	Well Spud
	☐ Convert to Injection	🗖 Plug B	ack	☐ Water D	Pisposal	
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  01/18/17 MI Patterson/UTI #245 & Spud 17 1/2" hole. TD hole @ 467'. Ran 452' of 13 3/8" 54.5# J55 ST&C csg from 0'-39' 13 3/8" 48# J55 ST&C csg from 39' - 452' Cemented with 500 sks Class C w/2% CaCl2. Mixed @ 14.8 #/g w/1.34 yd. Plug down @ 9:30 PM 01/19/17.  Circ 167 sks of cmt to the pit. Tested BOPE to 5000# & Annular to 2500#. FIT test to 10.8 PPG EMW. At 9:30 PM 01/20/17, tested csg to 1500# for 30 mins, held OK. Drilled out with 12 1/4" bit.  Chart & Schematic Attached.  MAR						0-4 must be filed once and the operator has
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #365292 verified by the BLM Well Information System  For MEWBOURNE OIL COMPANY, sent to the Carlsbad  Committed to AFMSS for processing by PRISCILLA PEREZ on 01/31/2017 (17PP0140SE)						
Name (Printed/Typed) JACKIE L.	T	itle REGUL	ATORY			
Signature (Electronic S		Date 01/30/2				
ACCEPTE	D FOR PECOER	R FEDERAL	OR STATE	OFFICE US	SE	
	DAVID & OFSE		Title			Date
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conductive co	not warrant or subject lease	Office				

Title 18 U.S.C. Section 1001 port File 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious of fraudulent statements of the United States are found in the Company of the United States and File 43 U.S.C. Section 1001 port File 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious of fraudulent statements of the United States any false, fictitious of fraudulent statements of the United States any false, fictitious of fraudulent statements of the United States any false, fictitious of fraudulent statements of the United States and States and States are statements of the United States and States and States and States and States are statements of the United States are

# MAN WELDING SERVICES, W.

Company Men Dourne	Date 1/70/17
Lease Fuller 11/3 B7 LM Jedcon 11/4	County Edycard, NM
Drilling Contractor Patter (2) 245	Plug & Drill Pipe Size for the flag 472 1 F
Accumulator Pressure: 3000 Manifold	Pressure: 1500 Annular Pressure: 700

### Accumulator Function Test - OO&GO#2

#### To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)

- Make sure all rams and annular are open and if applicable HCR is closed.
- Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
  - 1. Open HCR Valve. (If applicable)
  - 2. Close annular.
  - 3. Close all pipe rams.
  - 4. Open one set of the pipe rams to simulate closing the blind ram.
  - 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
  - 6. Record remaining pressure 1600 psi. Test Fails if pressure is lower than required.
    - **a.** {950 psi for a 1500 psi system} **b.** {1200 psi for a 2000 & 3000 psi system}
  - 7. If annular is closed, open it at this time and close HCR.

#### To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
  - **a.** (800 psi for a 1500 psi system) **b.** (1100 psi for 2000 and 3000 psi system)
  - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
  - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
  - 3. Record pressure drop 150 psi. Test fails if pressure drops below minimum.
- Minimum: a. [700 psi for a 1500 psi system] b. [900 psi for a 2000 & 3000 psi system]

#### To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
  - 1. Open the HCR valve, {if applicable}
  - 2. Close annular
  - 3. With pumps only, time how long it takes to regain the required manifold pressure.
  - 4. Record elapsed time 15,24. Test fails if it takes over 2 minutes.
- a. {950 psi for a 1500 psi system}
   b. {1200 psi for a 2000 & 3000 psi system}



## WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

Lovington, NM • 575-396-4540

	2		-	
Pa	1	Ωf	Lum.	
ıy.	The boundary of the second of	_ OI		

company: Mewiczune	Date:/	// /Invoice #	683767
Lease: FULLET LY/23 BUM Fed com		Pullerson Rig#	245
Plug Size &Type:	I Pipe Size 4471	Tester: Junior Or	· toyu
Required BOP:	Installed BOP:		
Annular #15 Pipe Rams #12 #1 #11 #10 #9 Pipe Rams #14  Pipe Rams #14	#26 #5 #6	Kelly/ Top Drive  #22 #3	Dart Valve #19 tand Pipe Valve #24
Casing			

TEST #	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	REMARKS
	27,31,6,28,7	10min	250	5000	Pass
2	30,28,26,6,7	ROMP		5000	Pass
3	1,2,29,6,7	10 min	250	5000	pass
U	20, 4, 62,23	10 min Bu	310	5000	Tamalo Pest South of Paul (Pass)
5	24	5,00	720	5000	Pass
6	17	I is a	250	5000	Pass
7	16	5min	250	5000	Pasi
B	19	5mla	2.50	50as	Pass
9	18	Simil	750	5m	Small can sale allo Soude of igiting
94	18	5,000	<b>マシ</b> )	5000	us/ keduly (bed off.
70	19	5min	2 Sm	$\Sigma \omega \omega$	worked valve Smill leak workedages
90	18	5min	<b>でか</b> り		
10	Herm	5	سهر	500	
10	12,9,4,35,88	10min-		5000	The second section of the section of the section of the second section of the section of t
10	19 cet 39	5min			Feecs
	18 ce 739	5min	250	5000	Pass
12	12,9,4,3,5,8B	10min	250	500	Pass
13	12,9,7	lomin.			Pass
, ,	12,10,78	lom:n		5000	



### WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

Pg. 2 of 2

Lovington, NM • 575-396-4548

نناطهن					
TEST #	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	REMARKS
15	lu	bonin	250	5000	Pass ·
16	15,10,8 13,10,3,4,5	bmin	250	2500	Pass Pass
17	13, 10, 3, 4,5	10 Min	250	5000	Pass
					·
	<u> </u>	-			
			<del></del>		
	1 1000				
<b>  </b>		·			
L					







