Form 3160-5 (August 2007) OCD-ARTESIA

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Lease Serial No. NMLC069108

abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allotted	e or Tribe Name	
SUBMIT IN TRII	PLICATE - Other instruction	s on reverse side. CON	ISERVAL G. If Unit or CA/Ag	reement, Name and/or No.	
1. Type of Well		MOTEON	0.17.11.1		
Oil Well Gas Well 🖸 Oth	er: INJECTION	MAY 1	1 2017 8. Well Name and N POKER LAKE U		
Name of Operator BOPCO LP	ACIE J CHERRY pet.com	9. API Well No. 30-015-26084	9. API Well No. 30-015-26084		
3a. Address P O BOX 2760 MIDLAND, TX 79702	Ph	Phone No. (include area code 1: 432-683-2277	10. Field and Pool	; DELAWARE-BS	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Paris	11. County or Parish, and State	
Sec 33 T23S R30E Mer NMP	EDDY COUN	TY, NM			
12. CHECK APPE	ROPRIATE BOX(ES) TO IN	DICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
(.	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	■ Well Integrity	
Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	□ Temporarily Abandon		
	Convert to Injection	□ Plug Back	■ Water Disposal		
BOPCO, LP respectfully subm disposal well to an Observation. The Poker Lake Unit #71A will Delaware formation due to his obtained by monitoring the sure submitted to the BLM by Sundigustification and details of this. The subject well was unsucce well was re-entered, the 9-5/8 authority was granted 06/10/2	Indee pressure and obtaining a lry Notice. Please refer to BO observation program. N ssfully drilled to the Delaware csg cut, and the hole sidetra 005 per NMOCD Administrati	PCO, LP?s 2016 Plan of a Justification a series in May 1989 by another acked and reompleted. In ve Order SWD-983. The	Development for POD operator. The operator well was then	PI-NM®O 5/17/17 epted for record NMOCD	
Meniter WellShut-		d until 02/02/3	2018 with QAO &	Macheal	
14. Thereby certify that the foregoing is	Electronic Submission #3398	48 verified by the BLM We CO LP, sent to the Carlsb	ell Information System ad		
Name(Printed/Typed) TRACIE J CHERRY		Title REGUI	Title REGULATORY ANALYST		
Signature (Electronic S	Submission)	Date 05/20/2	2016 .		
	THIS SPACE FOR F	FEDERAL OR STATE	OFFICE USE		
Approved By Klwa	\$2	Title	-PET	Date 5/3/1	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conductive the	litable title to those rights in the subj	warrant or ect lease Office	CFO		

Additional data for EC transaction #339848 that would not fit on the form

32. Additional remarks, continued

completed as an SWD in the Delaware in August 2005, injecting through perforations 4470-5850?. The attached wellbore diagram shows the perforated intervals, casing detail and formation tops. Cement on 5-1/2? casing is 3212? by temp survey, and 13-3/8? csg circulated to surface. A successful MIT was performed 10/21/2015, results submitted to the BLM via sundry notice. Annual bradenhead tests were also performed and witnessed by NMOCD.

LEASE: **POKER LAKE UNIT** WELL#: 71-A FIELD: NASH DRAW LOCATION: SL: 660' FNL & 1980' FWL, SEC 33, T23S, R30E BHL: 710' FNL & 2030' FWL, SEC 33, T23S, R30E **COUNTY: EDDY** ST:NM API: 30-015-2608 SURFACE CASING 3364' KB: SIZE: 20" GL: 3349' WT: 94# 3/25/1989 SPUD DATE: SET @: 618 618 COMP DATE: 05/90 P&A SX CMT: 1675 **RE-ENTRY:** 7/10/2001 CIRC: YES COMP RE-ENTRY: 7/22/2001 TOC: SURF **HOLE SIZE:** 26" 0-618 INTERMEDIATE CASING 3212 TOC 3212' (TS) SIZE: 13-3/8" WT: 68 & 72# EOT & PKR LOCATION @ 4417' 3753 2-7/8" 6.5# SET @: 3753' SX CMT: 3000 CIRC: YES PERF TOP 4470' TOC: SURF 5796 DVT @ 5790' **HOLE SIZE:** 17-1/2" 618-3753' KOP 5967' 5967 **PRODUCTION CASING** SIZE: 9-5/8" 0-6213' POH 6/6/90 WT: 47 & 53# PERF BTM 6737' 6209 PLUG SET @: 11,145 6390 SX CMT: 2100 CIRC: CIBP @ 7300' w/37' cmt LBC "U" SAND PERFS 7335-40' (5 HO TOC: 12-1/4" 3753-11,145 **HOLE SIZE:** 91.6 LBC "Y" SAND PERFS 7550-58' (16 HC EOT @ 7117' LINER 7900 PLUG SIZE: 5-1/2' 8100 WT: 23# PB 7796 SET @: 14.822' TD 7880' SX CMT: 300 CIRC: NO Formation Tops per Completion Repo TOC: 10,952' Lamar Limestone 3752 **HOLE SIZE:** 8-1/2" 11,145-14,822 Delaware 3779 4710 Cherry Canyon 4831 Manzanita SIDE TRACK Brushy Canyon 5977 SIZE: 5-1/2" 10,952 Bone Spring 7648 WT: 15.5 & 17# SET @: 7880' 11,050 PLUG SX CMT: 2112 11,200 CIRC: NO TOC: 13,100 PLUG **HOLE SIZE:** 7-7/8" 5998-7880 13,150 PERFS 13202-14266 13202-206, NO TREAT 13317-332, A/3kg Mod 202 14,516-522, 471-500', 341-359', no treat 14,226', A/18.6 kg 7-1/2" **VERTICAL** Updated: PBTD: 14,779' Author: KRA TD: 14,822' Engr: MLL

Order of the Authorized Officer BOPCO/XTO

Poker Lake Unit – 71A, API 3001526084 T23S-R30E, Sec 33, 660FNL & 1980FWL May 03, 2017

Records indicate no disposal volume injected since 02/2015.

The New Mexico Bureau of Land Management (BLM) Policy guideline limits total idle well status to five years. With sufficient documentation and justification via subsequent sundry reporting the AO may authorize renewal on a year-to-year, case-by-case basis.

Operator's designation of Monitoring Well status (MW) indicates the well is a service well for "Delaware Formation Observation and Monitoring". BLM accepts conversion from a Delaware WDW to a Shut-In Delaware Formation Observation/Monitoring Well.

05/03/2017 - Beginning 02/2015 until 02/03/2018 (the BLM designated renewal date) SI status accepted for record with this attached order of authorized officer. pswartz

To extend SI compliance beyond the BLM designated renewal date, submit a subsequent sundry listing:

- 1. Provide BLM with an (when available) electronic copy (Adobe Acrobat Document) of a cement bond log record from Packer depth or below to the top of cement with Opsig casing pressure. Attach the CBL to a psystem a psystem psystem email.
- 2. Provide a witnessed recent MIT record (taken in the last year) of the tubing/casing annulus.
 - i) The minimum MIT pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with a minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need reduction).
 - ii) Verify that all annular casing vents are open to the surface atmosphere during this pressure test.
 - iii) Document the pressure test on a one hour full rotation chart recorder (calibrated within the last 6 months) registering within 35 to 75 per cent of its full range. Greater than 10% pressure leakoff viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict status approval.
- 3. Maintain the annulus full of packer fluid at atmospheric pressure. Installation of equipment that will display a continuous open-air packer fluid level above the tubing/casing annulus vent is required.
- 4. Notify the BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov</u>>, cell phone 575-200-7902) to arrange for approval of the annular monitoring system.

- 5. Loss of packer fluid above five barrels per month indicates a developing problem. Submit a NOI plan of correction compliance for BLM approval.
- 6. Submit dated reports of each taken stabilized inactive shut-in wellhead and annulus pressure, fluid level, and tubing psig from no more than 20-30 feet above the injection packer on a request for renewal subsequent sundry.
- 7. Report operator's reasoning and conclusions drawn from the monitoring information.
- 8. If you do not comply as noted, you shall be issued an Incident of Noncompliance (INC) in accordance with 43 CFR 3163.1(a). Failure to comply with the INC may result in assessments as outline in 43 CFR 3163.1, and may also incur civil penalties (43CFR 3163.2). All self-certified corrections must be postmark no later than the next business day after the prescribed time frame for correction.
- 9. Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 days.
- 10. A person contesting a decision shall request a State Director review of the Written Order. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quincy Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.