Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well ☐ Oil Well ☐ Gas Well ☑ Other: UNKNOWN OTH					8. Well Name and No. OBS FEDERAL C	
2. Name of Operator Contact: ANTHONY P TRINKO					9. API Well No. 8 0 0 30-015-20576	
3a. Address 2 N. NEVADA AVENUE COLORADO SPRINGS, CO	3b. Phone No. (include area code) Ph: 719-520-4557			10. Field and Pool or Exploratory Area WASHINGTON RANCH		
4. Location of Well <i>(Footage, Sec., 1</i> Sec 35 T25S R24E Mer 6PM		11. County or Parish, State EDDY COUNTY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTI	HER DATA
TYPE OF SUBMISSION	YPE OF SUBMISSION TYPE OF ACTION					
<ul><li>☑ Notice of Intent</li><li>☐ Subsequent Report</li><li>☐ Final Abandonment Notice</li></ul>	t Report ☐ Alter Casing  ☑ Casing Repair		☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction ☐ Plug and Abandon ☐ Plug Back		ion (Start/Resume) ation plete rarily Abandon Disposal	☐ Water Shut-Off ☐ Well Integrity ☐ Other
13. Describe Proposed or Completed Op If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involvec testing has been completed. Final Al determined that the site is ready for f BLM Bond No. on File: 400JF	ally or recomplete horizontally, rk will be performed or provide I operations. If the operation re bandonment Notices must be fil inal inspection.	give subsurface the Bond No. on sults in a multiple	locations and measu file with BLM/BIA e completion or reco	ired and true ve A. Required sul completion in a r	ertical depths of all pertii bsequent reports must be new interval, a Form 316 n, have been completed	nent markers and zones. filed within 30 days fo-4 must be filed once and the operator has
Planned Procedure:  The existing tubing and packe into the well with a bridge plug casing for integrity.  If the casing holds pressure, we tools in the well and then run the tubing in the head and per	<ol> <li>The plug will be set an</li> <li>we will trip out the tubing a</li> </ol>	d pressure wil	l be applied to to	est the	CONDITIONS  NM OIL CO	ACHED FOR S OF APPROVAL  ONSERVATION  ODER OF THE PROPERTY OF
the tubing in the head and per		uther "	NGE a		_	<b>1 6</b> 2017
14. I hereby certify that the foregoing is  Name (Printed/Typed) KEVIN W	strue and correct. Electronic Submission # For EL PASO NAT Committed to AFMSS for	373965 verifie URAL GAS CO	MPANY, L, sent DEBORAH MCK	to the Carlsb INNEY on 04	ad system	ERV
Signature (Electronic Submission)			Date 04/26/2	<b>APP</b> F	ROVED	
	THIS SPACE FO	OR FEDERA	L OF STATE	OFFICE U	SE	
Approved By  Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to condition of the states any false, fictitious or fraudulent	e subject lease	Title Office	JUN PRA FAN OF LA	6, 2017 Ward	Date agency of the United	
States any raise, fictitious or fraudulent	statements or representations as	to any matter wi	unin us jurisdiction.	OUITOOUR	I ILLU UTTIUE	


#### Additional data for EC transaction #373965 that would not fit on the form

#### 32. Additional remarks, continued


If the casing does not hold pressure, we will isolate the hole(s) with tubing on a packer. The hole(s) will be squeezed with cement which will be drilled out the next day. The integrity of the casing will then be verified by a pressure test.

If the pressure test following the squeeze is successful, we will pull the tubing and run casing inspection tools in the well. When logging operations are complete, we will trip the tubing in and retrieve the plug. The well will be set up and tubing and a packer will be run in for final configuration.

The casing will be filled with packer fluid, the packer will be set, and the tubing will be landed in the head. A successful MIT will then be performed before the well is placed back in service.



### Annular Packer Fluid Level above the casing vent, open to the air, and visible.



## **Conditions of Approval**

# El Paso Natural Gas Company Washington Ranch Storage OBS - 01, API 3001520576 T25S-R24E, Sec 35, 2080FNL & 660FWL June 06, 2017

- 1. Within 90 days of these conditions of approval for the processed Electronic Submission #373965 notice of intent begin wellbore operations
- 2. Operator is required to have the BLM approved NOI procedure with applicable conditions of approval on location for this workover operation.
- 3. Before casing or a liner added, replaced, or repaired prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Subject to like approval by the New Mexico Oil Conservation Division.
- 5. Squeeze with Class "C" cement mixed 14.8#/gal, 1.32 ft<sup>3</sup>/sx, 6.3gal/sx water.
- 6. Surface disturbance beyond the existing pad shall have prior approval.
- 7. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 8. Functional H<sub>2</sub>S monitoring equipment shall be on location.
- 9. 3000 (3M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. Blind ram(s) and pipe ram(s) designed to close on all workstring diameters used is required equipment. A manual BOP closure system (hand wheels) shall be available for use regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) employed when needed for reasonable well control requirements.
- 10. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 11. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log from 6800 or below to top of cement taken with 0psig casing pressure reflecting cement bond conditions left after this procedure. Attach the CBL to a pswartz@blm.gov email.
- 12. The well is within the BLM designated Critical Cave Karst Area requiring three casing strings with cement circulated on each. This well completion has only surface and production casings. It is critical to protect the C.C.K.A. The operator shall construct and maintain an annular motoring system (described below).

#### Well with a Packer - Operations

- 1) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established. Repair that seal when replacing more than five barrels of packer fluid within 30 days.
- 2) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need reduced). Verify all annular casing vent valves are open to the surface during this pressure test. An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- 3) Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval.
- 4) Arrange 24 hours before the test for BLM to witness. In Eddy County, phone 575-361-2822. Leave a voice mail or email with the API#, workover purpose, and a contact information.
- 5) Relate the MIT activity on subsequent Sundry Form 3160-5. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness, and date of notification. NMOCD may retain the original recorded MIT chart.
- 6) Submit a (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test. Include workover activity, and the setting depths and descriptions of installed equipment.
- 7) List (by date) descriptions of daily activity previously unreported.
- 8) NMOCD Administrative Order compliance is required. Submit documentation of that authorization.
- 9) Report unexplained significant variations of rate or pressure within 5 days of notice.
- 10) Monitor the casing/tubing annulus for communication with injection fluid or loss of casing integrity. A BLM inspector may request verification of a full annular fluid level at any time.
- 11) Maintain the annulus full of packer fluid at atmospheric pressure. Installation of equipment that will display continuous open to the air fluid level above the casing vent is required for this critical cave karst area well.
- 12) Notify the BLM's authorized officer ("Paul R. Swartz" < pswartz@blm.gov>, cell phone 575-200-7902) before injection begins to arrange for approval of the annular monitoring system.
- 13) Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Carlsbad Field Office, Petroleum Engineering within 5 days.
- 14) A suggested format for monthly records documenting that the casing annulus is fluid filled is available from the BLM Carlsbad Field Office.
- 15) Gain of annular fluid requires notification within 24 hours. Cease injection and maintain a production casing pressure of 0 psia. Notify via phone #575-361-2822.