NMOCD NM OIL CONSERVATION
ARTESIA DISTRICT Fam 3160-5 (4ph) 2004) FORM APPROVED OM B Ho. 1004-0137 Experse Mursh 31, 2007 UNITED STATES DEPARTMENT OF THE INTERIORAUG 1 4 2017 5. Less Scrally SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or the CELLED ebandoned well. Use Form \$160 - 3 (APD) for such proposals. 7. If Unit or CN/Agreement, Name and/or No. SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well Oil Well Ges Well Other 1. Well Name and No. M3M Fe 2. Name of Operator 9. API Well No. la Address 30-005-( 10. Field and Pool, or Exploratory Area Pecos Slope 11. County or Parish, State Chaves, NM REPORT, OR OTHER DATA 12-CHECK APPROPRIATE BOXIES) TO INDICATE NATURE OF NOICE TYPE OF SUBMISSION TYPE OF ACTION Acidine Production (Start/Resume) Water Shut-Off Notice of Intent Well Integrity Alter Casing Fracture Trest Reclamation Casing Repeat New Construction Subsequent Report Change Plans Plug and Abandon Temporarily Abandor Final Abandonment Notice Plus Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give substantiace locations and measured and true vertical depths of all pertinent markers and zones. Attach the Band under which the work will be performed or provide the Band No. on file with BLM/BIA. Required subsequent reports shall be filed within 10 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be illect once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) MIRU P3A Unit. 1 Set CIBP @ 2844', cap w/ 705x cmT. TOC 2000' TAG 2. PDH, RIH. WI PKR perf @ 1900'. 405x woc TAG 1650'. 3. PuH perf 1600', pump SDSX WOC. TAG 1300' (8.5/8 snoeplug) 4. PuH perf 1100' SqZ 405X WOC TAG. 900'. 5. Put perf 650' 592 4'12"-8518" to surface


Tille P3 A Specialist
Due 08/03/2017
OR STATE OFFICE USE
THE THOLEUM ENGINEER CANS AS 2017 B
SE Office

Title 18 U.S.C. Section 1001 and Tide 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to 'any department or agency of the Dutter States any false, fletitious or fraudulent statements or representations as to arrymatter within its jurisdiction.

(Instructions on page 2)

APPROVED FOR 3 MONTH PERIOD NOV 03 2017

SEE ATTACHED FOR CONDITIONS OF APPROVAL



## BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90<sup>th</sup> day provide the BLM Roswell Field Office (RFO), prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.
- 2. <u>Notification:</u> Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. <u>Dry Hole Marker:</u> All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10 feet in length, 4 feet above the ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.