<u>District I</u> 1625 N. French Dr., Hobby, NM 88240	State of New Mexico	Form C-101 Revised July 18, 2013
Phone (575) 393-6161 Fax (575) 393-0720 District II	Energy Minerals and Natural Resources	Kernsed July 18, 2013
811 S. First St., Artesia, NM 88210 Phone. (575) 748-1283 Fav. (575) 748-9720 District III	Oil Conservation Division	<b>AMENDED REPORT</b>
1000 Rio Brazos Road, Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170	1220 South St. Francis Dr.	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505 Phone (505) 476-3460 Fax (505) 476-3462	Santa Fe, NM 87505	

## APPLICATION FOR PERMIT TO DRILL, RE-ENTER, DEEPEN, PLUGBACK, OR ADD A ZONE

			<sup>2</sup> Operator Name Cimarex Energy 202 S. Cheyenni		2 OGRID Number 162683 2 API Number						
				30-015-33229	)						
Prop	* Property Code Property Name #2							#2	Vell No.		
				<sup>7.</sup> Si	irface Location	1					
UL - Lot L	Section 32	Township 24S	Range 26E	Lot Idn	Feet from 1975	N/S Line South	Feet From 1200	E/W Line West	County Eddy		
				* Propos	ed Bottom Hol	e Location					
UL - Lot	Section	Township	Range	Lot ldn	Feet from	N/S Line	Feet From	E/W Line	Совязу		
	L			<sup>9.</sup> Pc	ol Information	)	DHC	4818			
	* Pool Information     DHCH8/8       Pool Name       Purple Sage Wolfcamp Gas & While City Penn Gas										

Pool Name Purple Sage Wolfcamp Gas & While City Penn Gas

### Additional Well Information

<sup>11</sup> Work Type PB	12	Well Type Gas	<sup>13</sup> Cable/Rotary	14 Leas State		<sup>15</sup> Ground Level Elevation 3398 <sup>1</sup>
<sup>16</sup> Multiple		posed Depth TD 11057'	<sup>18</sup> Formation Cisco Canyon/ Wolfcamp	<sup>13</sup> Cent	ractor	<sup>2</sup> Spud Date
Depth to Ground water 300'	L	Distance fro	m nearest fresh water well		Distance to n	earest surface water

We will be using a closed-loop system in lieu of lined pits

<sup>21.</sup> Proposed Casing and Cement Program

Type	Hole Size	Casing Size	Casing Weight/ft	Setting Depth	Sacks of Cement	Estimated TOC			
Surface	17 1/2"	13 3/8″ J-55	54.5#	361'	980 sks	Surface			
Intermediate	12 1/4*	9 5/8" NS110HC	40#	1682'	1100 sks	Surface			
Production	Production 8 3/4" 5 1/2" P-110		17# 11815'		2090 sks	580'			
Casing/Cement Program: Additional Comments									

22.	Pro	posed	Blowe	out Pr	evention	Program	

Туре	Working Pressure	Test Pressure	Manufacturer

best of my knowledge and belief.	ation given above is true and complete to t	OIL CONSERVATION DIVISION			
I further certify that I have con 19.15.14.9 B) NMAC , if app Signature	uplied with 19. 8.14.9 (A) NMAC 🛛 and dicable.	Approved By: Raymond & Podamy			
Printed name: Amithy Oran	wford U	Title: Greplonist.			
Title: Regulatory	Analyst	Approved Date: 9-5-20/7 Expiration Date. 9-5- 19			
E-mail Address: acrawford@	Jcimarex.com				
Date: 9/1/2017	Phone: 432-620-1909	Conditions of Approval Attached			

\*\* All Casing Previously set\*\*

District1 1625 N. French Dr., Holbs, NM 88240 Phone: (575) 333-6161 Fax: (575) 393-0720 District11 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District111 1000 Rio Brazos Road, Aztee, NM 87410 Phone (505) 334-6178 Fax: (505) 334-6170 District117 1220 S. St. Francis Dr., Santa Fe, NM 87505 Phone. (505) 476-3460 Fax: (505) 476-3462

1 . ...

•

State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-102 Revised August 1, 2011 Submit one copy to appropriate District Office

AMENDED REPORT

-

## WELL LOCATION AND ACREAGE DEDICATION PLAT

1	015-33229			98220	e	Purple Sage Wolfcamp Gas				
<sup>†</sup> Property (	Code			NN	* Property Name NM DD State Com				<sup>6</sup> Well Number 2	
<sup>7</sup> OGRID 162683	N0.	* Operator Name * Elevat Cimarex Energy Co of Colorado 3398'						Elevation 98'		
					<sup>10</sup> Surface I	Location				
UL ar lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East	West line	County
L	32	245	26E		1975	South	1200	Wes	1	Eddy
			" Bo	ttom Hol	le Location If	Different Fron	n Surface			
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East	/West line	County
<sup>12</sup> Dedicated Acres 640	<sup>13</sup> Joint of	r Infill 🛛 🛱 C	onsolidation	Code <sup>15</sup> Or	der No.					

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

to compare advectation of the second s	CONTRACTOR C	when we	- April 10 - Contraction of the	
18				" OPERATOR CERTIFICATION
				A I hereby certify that the information contained herein is true and complete
				to the best of my knowledge and belief, and that this organization either
				owns a working interest or unleased mineral interest in the land including
				the proposed bottom hole location or has a right to drill this well at this
				beation pursuant to a contract with an course of such a mineral or working
				interest, or to a voluntary pooling agreement or a compulsory pooling
	L			one or here to go the enternal by the displacent
				ANN 1 Mathe 9/1/2017
				Suprature Date
				Amithy Crawford
				Printed Name
				acrawford@cimarex.com
				E-mail Address
				<b>"SURVEYOR CERTIFICATION</b>
				I hereby certify that the well location shown on this
1000' NIM	DD State Com #2			plat was plotted from field notes of actual surveys
1200' NM	DD State Colli #2			made by me or under my supervision, and that the
				same is true and correct to the best of my belief.
				Date of Survey
				Signature and Seal of Professional Surveyor:
75			1	
16				
				Certificate Number

 District.1

 1625. N. Trench. Dr., Hobbs, NM 88240

 Phone. (575) 393-6161. Fax. (575) 393-0720

 District.11

 811.5. First.St., Artesia, NM 88210

 Phone. (575) 748-1283. Fax. (576) 748-0720

 District.12

 1000 Rob Brazos Road, Aztec, NM 87410

 Phone. (505) 334-6178. Fax. (505) 334-6170

 District.11X

 1220 S. St. Francis Dr., Santa Fe, NM 87505

 Phone. (505) 476-3460. Fax. (505) 476-3462

,

,

# State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-102 Revised August 1, 2011 Submit one copy to appropriate District Office

☐ AMENDED REPORT


## WELL LOCATION AND ACREAGE DEDICATION PLAT


1	API Numbe 015-33229			<sup>2</sup> Pool Code 87280		<sup>3</sup> Pool Name While City (Penn) Gas			
<sup>4</sup> Property (	<sup>4</sup> Property Code <sup>5</sup> Property Nanue NM DD State Com						2	Vell Number	
<sup>7</sup> OGRIÐ 162683						1	<sup>9</sup> Elevation 198'		
Laut					" Surface L	ocation			
UL or lot no.	Section 32	Township 24S	Range 26E	Lot Idn	Feet from the 1975	North/South line South	Feet from the	East/West line West	County Eddy

	L	32	245	26E		1975	South	1200	West	Eddy		
-	"Bottom Hole Location If Different From Surface											
ſ	L or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County		
		10	- IOn 14									
	<sup>2</sup> Dedicated Acres	i Doint o	r Infill  ** C	Consolidation	Code <sup>1</sup> *O	der No.						
1	640									J		

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

14	- Andrewski (1996) - Andrewski (19 Andrewski (1996) - Andrewski (1996) Andrewski (1996) - Andrewski (1996)	- Nillian	. ************************************	<ul> <li>AMA - T. Lador - TCL Silvers Advances</li> </ul>	" OPERATOR CERTIFICATION
1		1			There by certify that the information contained herein is true and complete
					to the best of my knowledge and belief, and that this organization either
1					owns a working interest or unleased romand interest in the band ischolog
					the proposed botion hole location or has a right to drill hits well at this
li -					Jocation pursuon to a controct with an correct of such a mineral or working
					interest or to a voluatory pooling agreement or a compulsory pooling
					order herelofore enjered by the disiston.
					MAAKIA MULT 91/2017
8					Bratterine Date
8					
					Amithy Crawford
li -					
					acrawford@cimarex.com
					E-mail Address
ľ <u></u>					 
					"SURVEYOR CERTIFICATION
					I hereby certify that the well location shown on this
	1200'	NM	DD State Com #2		plat was plotted from field notes of actual surveys
<b> </b>	1200	9	DD blace Colli #2		made by me or under my supervision, and that the
					same is true and correct to the best of my belief.
<u> </u>					Date of Survey
Į.		2			Signature and Seal of Professional Surveyor.
0		67			
P					
l					
					Certificate Number
l					L TEBLAC INGROU







CONFIDENTIAL. August 24, 2017 Production Operations – Carlsbad Region, Permian Basin New Mexico DD State Com #2 - Cisco Canyon and Wolfcamp (Ciscamp) Proposed Commingling Allocation Factors. Eddy County, NM

Appendix C: Recompletion Procedure – New Mexico DD State #2

Well Data	
КВ	23'
TD	11,815'
РВТО	11,814'
Casing	13-3/8" 54.5# J-55 @ 361'. Cmt'd w/ 400 sx, cmt to sfc 9-5/8" 40# J-55 @ 1,682'. Cmt'd w/ 1,775 sx, cmt circ 5-1/2" 17# P-110 @ 11,734'. Cmt'd w/ 930 sx, cmt @ 580'
Tubing	2-3/8" 4.7# L-80 8rd, EOT @ 10,845'
Proposed RC Perfs	Wolfcamp (8,372' – 9,667') & Cisco Canyon (9,884' – 10,074')

## PROCEDURE

- 1. Pull test anchors, replace as necessary before rig arrival.
- 2. MIRU pulling unit, rental flare, and choke manifold.
- 3. Hold safety meeting and perform JSA, discuss risks.
- 4. Kill well with FSW as needed. Observe all pressures on well and note detail in report.
  - a. NOTE: Treat all water throughout job with biocide.
  - b. Brendan McCalpin 406-498-6647
- 5. MIRU WSU. Ensure WSU is set and balanced on rig mats before proceeding.
  - a. Everyone on location has the ability to use STOP WORK AUTHORITY to shut down operations should a problem or concern arise.
- 6. ND WH and flowline, NU 5,000 psi hydraulic BOPs.
- 7. PU tubing, release 5-1/2" versa-set packer @ 11,080' (1/4 turn right hand release).
- 8. POOH w/2-3/8" tubing & packer. Lay down packer and tubing.
- 9. MIRU WL and 5-1/2" 17# CIBP.
- 10. Set CIBP @ +/- 11,092'.
- 11. Mix 25 sxs class H cement.
- 12. PU RIH with dump bailor on WL and dump bail cement on top of CIBP.
- 13. PU 2<sup>nd</sup> CIBP and set @ +/- 10,800'.
- 14. RDMO WL company.



.

CONFIDENTIAL. August 24, 2017 Production Operations – Carlsbad Region, Permian Basin New Mexico DD State Com #2 - Cisco Canyon and Wolfcamp (Ciscamp) Proposed Commingling Allocation Factors. Eddy County, NM

- 15. MIRU pump truck and pressure test CIBP, Cmt, and casing to 8,500 psi on a chart for thirty minutes observing leak-off.
  - a. Leak-off can be no more than 10%.
  - b. Report pressure back to Midland office.
  - c. If pressure test is successful proceed with Ciscamp completion.
- 16. ND 5k BOPs.
- 17. NU two 10k frac valves and flow cross.
- 18. MIRU water transfer with frac tanks to contain water pumped from frac ponds.
  - a. Test frac valves and flow cross prior to fracing to 10,000 psi.
- 19. MIRU WL with full lubricator for perforating the Ciscamp formation.
- 20. RIH with 4-1/2" gauge ring/JB to +/- 10,100'.
- 21. Perforate according to detailed perforation cluster sheet provided in separate document.
- 22. Perforate and frac the Ciscamp according to stimulation design in separate document.
  - a. 10K CBP will be set in between each stage (6 in total).

#### **POST FRAC**

- 23. RDMO frac crew.
- 24. MIRU 2" CTU with sufficient tubing to wash down to PBTD +/- 10,800' (CIBP)
- 25. MU 2.88" OD coil connector and perform pull test to 20k.
  - a. Note Check weight indicator versus hydraulics and note any discrepency
- 26. Fill coil and flush with 2% KCL to ensure tubing is clean
- 27. MU recommended BHA listed below
  - a. Coil Connector
  - b. Dual BPV
  - c. Dual Hydraulic Double Acting Jars
  - d. Hydraulic Disconnect
  - e. Dual Circulating Sub
  - f. PD Motor
  - g. 4.625" OD Blade Mill



.

CONFIDENTIAL. August 24, 2017 Production Operations – Carlsbad Region, Permian Basin New Mexico DD State Com #2 - Cisco Canyon and Wolfcamp (Ciscamp) Proposed Commingling Allocation Factors. Eddy County, NM

- 28. Verify coil company has mechanical means on location to splice coil together if coil parts across gooseneck while TOH.
- 29. Function test motor and mill on the surface.
- 30. NU BOPs and MU Injector head. Test BOPs and all lines to 4800 psi high and 500 psi low.
- 31. Break circulation and RIH to first plug depth.
- 32. D/O composite plugs one at a time.
- 33. Pumping sweeps:
  - a. After each plug is tagged
  - b. After each plug is drilled out
  - c. After every 60 bbls of fluid is pumped
- 34. Note weights, trip speeds, pump rates, flowrates, pressures, and viscosities on Drill\_IT reports while verifying return rates every 15 minutes.
- 35. Continue washing/milling to PBTD +/- 10,800'.
- 36. When clean out is complete and decision is made to POOH, pump a sweep and circulate double bottoms up.
  - a. Ensure clean returns before POOH.
- 37. POOH with motor, mill, and CT.
- 38. LD tools, close well BOP, and RD CTU.
  - a. DO NOT ND BOPs.
- 39. MIRU pulling unit.
- 40. MIRU WL unit with 5K lubricator.
- 41. Call Globe for AS1X (resettable) packer, on/off tool, and BHA
  - a. John Williams 432-553-0195
  - b. Daniel Ruiz 432-528-3919
- 42. Pickup 5-1/2" 17# AS1X packer packer with 1.875" X-Nipple
  - a. 2-3/8" collar with WLEG and pump out plug pinned to 3,000 psi
  - b. 2-3/8" 8rd EUE XN profile nipple w/1.791" No-Go
  - c. Wireline set 4-1/2" 13.5# AS1X packer
  - d. On/off tool with 2.00" X-Nipple
- 43. RIH and set packer @ +/- 8,322'.
- 44. POOH with setting tools and RDMO Wireline.
- 45. PU ON/OFF stinger and 2-3/8" tubing. RIH w/tbg & gas lift valves (GLV design attached).



. . •

CONFIDENTIAL. August 24, 2017 Production Operations – Carlsbad Region, Permian Basin New Mexico DD State Com #2 - Cisco Canyon and Wolfcamp (Ciscamp) Proposed Commingling Allocation Factors. Eddy County, NM

- 46. With tubing above packer pump 148 bbls of corrosion inhibited biocide treated packer fluid down the tubing and displace with 32 bbls fresh water. (Annular capacity 148 bbls & Tubing capacity 32 bbls).
- 47. Engage on/off tool. Set down 15 pts to ensure packer is set.
- 48. Space out tubing, PU and land tubing in 10k lbs tension.
- 49. ND BOP and NU wellhead.
- 50. RU kill truck and pressure up to break pump-out plug.
- 51. RD WSU.
- 52. Open well to frac tanks and turn well over to flowback.
- 53. When the well begins to make gas SWI. Notify Midland and turn production into the facility.
- 54. Report daily production and pressures to Midland office for 10 days.
- 55. Run production log for allocation purposes after recovering load. Run additional production logs if actual production varies significantly from expected performance
  - 1.