Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NM OIL CONSERVATION
ARTESIA DISTRICT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

BOIGHTO OF EMILD WHILE	" IOE I'IE I'I	10 T		
SUNDRY NOTICES AND REP	ODTO ON WELLS	JU 12	n	2017
SUNDKT NUTICES AND KEP	OK 13 ON WELLS	, ,	v	FA (1

Lease Serial No. NMNM85893

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. RECEIVED					6. If Indian, Allottee or Tribe Name				
SUBMIT IN	TRIPLICATE - Other instru	ctions on page :			7. If Unit or CA/Agre	ement, Name and/or No.			
Type of Well	ner				8. Well Name and No CEDAR CANYO	N 21-22 FEDERAL COM 32			
2. Name of Operator Contact: DAVID STEWART OXY USA INC E-Mail: david_stewart@oxy.com					9. API Well No. 30-015-44176-00-X1				
3a. Address MIDLAND, TX 79710 3b. Phone No. (include area code) Ph: 432.685.5717					10. Field and Pool or Exploratory Area PURPLE SAGE-WOLFCAMP (GAS) WOLFCAMP				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish,	11. County or Parish, State			
Sec 21 T24S R29E SWNW 1794FNL 141FWL 32.205326 N Lat, 103.997551 W Lon					EDDY COUNTY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES) T	O INDICATE NA	TURE O	F NOTICE	, REPORT, OR OT	HER DATA			
TYPE OF SUBMISSION		TYPE OF ACTION							
➤ Notice of Intent	☐ Acidize	□ Deepen		☐ Produc	tion (Start/Resume)	☐ Water Shut-Off			
_	☐ Alter Casing	☐ Hydraulic 1	racturing	☐ Reclan	nation	■ Well Integrity			
☐ Subsequent Report	☐ Casing Repair	■ New Const	ruction	☐ Recon	plete	☑ Other Change to Original A			
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and A	bandon	_	rarily Abandon	PD			
	☐ Convert to Injection	☐ Plug Back		□ Water Disposal					
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f OXY USA Inc. respectfully reconstructed by requests the option to consult. If the timing between rig Rig will MIRU and drill the we information on the spudder rig	d operations. If the operation resul- pandonment Notices must be filed inal inspection. quests approval for the follow ontract a Surface Rig to drill is is such that OXY would not it is entirety per the APD	Its in a multiple compi only after all requirer wing changes fror , set surface casir ot be able to pres	etion or reconents, includents, includents	empletion in a ing reclamati roved perm ment for th , the Prima	new interval, a Form 316 on, have been completed it:	60-4 must be filed once			
 OXY proposes to drill out the will consist of an external satu. This will eliminate the need to interval in the intermediate/property. 	rated brine phase with pH a	above 10 at all tim age both the salt a	es, from 4 and losses	00' to PCF circulation		ll apply			
14. I hereby certify that the foregoing is Co Name (Printed/Typed) DAVID ST	Electronic Submission #38 For OXY ommitted to AFMSS for proce	′ USA INC, şent to	the Carlsb ORTIZ on	ad 08/08/2017	•				
Traine(TrinearTypea) D/(VID C)	LVVACC		OITTE	30L/ (TOIL	ABVICOR				
Signature (Electronic S	Submission)	Date	08/02/2	017					
	THIS SPACE FOR	R FEDERAL OR	STATE	OFFICE L	JSE				
Approved By CHARLES NIMMER Conditions of approval, if any, are attache certify that the applicant holds legal or equ	d. Approval of this notice does notice does not table title to those rights in the significant tables.	ot warrant or ubject lease		UM ENGIN	IEER	Date 10/11/2017			
which would entitle the applicant to conduct operations thereon.		Offic	Office Carlsbad						

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #383510 that would not fit on the form

32. Additional remarks, continued

Fluid Type Mud Weight
Spud Mud 8.4-8.6
DEWBM 9.0-9.5
DEWBM (Brine/OBM-Contingency) 9.5-10.0 Depth 0-400' 400-PCP PCP-TD

OXY USA Inc APD ATTACHMENT: SPUDDER RIG DATA

OPERATOR NAME / NUMBER: OXY USA Inc

1. SUMMARY OF REQUEST:

Oxy USA respectfully requests approval for the following operations for the surface hole in the drill plan:

1. Utilize a spudder rig to pre-set surface casing for time and cost savings.

2. Description of Operations

- 1. Spudder rig will move in to drill the surface hole and pre-set surface casing on the well.
 - a. After drilling the surface hole section, the spudder rig will run casing and cement following all of the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations).
 - **b.** The spudder rig will utilize fresh water-based mud to drill the surface hole to TD. Solids control will be handled entirely on a closed loop basis. No earth pits will be used.
- 2. The wellhead will be installed and tested as soon as the surface casing is cut off and the WOC time has been reached.
- 3. A blind flange at the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with needle valves installed on two wingvalves.
 - a. A means for intervention will be maintained while the drilling rig is not over the well.
- **4.** Spudder rig operations are expected to take 2-3 days per well on the pad.
- 5. The BLM will be contacted and notified 24 hours prior to commencing spudder rig operations.
- **6.** Drilling operations will begin with a larger rig and a BOP stack equal to or greater than the pressure rating that was permitted will be nippled up and tested on the wellhead before drilling operations resume on each well.
 - **a.** The larger rig will move back onto the location within 90 days from the point at which the wells are secured and the spudder rig is moved off location.
 - **b.** The BLM will be contacted / notified 24 hours before the larger rig moves back on the pre-set locations.
- 7. Oxy will have supervision on the rig to ensure compliance with all BLM and NMOCD regulations and to oversee operations.
- **8.** Once the rig is removed, Oxy will secure the wellhead area by placing a guard rail around the cellar area.

Mud Pumps 1 & 2 Spudder Rig Layout Conex & Forklift