4

	FOR	M
	OMB	Ν

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	NMOCD
SUNDRY NOTICES AND REPORTS ON WEL Do not use this form for proposals to drill or to re-er abandoned well. Use form 3160-3 (APD) for such pro	LSArtesia

UNITED STATES

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM89819

abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name		
SUBMIT IN	TRIPLICATE - Other ins	tructions on page 2		7. If Unit or CA/Agree	ement, Name and/or No.
1. Type of Well ☐ Gas Well ☐ Other			8. Well Name and No. PATTON MDP1 18 FEDERAL 5H		
2. Name of Operator Contact: DAVID STEWART OXY USA INC. E-Mail: david_stewart@oxy.com			9. API Well No. 30-015-44272		
3a. Address 3b. Phone No. (include area code) P.O. BOX 50250 Ph: 432-685-5717 MIDLAND, TX 79710 Ph: 432-685-5717			10. Field and Pool or Exploratory Area COTTON DRAW BONE SPRING		
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	n)		11. County or Parish, State	
Sec 18 T24S R31E NENE 150FNL 285FEL 32.224180 N Lat, 103.809312 W Lon			EDDY COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE	, REPORT, OR OTI	IER DATA
TYPE OF SUBMISSION		TYPE OF	ACTION		
Notice of Intent	Acidize	Deepen	Product	tion (Start/Resume)	U Water Shut-Off
	Alter Casing	Hydraulic Fracturing	🗖 Reclam	ation	Well Integrity
Subsequent Report	Casing Repair	New Construction	🗖 Recom	plete	🛛 Other
Final Abandonment Notice	🗖 Change Plans	Plug and Abandon	🗖 Tempo	rarily Abandon	Change to Original A PD
	Convert to Injection	Plug Back	🗖 Water I	Disposal	
1. OXY requests the option to this well. If the timing betwee Primary Rig will MIRU and dri document for information on t	contract a Surface Rig to n rigs is such that OXY w Il the well in its entirety po he spudder rig.		cement for ace, the tached NM The wellhe	OIL CONSERVA adrtesia district	
3. Generic Mud program -		Accepted for record -	-/7 NMOCD	NOV 07 2017	\frown
well already	s disted			RECEIVED	$\left(\right)$
14. I hereby certify that the foregoing is Name (Printed/Typed) DAVID ST	Electronic Submission # For O Committed to AFMSS for	384440 verified by the BLM Wel XY USA INC., sent to the Carlso or processing by PRISCILLA PE Title SR. REC	ad REZ on 09/2	F	
Signature (Electronic)	Submission)	Date 08/11/20	ACCA	PTED FOR K	FCORDI
	THIS SPACE F	OR FEDERAL OR STATE			7 11
			+/+		
_Approved By		Title		(7 K)	/hDate/h
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to condu	uitable title to those rights in th		BURG	AN OF AND MANAG	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations a	a crime for any person knowingly and s to any matter within its jurisdiction.	willfully to m	ake to any department or	agency of the United
(Instructions on page 2) ** OPERA		PERATOR-SUBMITED *			** V

(Instructions on page 2) ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Additional data for EC transaction #384440 that would not fit on the form

32. Additional remarks, continued

٠

1

Depth	Fluid Type	Mud	Weight
0-SCP	Water Based I	Mud	8.4-8.6
SCP-ICP	Brine		10.0
ICP-KOP	Water Based	Mud	8.8-9.6
KOP-TD	Oil-Based M	hr	8.8-9.6

OXY USA Inc APD ATTACHMENT: SPUDDER RIG DATA

OPERATOR NAME / NUMBER: <u>OXY USA Inc</u>

1. SUMMARY OF REQUEST:

Oxy USA respectfully requests approval for the following operations for the surface hole in the drill plan:

1. Utilize a spudder rig to pre-set surface casing for time and cost savings.

2. Description of Operations

- 1. Spudder rig will move in to drill the surface hole and pre-set surface casing on the well.
 - **a.** After drilling the surface hole section, the spudder rig will run casing and cement following all of the applicable rules and regulations (OnShore Order 2, all COAs and NMOCD regulations).
 - **b.** The spudder rig will utilize fresh water-based mud to drill the surface hole to TD. Solids control will be handled entirely on a closed loop basis. No earth pits will be used.
- 2. The wellhead will be installed and tested as soon as the surface casing is cut off and the WOC time has been reached.
- **3.** A blind flange at the same pressure rating as the wellhead will be installed to seal the wellbore. Pressure will be monitored with needle valves installed on two wingvalves.
 - **a.** A means for intervention will be maintained while the drilling rig is not over the well.
- 4. Spudder rig operations are expected to take 2-3 days per well on the pad.
- 5. The BLM will be contacted and notified 24 hours prior to commencing spudder rig operations.
- 6. Drilling operations will begin with a larger rig and a BOP stack equal to or greater than the pressure rating that was permitted will be nippled up and tested on the wellhead before drilling operations resume on each well.
 - **a.** The larger rig will move back onto the location within 90 days from the point at which the wells are secured and the spudder rig is moved off location.
 - **b.** The BLM will be contacted / notified 24 hours before the larger rig moves back on the pre-set locations.
- 7. Oxy will have supervision on the rig to ensure compliance with all BLM and NMOCD regulations and to oversee operations.
- 8. Once the rig is removed, Oxy will secure the wellhead area by placing a guard rail around the cellar area.

