Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD	Artesia

FORM APPROVED OMB NO. 1004-0137 xpires: January 31, 2018

	Expires: January
ί.	Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMNM084402 If Indian, Allottee or Tribe Name				
SUBMIT IN 1	7. If Unit or CA/Agreement, Name and/or No. SW247								
1. Type of Well	8. Well Name and No. ROSS FEDERAL 5								
Oil Well Gas Well Oth 2. Name of Operator		9. API Well No.							
2. Name of Operator Contact: ADDISON LONG FASKEN OIL & RANCH LIMITED E-Mail: addisonl@forl.com				30-015-33592-00-S1					
3a. Address 6101 HOLIDAY HILL ROAD MIDLAND, TX 79707	. (include area code) 6-8661	emako	10. Field and Pool or Exploratory Area 74680 CEMETERY-MORROW						
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description	1)			11. County or Parish,				
Sec 4 T21S R24E NENE 6609	EDDY COUNTY, NM			′, NM					
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	, REPORT, OR OTH	IER DATA			
TYPE OF SUBMISSION		TYPE OF ACTION							
Nation of Intent	☐ Acidize	☐ Dee	☐ Deepen		tion (Start/Resume)	☐ Water Shut-Off			
Notice of Intent	☐ Alter Casing	□ Нус	☐ Hydraulic Fracturing		ation	☐ Well Integrity			
☐ Subsequent Report	Casing Repair	□ Nev	Construction	Recom	plete	☐ Other			
☐ Final Abandonment Notice	☐ Change Plans	Change Plans Plug		☐ Temporarily Abandon					
☐ Convert to Injection ☐ P			g Back	☐ Water Disposal		· · · · · · · · · · · · · · · · · · ·			
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for final Fasken Oil and Ranch, Ltd. reattached Procedure, Proposed	k will be performed or provide operations. If the operation re- vandonment Notices must be final inspection. quests to recomplete the	e the Bond No. or esults in a multip led only after all a above well to	n file with BLM/BIA le completion or reco requirements, includi the Wolfcamp. F	Required sumpletion in a ing reclamation	bsequent reports must be new interval, a Form 316 on, have been completed a	filed within 30 days 0-4 must be filed once and the operator has			
	OCD Artesia	NM O	L CONSERVA	ST ATION C	EE ATTACH ONDITIONS	ED FOR S OF APPROVA			
/			NOV 02 2017						
Suprot Clos to	NMOCD		RECEIVED						
14. I hereby certify that the foregoing is	true and correct. Electronic Submission	#374724 verifie		l Informatio	n System				
Comm	For FASKEN C	IL & RANCH L	MITED, sent to th	he Carlsbad	_				
Name (Printed/Typed) ADDISON	•	onig by orbo		ATORY AN					
Signature (Electronic S			Date 05/02/20						
	THIS SPACE F	OK FEDERA	AL OK SIAIE	OPFICE U))C				
Approved By ZOTA STEVENS			TitlePETROLE	<u>UM ENGIN</u>	EER	Date 10/26/2017			
Conditions of approval, if any, are attache	d. Approval of this notice doe	s not warrant or							

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. (Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

which would entitle the applicant to conduct operations thereon.

Office Carlsbad

\$7xxx-51

Recommended Workover Procedure Ross Federal No. 5 660' FNL & 660' FEL Sec 4, T21S R24E

OBJECTIVE: Recomplete to Wolfcamp **WELL DATA:** 13-3/8" 48#/ft H-40 ST&C casing: Set at 412.25' KB Cmt w/600 sx. Circ to Surf 9-5/8" 36.0#/ft K-55 LT&C casing: Set at 3002.34' KB, Cmt w/800 sx, circ 129 sx to surf. 5-1/2" 17# N-80 LT&C casing: Set at 9862.19', Cmt w/ 1100 sx, TOC 5800' by temp survey. Marker jts 18.03' @ 9404.67'; 18.02'@ 7290.98' Morrow 9463'-68' 9-19-07 (2jspf, 10h) Perfs: Morrow 9516'-26' 9-19-07 (2jspf, 20h) CIBP 9-18-17: 9585' w/1 sk "H" cmt (pbtd 9576') Morrow 11-10-04: 9590' - 9646' w/ 3-3/8" TCP guns, 4JSPF, .48"EH w/ 41.30" penetration (total 224 holes). 5-1/2" x 2-3/8" Arrowset 1X 10K packer, 1.781 "F", 5-1/2" x 2-Packer: 3/8" TOSSD, Top of packer @ 9376'. 2956 jts 2-3/8" EUE 8rd L-80 AB mod. Details in attached wbd. Tubing: KB: 18.5 TD: 9,870' PBTD: 9576' (CIBP @ 8585 wlsk "H" cmt)

- 1. Set test tank and lay flowline.
- 2. RUPU. Receive 12 jts 2-3/8" EUE 8rd N80 tubing to tag PBTD.
- 3. RU pump truck and kill well w/ 35 bbls 2% KCL w/ clay stabilizer, corrosion inhibitor and oxygen scavenger.
- 4. NDWH, NU BOP.
- 5. Release packer, POW with tubing and packer.
- 6. RIW with 5-1/2" CIBP, 4' perforated sub, SN, 2-3/8 EUE 8rd 4.7#/ft L-80 AB Modified tubing, and set CIBP at +/-9410' (minimum 50' above top perforation at 9463').
- 7. RU pump truck and circulate well with 2% Kcl water.
- 8. Test casing and plug to 2500 psi on chart recorder w/1 hr clock (calibrated within last 6 months).
- 9. RU cementers pump 34 bbls 9.5 ppg mud laden brine water containing 12.5#/bbl salt gel, 1 bbl freshwater spacer and spot 25 sx class "H" cement (1.17 cuft/sk yield) above CIBP 9410' for a PBTD of 9212' (calc 9212 w/ yield 1.06 cuft/sk). Displace cement with 1 bbl fresh water spacer and 6 bbls mud laden brine water followed by 29 bbls 2% Kcl water. '. POW to 7520' and WOC 8 hours and tag plug at 9212'.
- 10. POW laying down about 66 joints 2-3/8" EUE 8rd 4.7#/ft L-80 AB Modified tubing.
- 11. RIW with 4' x 2-3/8" EUE 8rd L-80 AB Modified tubing sub, Arrowset IX 10k packer, TOSSD with 1.781" "F" profile nipple, and 2-3/8" EUE 8rd 4.7#/ft L-80 AB Modified tubing to +/- 7300'.
- 12. Release TOSSD and circulate well with 2% KCL water containing packer fluid and clay stabilizer.
- 13. ND BOP. NUWH double valve flow tree, setting packer in 12 points compression.
- 14. Swab tubing volume to 6000' from surface.

15. RUWL with 3000 psi lubricator and grease. Perforate Wolfcamp with 1-11/16" Gamma strip gun as follows:

```
7369' - 7377' ( 9h, 1JSPF)
7398' - 7415' (18h, 1JSPF)
7425' - 7430' ( 6h, 1JSPF)
```

17 total holes by Baker Hughes Compensated Z-Densilog Compensated Neutron Log Gamma Ray Log dated 10-20-2004. POW, checking that all shots fired, and RDWL.

- 16. Flow test, swab and evaluate fluid entry.
- 17. RU pumping service. Trap 500 psi on annulus. Acidize Wolfcamp perfs 7369'-7430' via 2-3/8" tubing with 1500 gal 15% NEFE HCL acid dropping 60 ball sealers evenly spaced. Rate 2-4 bpm at max pressure 3000 psi (limited to casing test pressure). RD stimulation company.
- 18. Swab and flow back acid and load water to steel test tank and evaluate.
- 19. Flow well and evaluate.
- 20. Return well to sales.
- 21. RDPU.

Ross Federal No. 5

Operator: Fasken Oil and Ranch, Ltd. Location: 660' FEL and 660' FNL Sec 4, T21S, R24E Eddy County, NM 10/22/2004 released rig Compl.: API#: 30-015-33592 TD: 9.870' PBTD: 9576' (CIBP 9585 w/1sk "H", orig 9,818' FC) Casina: 13-3/8" 48# H-40 @ 412.25' w/400 sx "C" w/2% CaCl2 TOC surf. circ 113 sx 9-5/8" 36# K-55 @ 3002.34'KB w/ 600sx "C"w/4%gel+200sx "C" TOC surf, circ 129 sx 5-1/2" 17# N-80 @ 9862.19' 1100 sx Super C modified w/1% salt and 1.1% FL25 TOC: TOC 5800' by Temp Tubing: Proposed 3-20-17 AJL: 0.45 Wire line entry guide 31.71 5-1/2" x 2-3/8" Arrowset 1X 10K. 7.95 WL set pkr w/1.781" "F" steel profile 4-1/2" x 2-3/8" EUE 8 rd. TOSSD 1.35 7261.36 229 jt-2-3/8"EUE 8rd. L80 ABmod 4.7# 1 1 sub-2-3/8"EUE 8rd. L80 ABmod 4.7# 5.68 Below KB 7276.79 Below KB 15.00 7291.79 EOT **Proposed Perfs:** Wolfcamp 7369'-7377' w/ 1jspf, 9 holes 7398'-7415' w/ 1jspf, 18 holes Proposed 25 sx"H"9410'-9212', Plug #2, Tag CIBP 9410' Proposed

9463'-9468' w/ 2jspf, 10 holes

9585' w/1sk "H" cmt (pbtd 9576')

9590'-9646' w/ 4 JSPF, 224 total holes

12-1/4" 3003'

Mrrw Yellow 9516'-9526' w/ 2 jspf, 20 holes

Perfs: Mrrw Agua

CIBP

Morrow

Hole Sizes 17-1/2" 412'

9/19/07 9/19/07 9/19/07 9/18/07 11/10/04 8-3/4" 9870'


GL: 3689' KB: 3707.5' 13-3/8" 48# H-40 @ 412.25' w/400 sx "C" w/2% CaCl2 TOC surf, circ 113 sx 9-5/8" 36# K-55 @ 3002.34'KB w/ 600sx "C"w/4%gel+200sx "C" TOC surf, circ 129 sx TOC 5800' by Temp PN 7283.39 EOT 7291.79 Wolfcamp 7300' **Proposed Wolfcamp Perfs:** 7369'-7377' w/ 1jspf, 9 holes 7398'-7415' w/ 1jspf, 18 holes Strawn 8730' 25 sx"H"9410'-9212', Plug #2, Tag CIBP XX 9410' Morrow 9440' 9463'-9468' w/ 2jspf, 10 holes 9516'-9526' w/ 2 jspf, 20 holes Sand Fill 9524' Oct 2007 PBTD: 9576' (CIBP 9585 w/1sk "H", orig 9,818' FC) CIBP 9585' w/1sk "H" cmt (pbtd 9576') 9590'-9646' w/ 4 JSPF, 224 total holes 9,870 5-1/2" 17# N-80 @ 9862.19'

Proposed as of 3-20-17

cwb 3-20-17 Ross5 wb diag.xls Ross5 Prop Wlfcmp 3-20-17

1100 sx Super C modified w/1% salt

Ross Federal No. 5



3-20-17 Ross5 wb diag.xls Ross5 Curr 10-10-07

Ross Federal No. 5 30-015-33592 FASKEN OIL AND RANCH Conditions of Approval

Notify BLM at 575-361-2822 (Eddy County) a minimum of 24 hours prior to commencing work.

Work to be completed by January 27, 2018.

- 1. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plug back operations shall commence within <u>ninety (90)</u> days from this approval. If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of

cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date work was completed.** If plugging back to a new zone submit a Completion Report, form 3160-4 with the Subsequent Report.

7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

ZS 102717