B	UNITED STATES PARTMENT OF THE II UREAU OF LAND MANA	NTERIOR GMATIS	bad Fie	ld Offic	OMB NO	APPROVED 0. 1004-0137 nuary 31, 2018
SUNDRY Do not use the abandoned we	tesia 6. II	Indian, Allottee of	Tribe Name			
SUBMIT IN	TRIPLICATE - Other ins	tructions on p	age 2	7. Ii	Unit or CA/Agree	ment, Name and/or No.
1. Type of Well		'ell Name and No. IultipleSee Atta	ched			
2. Name of Operator Contact: DORIAN K FUENTES CHEVRON USA INCORPORATED E-Mail: DJVO@CHEVRON.COM					PI Well No. IultipleSee At	tached
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706	3b. Phone No. Ph: 432-687	3b. Phone No. (include area code) Ph: 432-687-7631		10. Field and Pool or Exploratory Area ABO PURPLE SAGE-WOLFCAMP (GAS)		
4. Location of Well (Footage, Sec., 7	C., R., M., or Survey Description	)		11.	County or Parish,	State
MultipleSee Attached					DDY COUNTY	′, NM
12. CHECK THE A	PROPRIATE BOX(ES)	TO INDICAT	E NATURE O	F NOTICE, REP	ORT, OR OTH	IER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	🗖 Deep	en	□ Production (S	Start/Resume)	□ Water Shut-Off
	Alter Casing	🗖 Hydr	Hydraulic Fracturing			🗖 Well Integrity
Subsequent Report	🗖 Casing Repair	🗖 New	Construction	C Recomplete		🛛 Other
Final Abandonment Notice	Change Plans	🗖 Plug	and Abandon	□ Temporarily	Abandon	Change to Original A PD
	Convert to Injection	🗖 Plug	Back	Water Disposal		·
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for the Summary: Variance to batch	ally or recomplete horizontally rk will be performed or provide d operations. If the operation re bandonment Notices must be fi inal inspection.	, give subsurface l e the Bond No. on esults in a multiple led only after all r	ocations and measu file with BLM/BIA completion or reco equirements, includ	red and true vertical A. Required subseque ompletion in a new ir ling reclamation, hav	depths of all pertir ent reports must be iterval, a Form 316	nent markers and zones. filed within 30 days 10-4 must be filed once
submission. Chevron respectfully requests provided is a brief description wells referenced as follow:	the ability to batch dril ir of the main operational s	the HH SO 10 sequences for a	15 FED 002. T drilling and casi	he summary ng the six		
HH SO 10 15 FED 002 6H 30-015-44367 HH SO 10 15 FED 002 5H 30-015-44371 HH SO 10 15 FED 002 4H 30-015-44353 HH SO 10 15 FED 002 3H 30-015-44351 HH SO 10 15 FED 002 2H 30-015-44354 HH SO 10 15 FED 002 1H 30-015-44352						
See COA on ?	Sundry 39973	6.25				
14. 1 hereby certify that the foregoing i	Electronic Submission #	USA INCORPÓI	RATED, sent to f	the Carlsbad		
	K FUENTES			ATORY SPECIA		
Signature (Electronic	Submission)		Date 12/22/2	017		
	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE USE		
Approved By ZOTA STEVENS						Date 01/10/2018
Approved By_ZOTA STEVENS Conditions of approval, if any, are attached. Approval of this notice does not warrant or						

certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Carlsbad Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## (Instructions on page 2) \*\* BLM REVISED \*\*

## Additional data for EC transaction #398949 that would not fit on the form

## Wells/Facilities, continued

4

1

Agreement NMNM121473	Lease NMNM121473	Well/Fac Name, Number HH SO 10 15 FED 002 2H	API Number 30-015-44354-00-X1	Location Sec 3 T26S R27E SWSW 214FSL 833FWL 32.064594 N Lat. 104.184273 W Lon
NMNM121473	NMNM121473	HH SO 10 15 FED 002 3H	30-015-44351-00-X1	Sec 3 T26S R27E SWSW 239FSL 833FWL 32.064663 N Lat, 104.184273 W Lon
NMNM121473	NMNM121473	HH SO 10 15 FED 002 4H	30-015-44353-00-X1	Sec 3 T26S R27E SWSW 264FSL 833FWL 32.064732 N Lat. 104.184265 W Lon
NMNM121473	NMNM121473	HH SO 10 15 FED 002 5H	30-015-44371-00-X1	Sec 3 T26S R27É SWSW 289FSL 833FWL 32.064800 N Lat. 104.184265 W Lon
NMNM121473	NMNM121473	HH SO 10 15 FED 002 6H	30-015-44367-00-X1	Sec 3 T26S R27E SWSW 314FSL 833FWL 32.064869 N Lat, 104.184265 W Lon
NMNM121473	NMNM121473	HH SO 10 15 FED 002 1H	30-015-44352-00-X1	Sec 3 T26S R27E NWNW 189FSL 833FWL 32.064526 N Lat, 104.184273 W Lon

## 32. Additional remarks, continued

Please refer to the attached additional documents for your reference and should you have any questions, please contact me.

Delaware Basin in Eddy County

Changes to APD FOR Federal Wells Batch Drill

HH SO 10 15 FED 002	6H	30-015-44367
HH SO 10 15 FED 002	5H	30-015-44371
HH SO 10 15 FED 002	4H	30-015-44353
HH SO 10 15 FED 002	3H	30-015-44351
HH SO 10 15 FED 002	2H	30-015-44354
HH SO 10 15 FED 002	1H	30-015-44352

CVX Contact: Rod Milligan, Drilling Engineer 281-413-9794

CVX Contact: Dorian K. Fuentes, Regulatory Specialist 432-687-7631

Surface Hole:

- 1. Drill 17-1/2" surface hole with fresh water to planned casing set depth with 10' rat hole.
- 2. Run casing as stated by approved APD, land out wellhead, and cement.
- 3. Dress out 13-5/8" 5M SH-2 wellhead and install/secure with temporary abandonment cap and a pressure gauge will be installed. Reference image below Part U 399984.
- 4. Skid to next well according to below "Drill Order".

Repeat steps 1 through 3 until all six surface holes are drilled, cased and cemented.


Intermediate Hole:

- 1. N/U, using an API approved Quick-Connect and test 13-5/8" 10M Class IV BOP to 250 psi/5,000 psi.
- 2. Test casing to required pressure. Drill out shoe track and 10' of new formation. Perform FIT. Drill 12-1/4" intermediate hole to planned casing set depth with 10' of rat hole.
- 3. Run casing as stated by approved APD, land out hanger and cement.

Production Hole:

- 1. Test casing to required pressure. Drill out shoe track and 10' of new formation. Perform FIT. Drill 8 1/2" vertical section, curve and lateral as stated by approved APD.
- 2. Run casing as stated by approved APD, cement, land out hanger and cement.
- 3. Install back pressure valve and temporary abandonment cap.

Repeat steps in intermediate hole and production hole until all six wells are drilled, cased and cemented.



ŕ

50 1.4 J 6

۶

,