

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88248

District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210

District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**NEW MEXICO OIL CONSERVATION DIVISION**  
Energy, Minerals and Natural Resources

JAN 29 2018  
RECEIVED

1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised July 18, 2013

WELL API NO. **30-015-36123**

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
**303271**

7. Lease Name or Unit Agreement Name  
**PINNACLE STATE**

8. Well Number **018**

9. OGRID Number **246289**

10. Pool name or Wildcat  
HERRADURA BEND; DELAWARE, EAST

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator **RKI EXPLORATION & PRODUCTION, LLC**

3. Address of Operator **3500 ONE WILLIAMS CENTER MD 35  
TULSA, OK 74172**

4. Well Location  
Unit Letter **G** : **2630** feet from the **NORTH** line and **1685** feet from the **EAST** line  
Section **36** Township **22S** Range **28E** NMPM EDDY County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
**3,120' GR**

**12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1-11-18 MIRU WSU.

1-16-18 Set CIBP @ 6396'. Tag & Verify.

1-17-18 Load & Test Well 500 PSI. Circulate 85 Bbl. Salt Gel.

Spot 30 Sacks Class C 6396'-6095'.

Spot 30 sacks Class C 4026'-3725'.

Spot 30 sacks Class C 2640'-2339'.

1-18-18 Perforate @ 457'. Not able to establish rate. Discuss with NMOCD. Approved to perforate @ 150'. Perforate @ 150'.

Establish rare with no circulation to surface. Discuss with NMOCD. Approved to spot form 507'- Surface and squeeze out perms. @

Spot to surface. POH Tubing. Squeeze out perms @ 150'. Perfs locked up and pressured up to 500 PSI with no bleed off. Total of 70 sacks Class C.

Spud Date:

**02/29/2008**

Rig Release Date:

**04/17/2008**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Caitlin O'Hair*

TITLE

**Permit Technician II**

DATE

**01/23/2018**

Type or print name

**Caitlin O'Hair**

E-mail address:

**caitlin.o'hair@wpenergy.com**

PHONE:

**539-573-3527**

**For State Use Only**

APPROVED BY:

*Staff*

TITLE

**Staff**

DATE

**1-29-18**

Conditions of Approval (if any):