Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM102036

	SUNDRY N	OTICES	AND	REPOR	TS ON V	NELLS	
Do	not use this	form for	propos	sals to d	Irill or to	re-enter ar)
bai	ndoned well.	Use for	m 3160	-3 (APD)) for sucl	h proposal	s

abandoned we	6. If Indian, Allottee	6. If Indian, Allottee or Tribe Name							
SUBMIT IN	7. If Unit or CA/Agre	7. If Unit or CA/Agreement, Name and/or No.							
1. Type of Well		8. Well Name and No. RDX 15 6							
☑ Oil Well ☐ Gas Well ☐ Oth	9. API Well No.								
Name of Operator RKI EXPLORATION & PROD	Contact: CAIT LLC E-Mail: caitlin.ohair@wp	LIN O'HAIR xenergy.com	30-015-36677-	00-S1					
3a. Address 3500 ONE WILLIAMS CENTE TULSA, OK 74172	ER MD 35 Ph:	Phone No. (include area code) 539-573-3527	Brushy Draw	Nushu Draw Delaware tast					
4. Location of Well (Footage, Sec., T	C., R., M., or Survey Description)		11. County or Parish,	State					
Sec 15 T26S R30E SWSW 99 32.038018 N Lat, 103.875601	EDDY COUNT	EDDY COUNTY, NM							
12. CHECK THE A	PPROPRIATE BOX(ES) TO I	NDICATE NATURE OF	F NOTICE, REPORT, OR OT	HER DATA					
TYPE OF SUBMISSION		TYPE OF	ACTION						
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off					
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity					
Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomplete	☐ Other					
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	□ Temporarily Abandon						
	☐ Convert to Injection	□ Plug Back	■ Water Disposal						
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 1-31-18 Notify BLM 2-1-18 MIRU WS Unit. 2-2-18 Set CIBP @ 4973'. Notify BLM. 2-5-18 Tag CIBP. Load & Test 500 PSI. Test Held. Circualte 100 bbl- 25 sx Salt Gel Mud. Spot 25 sacks Class C 4973'-4718'. Spot 25 sacks Class C 3617'-3365'. WOC Overnight. 2-6-18 Tag Plug @ 3370'. Notify BLM. Tag Approved. Perforate @ 1030' W/ 3-1/8" Gun. Establish circulation out Intermediate. Squeeze 80 sacks Class C to surface out intermediate. Aftempt to squeeze out surface casing. Pressured up. Leave casing full. **RECEIVED** **RECEIVED*									
14. I hereby certify that the foregoing is Con Name (Printed/Typed) CAITLIN (Electronic Submission #40443 For RKI EXPLORATION Inmitted to AFMSS for processin	ON & PROD LLC, sent to t	he Carlsbad n 02/15/2018 (18JA0117SE)						
O'ATENA	5 1 1 Mil C	- CODMIT	T bear 1						
Signature (Electronic S	Submission)	Date 02/14/20)18						
Accessed to Rence	THIS SPACE FOR F	EDERAL OR STATE	OFFICE USE						
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equ		arrant or oct lease	S. PET	2-27-18 Date					
which would entitle the applicant to condu	·	Office Cac	Kbad						
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent			willfully to make to any department o	r agency of the United					