

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*Carlsbad Field Office  
OCD Artesia  
Lease Serial No.  
NMNM86024

6. Indian Allottee or Tribe Name

**SUBMIT IN TRIPLICATE - Other instructions on page 2**

7. If Unit or CA/Agreement, Name and/or No.

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other: INJECTION8. Well Name and No.  
CYPRESS SWD 12. Name of Operator  
MESQUITE SWD, INC.Contact: MELANIE J WILSON  
E-Mail: mjp1692@gmail.com9. API Well No.  
30-015-438673a. Address  
PO BOX 1479  
CARLSBAD, NM 882213b. Phone No. (include area code)  
Ph: 575-914-146110. Field and Pool or Exploratory Area  
SWD;DEVONIAN

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 34 T23S R29E Mer NMP NWSW 1590FSL 165FWL

11. County or Parish, State

EDDY COUNTY, NM

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Change to Original A
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	PD

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletable horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletable in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Mesquite SWD, Inc. respectfully requests a variance to the 10M annular policy. Mesquite is proposing to use a 5M annular rather than a 10M annular.

Please see the attached Well Control Plan.

We also request permission to change the surface casing as follows:

From: 20 inch J55 106.5 lb LTC  
To: 20 inch K55 94 lb BTC

RECEIVED

APR 26 2018

DISTRICT II-ARTESIA O.C.D.

-All previous COAP still apply. Additional COA is not required.

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #411643 verified by the BLM Well Information System  
For MESQUITE SWD, INC., sent to the Carlsbad  
Committed to AFMSS for processing by MUSTAFA HAQUE on 04/19/2018 ( )

Name (Printed/Typed) MELANIE J WILSON

Title REGULATORY ANALYST

Signature (Electronic Submission)

Date 04/13/2018

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved By <u>MUSTAFA HAQUE</u>	Title <u>Engineer</u>	Date <u>04/19/2018</u>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office <u>CFO</u>	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**\*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\***

**Additional data for EC transaction #411643 that would not fit on the form**

**32. Additional remarks, continued**

# Mesquite SWD, Inc. Well Control Plan

## A. Component and Preventer Compatibility Table

Component	OD	Preventer	RWP
Drill Pipe	5"	Upper VBR: 3.5 – 5.5 Lower VBR: 3.5 – 5.5	10M
Heavyweight Drill Pipe	5"	Upper VBR: 3.5 – 5.5 Lower VBR: 3.5 – 5.5	10M
Drill Collars & MWD Tools	6 1/4"	Upper VBR: 3.5 – 5.5 Lower VBR: 3.5 – 5.5	10M
Mud Motor	6 1/4"	Upper VBR: 3.5 – 5.5 Lower VBR: 3.5 – 5.5	10M
Production Casing	5 1/2"	Upper VBR: 3.5 – 5.5 Lower VBR: 3.5 – 5.5	10M
All	0 – 13 5/8"	Annular	5M
Open Hole		Brind Rams	10M

## B. Well Control Procedures

### I. General Procedures While Drilling:

- a. Sound alarm – alert crew
- b. Space out drill string
- c. Shut down pumps and stop rotary
- d. Open HCR
- e. Shut well in, utilizing upper VBRs
- f. Close choke
- g. Confirm shut in
- h. Notify rig manager and Mesquite SWD, Inc. company representative
- i. Call Mesquite SWD, Inc. engineer
- j. Read and record:
  - i. Shut in drill pressure and shut in casing pressure
  - ii. Pit gain
  - iii. Time
- k. Regroup, identify forward plan

### II. General Procedures While Tripping:

- a. Sound alarm – alert crew
- b. Stab full opening safety valve and close
- c. Space out drill string
- d. Open HCR
- e. Shut well in, utilizing upper VBRs
- f. Close choke
- g. Confirm shut in
- h. Notify rig manager and Mesquite SWD, Inc. company representative
- i. Call Mesquite SWD, Inc. engineer
- j. Read and record:
  - i. Shut in drill pressure and shut in casing pressure
  - ii. Pit gain
  - iii. Time
- k. Regroup, identify forward plan

**Mesquite SWD, Inc.**  
**Well Control Plan**

**III. General Procedures While Running Casing:**

- a. Sound alarm – alert crew
- b. Stab full opening safety valve and close
- c. Space out drill string
- d. Open HCR
- e. Shut well in, utilizing upper VBRs
- f. Close choke
- g. Confirm shut in
- h. Notify rig manager and Mesquite SWD, Inc. company representative
- i. Call Mesquite SWD, Inc. engineer
- j. Read and record:
  - i. Shut in drill pressure and shut in casing pressure
  - ii. Pit gain
  - iii. Time
- k. Regroup, identify forward plan

**IV. General Procedures With No Pipe in Hole (Open Hole):**

- a. Sound alarm – alert crew
- b. Open HCR
- c. Shut well in with blind rams
- d. Close choke
- e. Confirm shut in
- f. Notify rig manager and Mesquite SWD, Inc. company representative
- g. Call Mesquite SWD, Inc. engineer
- h. Read and record:
  - i. Shut in drill pressure and shut in casing pressure
  - ii. Pit gain
  - iii. Time
- i. Regroup, identify forward plan

**V. General Procedures While Pulling BHL Through BOP Stack:**

1. Prior to pulling last joint of drill pipe through stack
  - A. Perform flow check and if flowing:
    - a. Sound alarm – alert crew
    - b. Stab full opening safety valve and close
    - c. Space out drill string with tool joint just beneath upper pipe ram
    - d. Open HCR
    - e. Shut well in utilizing upper VBRs
    - f. Close choke
    - g. Confirm shut in
    - h. Notify rig manager and Mesquite SWD, Inc. company representative
    - i. Call Mesquite SWD, Inc. engineer
    - j. Read and record:
      - i. Shut in drill pressure and shut in casing pressure
      - ii. Pit gain
      - iii. Time
    - k. Regroup, identify forward plan

## Mesquite SWD, Inc. Well Control Plan


2. With BHL in the BOP stack and compatible ram preventer and pipe combo immediately available.
  - a. Sound alarm – alert crew
  - b. Stab full opening safety valve and close
  - c. Space out drill string with tool joint just beneath upper pipe ram
  - d. Open HCR
  - e. Shut well in utilizing upper VBRs
  - f. Close choke
  - g. Confirm shut in
  - h. Notify rig manager and Mesquite SWD, Inc. company representative
  - i. Call Mesquite SWD, Inc. engineer
  - j. Read and record:
    - i. Shut in drill pressure and shut in casing pressure
    - ii. Pit gain
    - iii. Time
  - k. Regroup, identify forward plan
3. With BHA in the BOP stack and no compatible ram preventer and pipe combo immediately available
  - a. Sound alarm – alert crew
  - b. If possible to pick up high enough, pull string clear of the stack and follow Open Hole scenario (III)
  - c. If impossible to pick up high enough to pull the string clear of the stack:
    - i. Stab crossover, make up one joint/stand of drill pipe and full opening safety valve and close
    - ii. Space out drill string with tool joint just beneath the upper pipe ram
    - iii. Open HCR
    - iv. Shut in utilizing upper VBRs
    - v. Close choke
    - vi. Confirm shut in
    - vii. Notify rig manager and Mesquite SWD, Inc. company representative
    - viii. Read and record:
      1. Shut in drill pipe pressure and shut in casing pressure
      2. Pit gain
      3. Time
  - d. Regroup and identify forward plan

\*\* If annular is used to shut in well and pressure build to or is expected to get to 50% of RWP, confirm space-out and swap to upper VBRs for shut in.

Hydril "GK"  
13-5/8" 5M




Hydril "GK"




Variable Bore Rams


Cameron Type U  
13-5/8" 10M



BLIND RAMS



MUD CROSS




Variable Bore Rams




13 5/8" 10M



13 5/8" 10M



13 5/8" 10M



13 5/8" 10M

