E 21(0) 5			A Section Inc. 14	FORM AP	PROVED		
	UNITED STATES PARTMENT OF THE IN EAU OF LAND MANA	TERICEATISDAC		Office MB No. 1	1004-0137 ary 31, 2018		
	NOTICES AND REPOR	TS ON WELLS) Artesi	an, Allottee or Tribe Na	and the second		
Do not use this	form for proposals to Use Form 3160-3 (API	drill or to re-enter an					
SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well				7. If Unit of CA/Agreement, Name and/or No.			
				Grayburg-Jackson PSU			
Oil Well Gas Well Other			o. ADLU	8. Well Name and No. Grayburg-Jackson PSU MB #014			
2. Name of Operator EnergyQuest II, LLC				9. API Well No. 30-015-30023			
a. Address 4526 Research Forest The Woodlands, TX 77	 Phone No. (include area cod 281) 875-6200 	Grayb	10. Field and Pool or Exploratory Area Grayburg-Jackson 7 Rivers-QN-GB-SA				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 330' FSL & 2310' FWL, N-27-17S-30E				11. Country or Parish, State Eddy County, NM			
12. CHE	CK THE APPROPRIATE BOX	(ES) TO INDICATE NATUR	E OF NOTICE, REP	ORT OR OTHER DATA	A		
TYPE OF SUBMISSION	TYPE OF SUBMISSION				TYPE OF ACTION		
Notice of Intent	Acidize	Deepen Hydraulic Fracturing New Construction	Production (St Reclamation Recomplete	W	ater Shut-Off ell Integrity ther		
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back	Temporarily A Water Disposa				
	ally or recomplete horizontally, Il be perfonned or provide the B ons. If the operation results in a	nent details, including estimate give subsurface locations and ond No. on file with BLM/BI/ multiple completion or recom	d starting date of any neasured and true ver A. Required subseque pletion in a new inter	proposed work and app rtical depths of all pertin nt reports must be filed val, a Form 3160-4 mus	nent markers and zones. Attach within 30 days following st be filed once testing has been		
 Describe Proposed or Completed C the proposal is to deepen directions the Bond under which the work wi completion of the involved operati completed. Final Abandonment No is ready for final inspection.) 	Deperation: Clearly state all pertin ally or recomplete horizontally, Il be perfonned or provide the B ons. If the operation results in a	nent details, including estimate give subsurface locations and ond No. on file with BLM/BI/ multiple completion or recom	d starting date of any neasured and true ver A. Required subseque pletion in a new inter	proposed work and app rtical depths of all pertin nt reports must be filed val, a Form 3160-4 mus	nent markers and zones. Attack within 30 days following st be filed once testing has bee		
 Describe Proposed or Completed C the proposal is to deepen directions the Bond under which the work wi completion of the involved operati completed. Final Abandonment No is ready for final inspection.) MIRU pulling unit. Pull completion assembly Repair failed components Change pump Rig down pulling unit 	Deration: Clearly state all pertin ally or recomplete horizontally, Il be perfonned or provide the B ons. If the operation results in a strices must be filed only after all	nent details, including estimate give subsurface locations and ond No. on file with BLM/BI/ multiple completion or recom	d starting date of any measured and true vee A. Required subseque pletion in a new inter mation, have been co	r proposed work and app rtical depths of all pertin nt reports must be filed val, a Form 3160-4 mus mpleted and the operato	nent markers and zones. Attac within 30 days following to be filed once testing has bee or has detennined that the site		
 Describe Proposed or Completed C the proposal is to deepen directions the Bond under which the work wi completion of the involved operati completed. Final Abandonment No is ready for final inspection.) MIRU pulling unit. Pull completion assembly Repair failed components Change pump Rig down pulling unit 	Deration: Clearly state all pertin ally or recomplete horizontally, Il be perfonned or provide the B ons. If the operation results in a strices must be filed only after all	nent details, including estimate give subsurface locations and r ond No. on file with BLM/BI/ multiple completion or recomp requirements, including reclar	d starting date of any measured and true vee A. Required subseque pletion in a new inter mation, have been co	r proposed work and app rtical depths of all pertin nt reports must be filed val, a Form 3160-4 mus mpleted and the operato	nent markers and zones. Attack within 30 days following at be filed once testing has been or has detennined that the site		
 Describe Proposed or Completed C the proposal is to deepen directions the Bond under which the work wi completion of the involved operati completed. Final Abandonment No is ready for final inspection.) MIRU pulling unit. Pull completion assembly Repair failed components Change pump Rig down pulling unit 	Deration: Clearly state all pertin ally or recomplete horizontally, Il be perfonned or provide the B ons. If the operation results in a strices must be filed only after all	nent details, including estimate give subsurface locations and r ond No. on file with BLM/BI/ multiple completion or recomp requirements, including reclar	d starting date of any measured and true vee A. Required subseque pletion in a new inter mation, have been co	r proposed work and app rtical depths of all pertin nt reports must be filed val, a Form 3160-4 mus mpleted and the operato	nent markers and zones. Attack within 30 days following to be filed once testing has beer or has detennined that the site		
3. Describe Proposed or Completed C the proposal is to deepen directions the Bond under which the work wi completion of the involved operati completed. Final Abandonment No is ready for final inspection.) MIRU pulling unit. Pull completion assembly Repair failed components Change pump Rig down pulling unit Return to production	Deperation: Clearly state all pertin ally or recomplete horizontally, Il be perfonned or provide the B ons. If the operation results in a btices must be filed only after all stices must be filed only after all	nent details, including estimate give subsurface locations and re- sond No. on file with BLM/BL/ multiple completion or recomp requirements, including reclar 5 - 2 4 - 1 8 Moc led for record - NMOC	d starting date of any measured and true vee A. Required subseque pletion in a new inter mation, have been co	r proposed work and app rtical depths of all pertin nt reports must be filed val, a Form 3160-4 mus mpleted and the operato	nent markers and zones. Attack within 30 days following st be filed once testing has been or has detennined that the site EIVED 2 3 2018		
 Describe Proposed or Completed O the proposal is to deepen directions the Bond under which the work wi completion of the involved operati completed. Final Abandonment No is ready for final inspection.) MIRU pulling unit. Pull completion assembly Repair failed components Change pump Rig down pulling unit Return to production 4. I hereby certify that the foregoing is 	Deperation: Clearly state all pertin ally or recomplete horizontally, Il be perfonned or provide the B ons. If the operation results in a btices must be filed only after all stices must be filed only after all	nent details, including estimate give subsurface locations and re- sond No. on file with BLM/BI/ multiple completion or recomp requirements, including reclar 5 - 2 4 - 1 8 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	d starting date of any measured and true vee A. Required subseque pletion in a new inter mation, have been co	r proposed work and app rtical depths of all pertin nt reports must be filed val, a Form 3160-4 mus mpleted and the operato	nent markers and zones. Attack within 30 days following st be filed once testing has been or has detennined that the site EIVED 2 3 2018		
 3. Describe Proposed or Completed C the proposal is to deepen directions the Bond under which the work wi completion of the involved operati completed. Final Abandonment No is ready for final inspection.) MIRU pulling unit. Pull completion assembly Repair failed components Change pump Rig down pulling unit Return to production 4. I hereby certify that the foregoing is DEBRA MOORE 	Deperation: Clearly state all pertin ally or recomplete horizontally, Il be perfonned or provide the B ons. If the operation results in a btices must be filed only after all stices must be filed only after all	requirements, including estimate give subsurface locations and re- sond No. on file with BLM/BL/ multiple completion or recomp requirements, including reclar 5 - 2 4 - 1 8 1 1 1 1 1 1 1 1 1 1	d starting date of any measured and true ve A. Required subseque pletion in a new inter mation, have been co	r proposed work and app rtical depths of all pertin nt reports must be filed val, a Form 3160-4 mus mpleted and the operato REC MAY DISTRICT II-A	nent markers and zones. Attack within 30 days following st be filed once testing has been or has detennined that the site EIVED 2 3 2018		
 3. Describe Proposed or Completed C the proposal is to deepen directions the Bond under which the work wi completion of the involved operati completed. Final Abandonment No is ready for final inspection.) MIRU pulling unit. Pull completion assembly Repair failed components Change pump Rig down pulling unit Return to production 4. I hereby certify that the foregoing is DEBRA MOORE 	Deperation: Clearly state all pertin ally or recomplete horizontally, Il be perfonned or provide the B ons. If the operation results in a strices must be filed only after all GCA	requirements, including estimate give subsurface locations and re- bond No. on file with BLM/BL/ multiple completion or recomp requirements, including reclar including reclar including reclar including reclar including reclar including reclar including reclar including reclar	d starting date of any measured and true ve A. Required subseque pletion in a new inter mation, have been co	proposed work and app rtical depths of all pertin nt reports must be filed val, a Form 3160-4 mus mpleted and the operato REC MAY 1 DISTRICT II-4 04/02/2018 /S/	nent markers and zones. Attack within 30 days following at be filed once testing has been or has detennined that the site EIVED 2 3 2018 ARTESIA O.C.D.		
 3. Describe Proposed or Completed C the proposal is to deepen directions the Bond under which the work wi completion of the involved operati completed. Final Abandonment No is ready for final inspection.) MIRU pulling unit. Pull completion assembly Repair failed components Change pump Rig down pulling unit Return to production 4. I hereby certify that the foregoing is DEBRA MOORE 	Deperation: Clearly state all pertin ally or recomplete horizontally, Il be perfonned or provide the B ons. If the operation results in a strices must be filed only after all GCA	requirements, including estimate give subsurface locations and re- sond No. on file with BLM/BL/ multiple completion or recomp requirements, including reclar 5 - 2 4 - 1 8 1 1 1 1 1 1 1 1 1 1	d starting date of any measured and true ve A. Required subseque pletion in a new inter mation, have been co	proposed work and app rtical depths of all pertin nt reports must be filed val, a Form 3160-4 mus mpleted and the operato REC MAY 1 DISTRICT II-4 04/02/2018 /S/	nent markers and zones. Attack within 30 days following at be filed once testing has been or has detennined that the site EIVED 2 3 2018 ARTESIA O.C.D.		

(Instructions on page 2)