· • • • • • • • • • • • • • • • • • • •	
. Submit Copy To Appropriate District State of New Mexico	Form C-103
Office District 1 - (575) 393-6161 Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-26172 5. Indicate Type of Lease
<u>District III</u> - (505) 334-6178 1220 South St. Francis Dr.	STATE STEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Harroun Trust
1. Type of Well: Oil Well Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
Devon Energy Production Company, LP	6137
3. Address of Operator	10. Pool name or Wildcat
333 W. Sheridan Avenue, Oklahoma City, OK 73102	Culebra Bluff Atoka, South (gas)
4. Well Location	
	om theEastline
Section 30 Township 23S Range 29E	NMPM Eddy County, NM
11. Elevation (Show whether DR, RKB, RT, GR, etc. 2959.8' GR)
2737.0 UK	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
_	ILLING OPNS. P AND A
PULL OR ALTER CASING	T JOB
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion. Notify NMOCD 24 hrs before MIRU	TA 0
1. MIRU P&A Unit.	SCOT 255X TOTO
MIRU P&A Unit. MIRU P&A Unit. Set CIBP at 12000' and tag. Place 35' Class ocement on top of plug. w/Dump DANIC. Spot 100' CI P cmt at 10700''-10800'. Tag. Spot 200' CI P cmt at 9780'-9980'. Tag. Spot 200' CI P cmt at 6400'-6500' Spot 100' CI C cmt at 6400'-6500'	"NM OIL CONSERVATION ARTESIA DISTRICT
3. Spot 100' Cl Cont at 10700"-10800'. Tag.	Z ARTESIA SIGNA
4. Spot 200' CI (cmt at 9780'-9980'. Tag. 5. Spot 100' CI C cmt at 6400'-6500'.	AUG 0 3 2018
5. Spot 100' CI C cmt at 6400'-6500'. 6. Perf 9-5/8" csg at 2900'. Tag Attempt to Sg 2 25 sks cut + Tag	
	RECEIVED
8. Perf 9-5/8" csg at 500'. Pump CI C cmt in/out to surface. Parf @ 550' 9. Cut wellhead off 3' BGL, set dry hole marker.	0.400-6.000
5. Cut Weilitead off 5 BGL, Set dry Hole Marker.	
Spud Date: Rig Release Date:	
* See Attachel COA's must J.	- Plassed by 8-3-19
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
17 12	•
SIGNATURE Max Kulif TITLE Production Engineer	DATE 8/2/2018
Type or print name Max LubitzE-mail address: _max.lubitz@dvn.com PHON	NE: _405-552-7825 or 580-302-4593
For State Use Only	
11:	
APPROVED BY TITLE STATE ME	DATE 8-6-18



