
Form 3160-5			rlsbad I OCD	Artesi		APPROVED
(June 2015)	UNITED STATE	NTERIOR	- ~ 0		OMBN	NO. 1004-0137 January 31, 2018
SII	BUREAU OF LAND MANA		FUIS		5. Lease Serial No. NMNM88134	
Do not	use this form for proposals to ned well. Use form 3160-3 (AP	drill or to re	enter an		6. If Indian, Allottee	or Tribe Name
······································	MIT IN TRIPLICATE - Other ins				7. If Unit or CA/Agro	ecment, Name and/or No.
1. Typc of Well	•				8. Well Name and No H B 11 FEDERA	
2. Name of Operator		BRITTNEY			9. API Well No.	
DEVON ÈNERGY PRO		neaton@dvn.co			30-015-32741-	
3a. Address 333 WEST SHERIDAN OKLAHOMA, OK 7310		3b. Phone No Ph: 405.22	o. (include area code) 28.2810			r Exploratory Arca
4. Location of Well (Footage	e, Sec., T., R., M., or Survey Description	Ŋ			11. County or Parish,	
Sec 11 T24S R29E NE	NW 330FNL 1750FWL				EDDY COUNT	Ύ, ΝΜ
12. CHECK T	THE APPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OT	HER DATA
TYPE OF SUBMISSIO	N		TYPE OI	FACTION		
□ Notice of Intent		Dee	epen	Producti	ion (Start/Resume)	UWater Shut-Off
Subsequent Report	Alter Casing		draulic Fracturing			U Well Integrity
8	Casing Repair		w Construction	🖸 Recomp	olete	Other
Final Ahandonment N	otice Change Plans		e and Abandon	67 Tempor	arily Abandon	
If the proposal is to deepen on Attach the Bond under which	Convert to Injection leted Operation: Clearly state all pertinn directionally or recomplete horizontally, h the work will be performed or provide	Plug ent details, includ , give subsurface the Bond No. o	ding estimated startin clocations and measu on file with BLM/BIA	Water D g date of any purced and true ve Required sub	roposed work and appro rucal depths of all perti osequent reports must b	inent markers and zones. In filed within 30 days
13. Describe Proposed or Comp If the proposal is to decene of Attach the Bond under which following completion of the testing has been completed. determined that the site is re Devon Energy Product	Convert to Injection leted Operation: Clearly state all pertine directionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation rc Final Abandonment Notices must be fi ady for final inspection. ion Co. LP, respectfully requests	Plup ent details, inclue give subsurface the Bond No. o sults in a multip led only after all s TA status fo	g Back ding estimated startin e locations and measu in file with BLM/BIA le completion or rece requirements, includ	Water D g date of any purced and true ve A. Required sub completion in a r ling reclamation	Disposal roposed work and appre- rtical depths of all perti- sequent reports must b new interval, a Form 31 n, have been completed	inent markers and zones. The filed within 30 days 60-4 must be filed once
13. Describe Proposed or Comp If the proposal is to decene of Attach the Bond under which following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed	Convert to Injection leted Operation: Clearly state all pertine directionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices must be fi ady for final inspection.	Plup ent details, inclue give subsurface the Bond No. o sults in a multip led only after all s TA status fo	g Back ding estimated startin e locations and measu in file with BLM/BIA le completion or rece requirements, includ	Water D g date of any purced and true ve A. Required sub completion in a r ling reclamation	Disposal roposed work and appre- rtical depths of all perti- sequent reports must b new interval, a Form 31 n, have been completed	inent markers and zones. The filed within 30 days 60-4 must be filed once
13. Describe Proposed or Comp If the proposal is to deepen Attach the Bond under whic following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed ATTACHMENTS: PROCEDURES	Convert to Injection leted Operation: Clearly state all pertine directionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation rc Final Abandonment Notices must be fi ady for final inspection. ion Co. LP, respectfully requests	Plup ent details, inclue give subsurface the Bond No. o sults in a multip led only after all s TA status fo	g Back ding estimated startin e locations and measu in file with BLM/BIA le completion or reco requirements, includ or two years with	Water D g date of any p ured and true ve A Required sub ompletion in a m ling reclamation the attached	Disposal roposed work and appri- rtical depths of all perti- sequent reports must b new interval, a Form 31 n, have been completed	inent markers and zones. The filed within 30 days 60-4 must be filed once
13. Describe Proposed or Comp If the proposal is to decpen o Attach the Bond under which following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed ATTACHMENTS: PROCEDURES MIT 500 PSI MIT 1000 PSI	Convert to Injection leted Operation: Clearly state all pertine directionally or recomplete horizontally, involved operations. If the operation re- Final Abandonment Notices must be fi ady for final inspection. ion Co. LP, respectfully requests from 01/25/2018 to 01/29/2018.	Plug ent details, includ, give subsurface the Bond No. o soults in a multip led only after all s TA status fo	g Back ding estimated startin e locations and measu in file with BLM/BIA de completion or reco requirements, includ or two years with	Water D g date of any p ured and true ve A. Required sub ompletion in a m ling reclamation the attached	Disposal roposed work and appri- rrtical depths of all perti- secuent reports must b new interval, a Form 31 n, have been completed	inent markers and zones. Se filed within 30 days 60-4 must be filed once I and the operator has RECEIVED
13. Describe Proposed or Comp If the proposal is to deepen Attach the Bond under whic following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed ATTACHMENTS: PROCEDURES MIT 500 PSI	Convert to Injection leted Operation: Clearly state all pertine directionally or recomplete horizontally, involved operations. If the operation re- Final Abandonment Notices must be fi ady for final inspection. ion Co. LP, respectfully requests from 01/25/2018 to 01/29/2018.	Plug ent details, includ, give subsurface the Bond No. o soults in a multip led only after all s TA status fo	g Back ding estimated startin e locations and measu in file with BLM/BIA le completion or reco requirements, includ or two years with	Water D g date of any p ured and true ve A. Required sub ompletion in a m ling reclamation the attached	Disposal roposed work and appri- rrtical depths of all perti- secuent reports must b new interval, a Form 31 n, have been completed	inent markers and zones. the filed within 30 days 160-4 must be filed once 1 and the operator has
13. Describe Proposed or Comp If the proposal is to decpen o Attach the Bond under which following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed ATTACHMENTS: PROCEDURES MIT 500 PSI MIT 1000 PSI	Convert to Injection leted Operation: Clearly state all pertine directionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re- Final Abandonment Notices must be final inspection. ion Co. LP, respectfully requests from 01/25/2018 to 01/29/2018. E SCHEMATIC	Plug ent details, includ, give subsurface the Bond No. o soults in a multip led only after all s TA status fo	g Back ding estimated startin e locations and measu in file with BLM/BIA de completion or reco requirements, includ or two years with	Water D g date of any p ured and true ve A. Required sub ompletion in a m ling reclamation the attached	Disposal roposed work and appr rrical depths of all perti sequent reports must b new interval, a Form 31 n, have been completed	inent markers and zones. Se filed within 30 days 60-4 must be filed once I and the operator has RECEIVED
13. Describe Proposed or Comp If the proposal is to deepen of Attach the Bond under which following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed ATTACHMENTS: PROCEDURES MIT 500 PSI MIT 1000 PSI CURRENT WELLBOR	E SCHEMATIC	Plug ent details, includ, give subsurface the Bond No. o soults in a multip led only after all s TA status fo	g Back ding estimated startin e locations and measu in file with BLM/BIA de completion or reco requirements, includ or two years with	Water D g date of any p ured and true ve A. Required sub ompletion in a m ling reclamation the attached	Disposal roposed work and appr rrical depths of all perti sequent reports must b new interval, a Form 31 n, have been completed	inent markers and zones. the filed within 30 days 60-4 must be filed once 1 and the operator has RECEIVED JL 1 1 2018
13. Describe Proposed or Comp If the proposal is to decpen o Attach the Bond under which following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed ATTACHMENTS: PROCEDURES MIT 500 PSI MIT 1000 PSI CURRENT WELLBOR	Convert to Injection Convert to Injection	Plup prot details, includ give subsurface the Bond No. o sults in a multip led only after all s TA status for Accepted H404008 verifie BY PRODUCTION	g Back ding estimated startin e locations and measu in file with BLM/BI- ble completion or reco requirements, includ or two years with 7 - / 2 1 for record - R 1 for record - R	Water D g date of any purchand true ve . Required sub completion in a m ling reclamation the attached / & MOCD	Disposal roposed work and appre- rical depths of all perti- sequent reports must b new interval, a Form 3 I n, have been completed JU DISTRICT	inent markers and zones. the filed within 30 days 60-4 must be filed once 1 and the operator has RECEIVED JL 1 1 2018
 13. Describe Proposed or Comp If the proposal is to deepen of Attach the Bond under which following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed ATTACHMENTS: PROCEDURES MIT 500 PSI MIT 1000 PSI CURRENT WELLBOR MIT 1000 PSI CURRENT WELLBOR 14. Thereby certify that the formation 	Convert to Injection Convert to Injection Convertional Convertion Convertional Convert Convertional Convert Convert Convert Convert Convert Convert Convert Convert	Plup prot details, includ give subsurface the Bond No. o sults in a multip led only after all s TA status for Accepted H404008 verifie BY PRODUCTION	g Back ding estimated startin e locations and measu in file with BLM/BI/ le completion or reco requirements, includ or two years with 7 - / 2 5 for record - R 6 for record - R	Water D g date of any p irred and true ve . Required sub ompletion in a n ling reclamation the attached / & MOCD	Disposal roposed work and appre- rical depths of all perti- sequent reports must b new interval, a Form 3 I n, have been completed JU DISTRICT	inent markers and zones. the filed within 30 days 60-4 must be filed once 1 and the operator has RECEIVED JL 1 1 2018
 13. Describe Proposed or Comp If the proposal is to deepen of Attach the Bond under which following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed ATTACHMENTS: PROCEDURES MIT 500 PSI MIT 1000 PSI CURRENT WELLBOR URRENT WELLBOR 14. I hereby certify that the for Name (Printed/Typed) BR 	Convert to Injection Convert to Injection Convertion Convert to Injection Convert to Injection Convert to Injection Convert to Injection Convertion Convert to Injection Convertion Convert to Injection Convert to Injection Convertion Convertion Convert to Injection Convertion	Plup prot details, includ give subsurface the Bond No. o sults in a multip led only after all s TA status for Accepted H404008 verifie BY PRODUCTION	g Back ding estimated startin e locations and measu in file with BLM/BI/ le completion or reco requirements, includ or two years with 7 - / 2 5 for record - R 6 for record - R	Water D g date of any pr rcd and true ve . Required sub ompletion in a r ling reclamation the attached / & MOCD il Information to the Carls n 02/15/2018 .ATORY PRO	Disposal roposed work and appre- rical depths of all perti- sequent reports must b we interval, a Form 3 I n, have been completed JU DISTRICT System bad (17PP0988SE)	inent markers and zones. the filed within 30 days 60-4 must be filed once 1 and the operator has RECEIVED JL 1 1 2018
 13. Describe Proposed or Comp If the proposal is to decpen of Attach the Bond under which following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed ATTACHMENTS: PROCEDURES MIT 500 PSI MIT 1000 PSI CURRENT WELLBOR URRENT WELLBOR 14. I hereby certify that the for Name (Printed/Typed) BR 	Convert to Injection Convert to Injection Convertion Convert to Injection Convertion Convert to Injection Convertion Convert to Injection Convertion Convertion Convert to Injection Convertion	Plup nt details, includ give subsurface the Bond No. o sults in a multip led only after all s TA status for Accepted H404008 verifie SY PRODUCTING Sy PRODUCTING	g Back ding estimated startin e locations and measu in file with BLM/BI/ le completion or reco requirements, includ or two years with 7 - / 2 1 for record - R 1 for REGUL Date 02/09/2	Water D g date of any pi rcd and true ve . Required sub ompletion in a r ling reclamation the attached / & MOCD II Information t to the Carlsi n 02/15/2018 ATORY PRO	Disposal roposed work and appre- rrical depths of all perti- sequent reports must b new interval, a Form 31 n, have been completed JU DISTRICT System bad (17PP0988SE) OFESSIONAL	inent markers and zones. the filed within 30 days 60-4 must be filed once 1 and the operator has RECEIVED JL 1 1 2018
13. Describe Proposed or Comp If the proposal is to deepen of Attach the Bond under which following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed ATTACHMENTS: PROCEDURES MIT 500 PSI MIT 1000 PSI CURRENT WELLBOR UPPOLO ISI CURRENT WELLBOR Id. I hereby certify that the for Name (Printed/Typed) BR Signature (Elector)	Convert to Injection Convert to Injection Convertion Convertion Convertion Convertion Convertion Convert to Injection Convertion Co	Plup nt details, includ give subsurface the Bond No. o sults in a multip led only after all s TA status for Accepted H404008 verifie SY PRODUCTING Sy PRODUCTING	g Back ding estimated startin e locations and measu in file with BLM/BIL/ le completion or reco requirements, includ or two years with 7 - / 2 for record - R for record - R for record - R for COM LP, sent (SCILLA PEREZ o Tide REGUL	Water D g date of any pi rcd and true ve . Required sub ompletion in a r ling reclamation the attached / & MOCD II Information t to the Carlsi n 02/15/2018 ATORY PRO	Disposal roposed work and appri- rical depths of all perti- sequent reports must b- new interval, a Form 31- n, have been completed JU DISTRICT System bad (17PP0988SE) OFESSIONAL	inent markers and zones. See filed within 30 days 60-4 must be filed once 1 and the operator has RECEIVED JL 1 1 2018 T II-ARTESIA O.C.D.
13. Describe Proposed or Comp If the proposal is to deepen of Attach the Bond under which following completion of the testing has been completed. determined that the site is re Devon Energy Product procedures completed ATTACHMENTS: PROCEDURES MIT 500 PSI MIT 1000 PSI CURRENT WELLBOR I. I hereby certify that the for Name (Printed/Typed) BR Signature (Ele Approved By Conditions of approval, if any, an	Convert to Injection Convert to Injection Convertion Convert to Injection Convert to Injection Convertion Convert to Injection Convertion Convertion Convertion Convert to Injection Convertion Conv	Plup Int details, includ- give subsurface the Bond No. o sults in a multip led only after all s TA status for G C- Accepted H404008 verifie BY PRODUCTING BY PRO	g Back ding estimated startin e locations and measu in file with BLM/BI/ le completion or record requirements, includ or two years with for record - P for record - P for record - P for COM LP, sent SCILLA PEREZ o Title REGUL Date 02/09/2 COPPERDE	Water D g date of any pi red and true ve . Required sub ompletion in a r ling reclamation the attached / & MOCD II Information t to the Carlsi n 02/15/2018 ATORY PRO	Disposal roposed work and appri- rrical depths of all perti- sequent reports must b- new interval, a Form 31- n, have been completed JU DISTRICT System bad (17PP0988SE) OFESSIONAL SORD	inent markers and zones. the filed within 30 days 60-4 must be filed once 1 and the operator has RECEIVED JL 1 1 2018



t

۰.

HB 11 Fed 5 Temporary Abandonment

Summary: TOOH rod string and pump, unset TAC, TOOH tubing and BHA, RIH and set CIBP, cap with cement, run CBL, perform MIT with BLM notification / witness

Rig anchors on location have been tested SATISFACTORY

WBS MM-125224.CA.WWO is approved for \$55,756.00

Potato Basin Workover Team,

The **HB 11 Fed 5** is to be Temporarily Abandoned to evaluate uphole potential. As part of the TA process, we will install a CIBP above the existing perforated interval, cap with cement, and pressure test the wellbore.

Note the following in the approved TA Sundry:

- Complete a CBL after tagging cement to validate uphole potential perforated intervals.
- Complete a 500 PSIG MIT for 30 min. on a 1 hour, 1,000 PSIG chart recorder for submission to the BLM.
- Maintain a copy of the approved sundry procedure on location at all times.

H2S: No history of H2S on the HB 11 Fed 5; however, all normal H2S monitoring precautions are still required

BLM Contact: Paul Schwartz – Office: (575) 234-5985 or Office: (575) 361-2822 *Contact at least 24 hours prior to performing MIT*

HB 11 Fed 5 Pre-TA Notes:

- 2nd BSSS perforated interval from 7,956' to 7,963', 8,108' to 8,121', and 8,128' to 8,132' MD.
- Current PBTD: 8,408' in 2006.
- 5 ½" 17# J-55 casing set from surface to 8,497' MD.
- CIBP to be set between 7,850' and 7,940' MD per approved sundry.
- Note full Conditions of Approval in Approved Sundry. Contact engineering if there is a conflict between this procedure and the Approved Sundry.
- 1. Hold tailgate safety meetings prior to R.U., each morning and before each operational change or event. Clearly identify the Person In Charge.
- 2. Bleed down casing pressure and top kill well as needed with KCL brine.
- 3. This well is being pulled in preparation for Temporary Abandonment.

NORM Check required for equipment leaving location & downhole parts left on surface

- a. ND wellhead. NU rod rams.
- b. TOOH rod string as follows:

RCD		Run Oale 4:1/2014				58		
tiem Oes	JB	(n; CD	Grade	Cond Run	Cond Put	Len (ft)	Top (1KB;	8:m;ft(f8)
POLISH RCD		115				26.00		211
RODS		775	· · · ·	 		5.00	110	
RODS	103	7/8				2.575.00		1 ::- :
RODS	202	3:4				5.050.00	1 2 2 2 2	
RODS	20	7/5				500.00	1111	
RODS	'	1		···		1:0		
RHEC PUMP		2 1/2				20.00		

c. ND rod rams.

 NU 5,000 psig BOP with 1 set of blind rams on bottom and 1 set of 2 7/8" tubing rams on top. Test BOP to Devon specifications. Ensure 2 7/8" TIW available on location for well control.

PROD TUBING set at 6	,193.4ftKB on 3	15/2006	00:00					
Turny 14220100 FF1112 Turny 14	FL* 1916 : 51111	Fur Isle : f 1000				541 Depth - EOT (47 5) 5. 193-4		
ಮೇಗ Des	JL	00 (n)	WC DT.	Grafa	Ler (fi)	Teo (DG)	8:m (RKE)	
-E 3	126	27/8	6.50	0-55	41114-		- 117-	
	12'	2713	6 53	1.50				
	1	5 1/2						
-::	3	17/8	£ 53	LEO	25.5	- ::: :	• • • • •	
CELT PALE		27.8	6.50		···	1 1 1 1 1	• • • •	
===F::e	1	27/2	6.50	3-35	• ::	1 1 1 1	: ::: :	
	1	27/5	6 50	1-20			1.13	
5	1	2 7/8	£.50			÷ : 2 : 1		
	0			 		1 1 1 2 4		

е.	Unset	TAC.	тоон	tubing	string	as	follows


- 4. RIH w/ Wireline and set CIBP between 7,850' and 7,940' MD per BLM approved procedure.
- 5. Pressure test casing to 500 PSIG for 30 minutes to verify casing will pass MIT. Contact foreman and engineering if casing fails integrity check.
- 6. RIH and complete CBL past top of cement. Complete casing integrity log to surface. Obtain copies for BLM and engineering.
- 7. TIH with 2 7/8" tubing and cap CIBP with 35' of cement. Wait on cement.
- 8. TIH and tag top of cement to verify PBTD. TOOH tubing string.
- 9. Prior to performing MIT, contact BLM Engineer Paul Schwartz via contact info.
 - a. Use a 1 hr circular chart rated for 1,000 PSIG.
 - b. Fill casing with corrosion inhibited fluid.
 - c. Test casing at surface to 500 psig. Record pressure on chart for 30 minutes.
 - d. Maintain chart for submission to BLM and Devon Engineering.

10. Shut in well. RDMO.

Additional Notes:

- Record any relevant information in daily reports too much information/data will never be an issue.
- SAFETY FIRST anyone has the authority to stop work if an activity appears unsafe. Be proactive on any procedural or technical recommendations and relay any ideas along for discussion.

· Contact	Company	Office #	Mobile #
Tracy Egeland	Devon - Workover Foreman	(575) 746-5593	(575)513-9290
Joe Koessler	Devon – Engineer	(405) 228-8407	(405) 880-6627
Wesley Ryan	Devon – Foreman	(575)748-0177	(575)390-5436
Leonard Aguilar	Devon – Assistant Foreman	(575)234-0207	(575) 234-0242
Paul Schwartz	BLM Engineer	(575) 361-2822	(575) 234-5985




۰ ·

WELLBORE DIAGRAM PARTS LIST

. •

. . . .

٠



Je wa