	State of New Mexico Energy, Minerals and Natural Resources		_	Form C-103	
Office <u>District I</u> – (575) 393-6161	Energy, Minerals a	nd Natui	ral Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	D1 - 1 - 17 - 4550 G40 1000			WELL API NO. 30-015-44741	
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of Leas	Se .	
District III - (505) 334-6178	1220 South St. Francis Dr.			STATE	FEE 🛛
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460				6. State Oil & Gas Lease	
1220 S. St. Francis Dr., Santa Fe, NM	·				
87505 SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit A	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				Morris Boyd State Com	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					
1. Type of Well: Oil Well Gas Well Other				8. Well Number 4H	
2. Name of Operator				9. OGRID Number	
Percussion Petroleum Operating LLC 3 Address of Operator				371755 10. Pool name or Wildcat	
3. Address of Operator 919 Milam St. Suite 2475 Houston, TX 77002				10. Foot hance of white	, at
4. Well Location					
Unit Letter N:	555 feet from the	sout	th line and	1580 feet from the	e west line
Section 23	Township	19S	Range 25E	NMPM	County Eddy
Ovedon.	11. Elevation (Show who)	
	3431 GR				
12. Check A	Appropriate Box to Inc	licate N	ature of Notice,	Report or Other Data	
NOTICE OF IN	TENTION TO:		l SUB	SEQUENT REPOR	T OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WOR		RING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR		_
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMEN	_	
DOWNHOLE COMMINGLE					
CLOSED-LOOP SYSTEM					-
OTHER:			OTHER:		⊠
Describe proposed or comp	leted operations. (Clearly	state all p	pertinent details, an	d give pertinent dates, incl	luding estimated date
of starting any proposed we	ork). SEE RULE 19.15.7.1	state all j 14 NMAC	pertinent details, an	d give pertinent dates, incl mpletions: Attach wellbor	luding estimated date re diagram of
 Describe proposed or comp of starting any proposed we proposed completion or rec 	ork). SEE RULE 19.15.7.1	state all j 14 NMAC	pertinent details, an	d give pertinent dates, incl mpletions: Attach wellbor	luding estimated date re diagram of
of starting any proposed we proposed completion or rec	ork). SEE RULE 19.15.7.1 completion.	14 NMA(pertinent details, an C. For Multiple Co	mpletions: Attach wellbor	luding estimated date re diagram of
of starting any proposed we proposed completion or rec	ork). SEE RULE 19.15.7.1 completion. re test on 9-5/8" surface ca	14 NMAC	pertinent details, an C. For Multiple Co 400 psi for 30 minu	mpletions: Attach wellbor test, lost 0 psi, good test.	re diagram of
of starting any proposed we proposed completion or recompletion of recompletion of 3/28/18 perform pressure on 4/21/18 perform Pre fra	ork). SEE RULE 19.15.7.1 completion. re test on 9-5/8" surface ca	14 NMAC	pertinent details, an C. For Multiple Co 400 psi for 30 minu	mpletions: Attach wellbor test, lost 0 psi, good test.	re diagram of
of starting any proposed we proposed completion or rec	ork). SEE RULE 19.15.7.1 completion. re test on 9-5/8" surface ca	14 NMAC	pertinent details, and C. For Multiple Co. For Multiple Co. 400 psi for 30 minulong string. Tested to	mpletions: Attach wellbor ntes, lost 0 psi, good test. to 6500 psi for 30 minutes	re diagram of
of starting any proposed we proposed completion or recompletion of recompletion of 3/28/18 perform pressure on 4/21/18 perform Pre fra	ork). SEE RULE 19.15.7.1 completion. re test on 9-5/8" surface ca	14 NMAC	pertinent details, and C. For Multiple Co. 400 psi for 30 minulong string. Tested to NM C	mpletions: Attach wellbor ates, lost 0 psi, good test. to 6500 psi for 30 minutes	re diagram of
of starting any proposed we proposed completion or recompletion of recompletion of 3/28/18 perform pressure on 4/21/18 perform Pre fra	ork). SEE RULE 19.15.7.1 completion. re test on 9-5/8" surface ca	14 NMAC	pertinent details, and C. For Multiple Co. 400 psi for 30 minulong string. Tested to NM C	mpletions: Attach wellbor ates, lost 0 psi, good test. to 6500 psi for 30 minutes ML CONSERVATION RTESIA DISTRICT	re diagram of
of starting any proposed we proposed completion or recompletion of recompletion of 3/28/18 perform pressure on 4/21/18 perform Pre fra	ork). SEE RULE 19.15.7.1 completion. re test on 9-5/8" surface ca	14 NMAC	pertinent details, and C. For Multiple Co. 400 psi for 30 minulong string. Tested to NM C	mpletions: Attach wellbor ates, lost 0 psi, good test. to 6500 psi for 30 minutes	re diagram of
of starting any proposed we proposed completion or recompletion of recompletion of 3/28/18 perform pressure on 4/21/18 perform Pre fra	ork). SEE RULE 19.15.7.1 completion. re test on 9-5/8" surface ca	14 NMAC	pertinent details, and C. For Multiple Co. 400 psi for 30 minulong string. Tested to NM C	mpletions: Attach wellbor ates, lost 0 psi, good test. to 6500 psi for 30 minutes ML CONSERVATION RTESIA DISTRICT	re diagram of
of starting any proposed we proposed completion or rec On 3/28/18 perform pressu On 4/21/18 perform Pre fra	ork). SEE RULE 19.15.7.1 completion. re test on 9-5/8" surface ca	14 NMAC	pertinent details, and C. For Multiple Co. 400 psi for 30 minulong string. Tested to NM C	mpletions: Attach wellbor ates, lost 0 psi, good test. to 6500 psi for 30 minutes ML CONSERVATION RTESIA DISTRICT	re diagram of
of starting any proposed we proposed completion or rec On 3/28/18 perform pressu On 4/21/18 perform Pre fra	ork). SEE RULE 19.15.7.1 completion. re test on 9-5/8" surface ca	14 NMAC	pertinent details, and C. For Multiple Co. 400 psi for 30 minulong string. Tested to NM C	ites, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RTESIA DISTRICT JUL 2 0 2018	re diagram of
of starting any proposed we proposed completion or recompletion of recompletion of 3/28/18 perform pressure on 4/21/18 perform Pre fra	ork). SEE RULE 19.15.7.1 completion. re test on 9-5/8" surface ca	14 NMAC	pertinent details, and C. For Multiple Co. 400 psi for 30 minulong string. Tested to NM C	ites, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RTESIA DISTRICT JUL 2 0 2018	re diagram of
of starting any proposed we proposed completion or recompletion of recompletion of 3/28/18 perform pressure on 4/21/18 perform Pre fra	ork). SEE RULE 19.15.7.1 completion. re test on 9-5/8" surface ca	14 NMAC	pertinent details, and C. For Multiple Co. 400 psi for 30 minulong string. Tested to NM C	ites, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RTESIA DISTRICT JUL 2 0 2018	re diagram of
of starting any proposed we proposed completion or recompletion or recompletio	ork). SEE RULE 19.15.7.1 completion. The test on 9-5/8" surface can be casing pressure test on 7	14 NMAC	pertinent details, and C. For Multiple Co. 400 psi for 30 minuong string. Tested to A.	ites, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RTESIA DISTRICT JUL 2 0 2018	re diagram of
of starting any proposed we proposed completion or recompletion of recompletion of 3/28/18 perform pressure on 4/21/18 perform Pre fra	ork). SEE RULE 19.15.7.1 completion. The test on 9-5/8" surface can be casing pressure test on 7	ising to l	pertinent details, and C. For Multiple Co. 400 psi for 30 minuong string. Tested to A.	ites, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RTESIA DISTRICT JUL 2 0 2018	re diagram of
of starting any proposed we proposed completion or recompletion or recompletio	ork). SEE RULE 19.15.7.1 completion. The test on 9-5/8" surface can be casing pressure test on 7	ising to l	pertinent details, and C. For Multiple Co. 400 psi for 30 minuong string. Tested to A.	ites, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RTESIA DISTRICT JUL 2 0 2018	re diagram of
of starting any proposed we proposed completion or recompletion or recompletio	ork). SEE RULE 19.15.7.1 completion. The test on 9-5/8" surface can be casing pressure test on 7. Rig R	asing to 14" x 5.5" 1	pertinent details, and C. For Multiple Co. 400 psi for 30 minutong string. Tested to A.	ites, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RTESIA DISTRICT JUL 2 0 2018 RECEIVED	re diagram of
of starting any proposed we proposed completion or recompletion or recompletio	ork). SEE RULE 19.15.7.1 completion. The test on 9-5/8" surface can be casing pressure test on 7. Rig R	asing to 14" x 5.5" 1	pertinent details, and C. For Multiple Co. 400 psi for 30 minutong string. Tested to A.	ates, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RECEIVED ge and belief.	and lost 66 psi, good
of starting any proposed we proposed completion or recompletion or recompletio	ork). SEE RULE 19.15.7.1 completion. The test on 9-5/8" surface can be casing pressure test on 7. Rig R. Tabove is true and complet	e to the b	pertinent details, and C. For Multiple Co. 400 psi for 30 minutong string. Tested to NM O. A.	ates, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RECEIVED ge and belief.	and lost 66 psi, good
of starting any proposed we proposed completion or recompletion or recompletio	re test on 9-5/8" surface can casing pressure test on 7 Rig R above is true and complet	e to the b	pertinent details, and C. For Multiple Co. 400 psi for 30 minutong string. Tested to NM O. A.	mpletions: Attach wellbor ates, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RECEIVED RECEIVED ge and belief.	7/18/18
of starting any proposed we proposed completion or recompletion or recompletio	re test on 9-5/8" surface can casing pressure test on 7 Rig R above is true and complet	e to the b	pertinent details, and C. For Multiple Co. 400 psi for 30 minutong string. Tested to NM O. A.	ates, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RECEIVED ge and belief.	7/18/18
of starting any proposed we proposed completion or recompletion or recompletio	re test on 9-5/8" surface can casing pressure test on 7 Rig R above is true and complet	e to the b	pertinent details, and C. For Multiple Co. 400 psi for 30 minutong string. Tested to NM O. A.	mpletions: Attach wellbor ates, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RECEIVED RECEIVED ge and belief. phone: _979-292	7/18/18
of starting any proposed we proposed completion or recompletion on 4/21/18 perform Pre fratest. Spud Date: I hereby certify that the information of the state Use Only Type or print name Ryan Barbe For State Use Only	Rig R above is true and complet TITI E-mail address: _ry	e to the b	pertinent details, and C. For Multiple Co. 400 psi for 30 minutong string. Tested to NM O. A.	mpletions: Attach wellbor ates, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RECEIVED RECEIVED ge and belief. phone: _979-292	7/18/18
of starting any proposed we proposed completion or recompletion or recompletio	re test on 9-5/8" surface can casing pressure test on 7 Rig R above is true and complet	e to the b	pertinent details, and C. For Multiple Co. 400 psi for 30 minutong string. Tested to NM O. A.	mpletions: Attach wellbor ates, lost 0 psi, good test. to 6500 psi for 30 minutes IL CONSERVATION RECEIVED RECEIVED ge and belief. phone: _979-292	7/18/18