Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103		
Office <u>District 1</u> - (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011		
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
<u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-29405 5. Indicate Type of Lease		
District III - (505) 334-6178	1220 South St. Francis Dr.		STATE	FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460	Santa Fe, NM 87505		6. State Oil & G		
1220 S. St. Francis Dr., Santa Fe, NM	,		,		
87505 SUNIDRY NOTICES AND REPORTS ON WELLS			7 I eace Name o	or I Init Agreement Name	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Todd 36 O State		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other NM OIL CONSERVATION			8. Well Number 10		
2. Name of Operator				9. OGRID Number	
Devon Energy Production Comp	any, LP		6137		
3. Address of Operator	AUG U 7 2018		10. Pool name or Wildcat		
333 W. Sheridan Avenue, Oklahoma City, OK 73102			Ingle Wells; De	elaware	
4. Well Location RECEIVED					
Unit Letter <u>o</u> :	660 feet from the South	line and198		om the East line	
Section 36		inge 31E	NMPM Edd	y County, NM	
	11. Elevation (Show whether DR,	-	'		
3518' KB; 3506' GL; 12' KB to GL					
12. Check Appropriate Poy to Indicate Nature of Natice, Papert or Other Date					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK					
TEMPORARILY ABANDON	CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A 🔼				
PULL OR ALTER CASING	B ☐ MULTIPLE COMPL ☐ CASING/CEMENT JOB ☐				
DOWNHOLE COMMINGLE					
OTHER:	П	OTHER:		П	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion.					
1. 7/16/18 Notify OCD 24 HRS Prior To MIRU To P&A intent					
2. 7/17/18 Set 5 1/2" CIBP @ 70	•				
3. 7/18/18 Circ 170 bbls mlf pressure test 500 psi spot 45x class c cmt 7055'-6605' Tag toc @ 6601' spot 25x class c cmt 5100' - 4850' Tag toc @ 4841					
 7/19/18 Spot 45sx class c cmt @ 4550' - 4100' Tag toc @4085' 7/20/18 Sqz 85x class c cmt @ 1190' - 830', 5 1/2"x 8 5/8" tag toc @ 798' perf/circ 35x class c cmt 140' - surf 5 1/2" x 8 5/8" Verify cmt @ surf 					
6. 7/23/18 Cut off wellhead and anchors and cleaned location, set dry hole marker. P & A completed					
,					
Spud Date:	Rig Release D	200			
Spud Date.	Nig Release D	atc.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
	/ //				
SIGNATURE	TITLE	Agent		DATE 07/20/18	
Time or print name Jimmy Bagley	0 U	sunsetwellsen/ice@)vahoo.com ~	432-561-8600	
Type of print name PHONE.					
For State Use Only					
APPROVED BY:	TITLE STA	# M.	D	ATE 8-10-18	
Conditions of Approval (if any):					

.

- - .