

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OPERATOR'S COPY

FORM APPROVED
OMB No. 1004-0135
Expires: January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

APR 0 5 2006

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other Disposal

2. Name of Operator

Nadel and Gussman Permian LLC

3a. Address

601 N. Marienfeld Suite 508

3b. Phone No. (include area code)

432-682-4429

4. Location of Well (Footage, Sec., T, R., M., or Survey Description)

UL D 1650 FNL, 660 FWL, Sec. 16, T 15S, R 29E

5. Lease Serial No.

NM- 54400

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Shell 15 Federal No. 1

9. API Well No.

30-005-10185

10. Field and Pool, or Exploratory Area

Lucky Lake Queen

11. County or Parish, State

Chaves, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Acidize ☐ Deepen ☐ Production (Start/Resume) ☐ Water Shut-Off
☐ Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity
☐ Casing Repair ☐ New Construction ☐ Recomplete ☐ Other
☐ Change Plans ☐ Plug and Abandon ☒ Temporarily Abandon
☐ Convert to Injection ☐ Plug Back ☐ Water Disposal


3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Request ta status for 1 year to bring well into NMOCD compliance. Our plan is to TA the well and then plug it with in 12 months.
Plan to set cibp above the Queen perfs @ 1800' cap w/ 50 cmt.
Pressure test csg to 500 psi.

Submit P&A procedures, well to be P&A w/in one year.

Plugging Procedures Requires:

- 1) CIBP @ 1800 + 50 cmt.
- 2) 25 sx (450 to 350 ft) and TAG
- 3) Perf and Sqz minimum 50 feet at Surface



APPROVED FOR 12 MONTH PERIOD
ENDING 4-9-07

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Kem E. McCready

Title NM Operations Manager

Signature

K. E. McCready

Date March 29, 2006

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by (Signature)

Name
(Printed/Typed)

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Date

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Continued on next page)

Authority to injection has been withdrawn IAW Rule
19.15.9.705. C (i)
APR 27 2006