Form 3160-5 (June 2015)

AUG 1 6 2018 UNITED STATES AUG 1 6 2018

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT II-ARTESIA O.C.D.

SUNDRY NOTICES AND REPORTS ON WELLS

Poor use this form for proposals to drill or to recenter and

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Э.	NMNM			
_	TOT I	4.11	 	

Do not use th	<u> </u>	6. If Indian, Allottee or Tribe Name						
abandoned we	6. If Indian, Allottee							
SUBMIT IN	TRIPLICATE - Other instruction	ons on page 2	7. If Unit or CA/Ag	7. If Unit or CA/Agreement, Name and/or No.				
Type of Well	her	,	8. Well Name and N NAGOOLTEE F	8. Well Name and No. NAGOOLTEE PEAK 5 FEDERAL COM 3				
2. Name of Operator OXY USA WTP LP	Contact: DAVII E-Mail: david_stewart@o	D STEWART oxy.com	9. API Well No. 30-015-29900	9. API Well No. 30-015-29900				
3a. Address P.O. BOX 50250 MIDLAND, TX 79710		Phone No. (include area code) 432-685-5717	10. Field and Pool o INDIAN BASIN					
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)		11. County or Parish	11. County or Parish, State				
Sec 5 T22S R24E SWSW 123 32.415985 N Lat, 104.526245			EDDY COUNT	ΓY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES) TO IN	NDICATE NATURE OF	F NOTICE, REPORT, OR OT	THER DATA				
TYPE OF SUBMISSION	YPE OF SUBMISSION TYPE OF ACTION							
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off				
	☐ Alter Casing	☐ Hydraulic Fracturing	■ Reclamation	■ Well Integrity				
Subsequent Report	□ Casing Repair	■ New Construction	□ Recomplete	□ Other				
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	☐ Temporarily Abandon					
	☐ Convert to Injection	□ Plug Back	■ Water Disposal					
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filled within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filled once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  7/12/18 - MIRU PU, NDWH, NUBOP, RIH w/ gauge ring, tag up @ 7980', POOH. RIH & set CIBP @ 7964', POOH.  7/16/18 - RIH & tag CIBP @ 7964', PUH, circ hole w/ 10# MLF, M&P 70sx CL H cmt, PUH, WOC.  7/17/18 - RIH & tag cmt @ 7673', verified by BLM. PUH to 6385', M&P 40sx CL C cmt, PUH, WOC. RIH & tag cmt @ 6186', PUH & set pkr @ 4693', RIH & perf @ 4950', EIR @ 2bpm @ 1000#, M&P 60sx CL C cmt, got returns to surface.  7/18/18 - RIH & tag cmt @ 4819', PUH & set pkr @ 2536'. RIH & perf @ 2945', attempt to EIR, pressure to 1850#, no rate or loss. Notify BLM, request perf @ 2935'. RIH & perf @ 2935', attempt to EIR, pressure to 2200#, no rate or loss. Rec approval BLM to spot 70sx cmt plug. POOH w/ pkr,								
Electronic Submission #430438 verified by the BLM Well Information System For OXY USA WTP LP, sent to the Carisbad								
Name (Printed/Typed) DAVID ST	EVVARI	Title SR. REC	SULATORY ADVISOR					
Signature (Electronic S	Submission)	Date 08/09/20	018					
	THIS SPACE FOR FE	DERAL OR STATE (	OFFICE USE					
Approved By		Title		Date				
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu	uitable title to those rights in the subject	rrant or		•				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime for statements or representations as to any	or any person knowingly and matter within its jurisdiction.	willfully to make to any department o	or agency of the United				

## Additional data for EC transaction #430438 that would not fit on the form

## 32. Additional remarks, continued

RIH to 3012', M&P 70sx CL C cmt, POOH, WOC. RIH w/ pkr & tag cmt @ 2875', notify BLM of tag, request perf @ 2864'. PUH & set pkr @ 2536', RIH & perf @ 2864', attempt to EIR, pressure to 1700#, no rate or loss.

7/19/18 - POOH w/ pkr, RIH w/ tbg to 2853', M&P 45sx CI C cmt, POOH, WOC. RIH & tag cmt @ 2588', notified BLM of tag. PUH & set pkr @ 1426', RIH & perf @ 1670', attempt to EIR, pressure to 2200#, no rate or loss. Rec BLM Approval to spot plug. RIH to 1712', M&P 45sx CL C cmt, PUH, WOC.

7/23/18 - RIH & tag cmt @ 1451', POOH. RIH & set pkr @ 1046', RIH & perf @ 1290', EIR @ .5bpm @ 1900#. Pkr came unset, POOH w/ pkr, RIH w/ tbg to 1371', M&P 45sx CI C cmt, PUH, WOC.

7/24/18 - RIH & tag cmt @ 1188', POOH. RIH & perf @ 405', EIR @ 1.5bpm @ 1000# w/ full returns to surface. ND BOP, NU adapter flange, M&P 135sx CI C cmt, circ cmt to surface on all strings. RDPU.