Submit I Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I - (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			30-015-28522	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III - (505) 334-6178	1220 South St. Francis Dr.		STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lea	ise No.
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SWS Inv# 13695 SUNDRY NOTICES AND REPORTS ON WELLS		95	7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPE	DSALS TO DRILL OR TO DEEPEN OR PLU	G BACK TO A		
DIFFERENT RESERVOIR. USE "APPL	ICATION FOR PERMIT IFORM C-1011 FO	R SLICH I	Todd 36 C State	j
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other APTESIA DISTRICT		8. Well Number 7		
1. Type of Well: Oil Well Gas Well Other ARTESIA DISTRICT 2. Name of Operator		ESIA DISTRICT	9. OGRID Number	
Devon Energy Production Company, LP 007 79 2018			6137	
3. Address of Operator		10. Pool name or Wildcat		
333 W. Sheridan Avenue, Oklahoma City, OK 73102		ingle Wells; Delaware		
4. Well Location RECEIVED				
Unit Letter C	: 660 feet from the North	_	1650 feet from the	: Westline
		nge 31E	_	unty NM
Section 36	11. Elevation (Show whether DR,			
	3504' GL	141D, 1(1, O1, C.C.)		* · · · · · · · · · · · · · · · · · · ·
the state of the s	300 00			
12 Check	Appropriate Box to Indicate N	ature of Notice.	Report or Other Dat	a
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				TERING CASING
TEMPORARILY ABANDON			_	ND A 🔼
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT			L JOB \square	
DOWNHOLE COMMINGLE]			
OTHER:	П	OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
1. 10/10/18 Notify OCD of intent.				
2. 10/11/18 Set 5 1/2" CIBP @ 7050'.				
3. 10/12/18 Verify CIBP @ 7050' w/2 3/8" tbg. circ 170 bbl MLF. Press test well 500 psi. Good. Spot 40 sx class "c" cmt @ 7050'-6660' TOC				
@ 6603'. 4. 10/13/18 Perf/press up @ 4429'. Spot 35 sx class "c" cmt @ 4480'-4160'. Tag TOC @ 4121'. Perf/sqz 50 sx class "c" cmt @ 900'-740'.				
Tag TOC @ 719'.				
5. 10/16/18 Perficirc 75 sx class "c" cmt @ 140'-surf 5 1/2" x 8 5/8". Verify cmt @ surf. Cut off wellhead, anchors and cleaned location, set				
hole marker. P&A completed				
note mainer, i with the process				
•				
Spud Date:	Rig Release D	ate:		4
L		<u> </u>		'
	•		<u> </u>	
I hereby certify that the information	on above is true and complete to the b	est of my knowledg	ge and belief.	
\sim				
	/ // minute	Agent	DATE	10/17/18
SIGNATURE 2	TITLE	Agent	DATE	
Type or print name E-mail address: sunsetwellservice@yahoo.com PHONE: 432-561-8600				
Type or print name E-mail address: Sunsetweilservice@yanoo.com PHONE: For State Use Only				
. VI State VSE VIII		~		11 , 18
APPROVED BY:	TITLE	Hore	DATE	11-1-10
Conditions of Approval (if any):				

