Form 3,50-5 च (June 2015) Е	UNITED STATES EPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SDAO FIELO				FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
SUNDRY	INOTICES AND REPOR	IS ON W	LLS.		StateseSerial No. NMLC0289921		
Do not use this form for proposals to drill or to re-enter and A TOPS abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. 8910085020		
1. Type of Well					8. Well Name and No. GB JACKSON TR12 1		
Oil Well Gas Well Other: INJECTION Ontact: ZAYMAN J VILLEGAS					9. API Well No. 30-015-04339-00-S1		
SAGUARO PETROLEUM E-Mail: zayman@saguaropetroleum.com 3a. Address 3b. Phone No. (include area code)					10. Field and Pool or Exploratory Area		
1509 W WALL STREET SU MIDLAND, TX 79701-6576	8-5289		GRAYBURG				
4. Location of Well (Footage, Sec.,		11. County or Parish, State					
Sec 26 T17S R30E SENW 1			EDDY COUNTY, NM				
12. CHECK THE A	APPROPRIATE BOX(ES) T	O INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent			Deepen		ion (Start/Resume)	U Water Shut-Off	
_	Alter Casing	🗖 Hyd	raulic Fracturing	🗖 Reclam	ation	Well Integrity	
Subsequent Report	Casing Repair	🗖 Nev	Construction	🗖 Recomp	olete	Other Workover Operations	
Final Abandonment Notice	Change Plans	-	and Abandon		arily Abandon		
	Convert to Injection	🗖 Plug	Back	U Water I	Disposal		
If the proposal is to deepen direction Attach the Bond under which the w following completion of the involv testing has been completed. Final determined that the site is ready for	ork will be performed or provide it ed operations. If the operation resu Abandonment Notices must be filed final inspection.	he Bond No. or ilts in a multipl I only after all	a file with BLM/BIA e completion or reco requirements, includ	Required sub impletion in a r ing reclamation	osequent reports must be new interval a Form 316	filed within 30 days 0-4 must be filed once nd the operator has	
12/12/18: POOH. LD rods, pump & tbg Accepted for record NMOCD							
12/13/18: Verify PBTD @ 3310.18 (no fill in hole)			FEB 08 2019				
12/14/18: RIH with caliper ar with tools had soft iron sulfid jts. of 2 3/8? white banded tu with used 4 ?? bit, x-over on up 3310? with 12? out of 10 80 bbls. Getting black water hole clean. RD down pump, run Caliper, Gamma Ray log	e on caliper tool. Rigged down bing RIH hole opened POC 106 jts. 2 3/8? tubing did no 7th joint. RU reverse unit pur and iron sulfide in returns. (POOH standing back LD 4 ?	wn wireline a DH standing It feel fill pick mp. Started Circ. with tot	and release. Pick back while waitin ked up 107th join circulating broke al 230 bbls. for 2	ng on bit. RI It tagged e circ. with ! hrs.			
14. I hereby certify that the foregoing	Electronic Submission #44				I System	· · · · · · · · · · · · · · · · · · ·	
Co	For SAGUAR mmitted to AFMSS for proces	O PETROLE ssing by PRI	UM, sent to the C SCILLA PEREZ or	arisbad n 01/11/2019	(19PP0594SE)		
Name (Printed/Typed) ZAYMAN	Title ENGINE	EER					
Signature (Electronic	Date 01/07/20	019					
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE		
Approved Dv			Title 6		······································	FEB 0 1 2019 Date	
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Title J	<u>. </u>	/s/ Jon	athon Shepard	
Title 18 U.S.C. Section 1001 and Title 4 States any false, fictitious or fraudulen	3 U.S.C. Section 1212, make it a cr	rune for any pe	rson knowingly and	willfully to ma	ke to any department or	agency of the United	
(Instructions on page 2)	of representations as to	. any matter w		.			
** BLM RE	VISED ** BLM REVISED	** BLM RE	VISED ** BLN	I REVISED	** BLM REVISE) **	

Additional data for EC transaction #449340 that would not fit on the form

32. Additional remarks, continued

12/17/18:RU wireline RIH to run gamma ray neutron log, from 3310? to 2300? unable to verify existing perfs. or top of liner with log. POOH laid down tools, PU caliper ran caliper log from 3308?to 2852? Top of liner at 2894? could see existing perfs. showed casing wall lost from 3310? to 3240? POOH laid down tools RD wireline. PU 5 ?? AD-1 pkr. 2 3/8? S.N. RIH on 101 jts. 2 3/8? white banded tubing set pkr. @ 3144?. RU acid company. Loaded annulus to 300 PSI to monitor, w/55 bbls. 2% KCL. Tied on to tbg. tested lines to 3400 psi. bled off pressure. Max. Treating Pressure 2000 PSI. to acidize with 1000 gals. 15% HCL Acid with 250# rock salt for diversion as follows.

Establish rate on 2% KCL fresh water 4 BPM 2 bbls. in 12 PSI @ 4 BPM 7 bbls. in 1732 PSI @ 4 BPM tubing loaded 8 bbls. in 1926 PSI @ 4 BPM cut rate to 3.5 BPM On Acid 12 bbls Acid in Dropped 250# RS 3.5 BPM 1312 PSI 16 bbls. Acid in on formation 1571 PSI @ 3.5 BPM On Flush 3.5 BPM Block on 1254 PSI @ 3.5 BPM Block all in 1754 PSI @ 3.5 BPM 500 PSI increase 22 bbls. acid in Broke back 1486 PSI @ 3.6 BPM 24 bbls. acid in on Flush 36 bbls. Flush all in 1186 PSI @ 3.7 BPM ISIP 514 PSI 5 Min. 0 PSI

RD & release acid company. Left well shut for 2 hrs. Started Swabbing into vac. trk at 6:00 PM swabbed 4 hrs. made 17 runs Starting @ 1100 FFS Ending fluid level 2000? FFS. starting sample laden with heavy iron sulfide ending sample clearing with some iron sulfide. Swabbed back 100 bbls. Shut down @ 10:00 PM RD swab Secure well Shut in overnight.

12/18/18: Rel. pkr. POOH standing back laid down pkr. RIH w/ N.C. S.N on 105 jts. 2 3/8? white band tbg. ND BOP land tbg. EOT @ 3263?. RIH picking up w/ Quinn 20-150-RWTC-12-3-0 Insert Pump, 200? #1 Grade ?D? 7/8? rods SH-T #1 cplgs. 122 ?? #1 Grade ?D? ??rods FS-T #1 cplgs. ?? x 4? X 8? rod subs. ? Pins 1 ??x 16? Polish rod with 1 ??x 7? Hung well on. Open flow line. Left well down to load tbg. in morning.

12/19/18: Hot Oil Truck loaded tbg. with 5 bbls. freshwater to 500 psi. held, release pressure pumped up with Pump Jack to 500 psi. Ok. Release Hot Oil Trk. Rigged down Pulling Unit. Left well pumping on Hand going through brooks meter to flowline.