5	Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS OCD Artesia Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM0557142 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.			
	SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well Image: Solid Well in Gas Well in Other 2. Name of Operator Contact: TINA HUERTA Image: Solid Well In Corporation Contact: TINA HUERTA Image: Solid Well In Corporation Contact: TINA HUERTA Image: Solid Well In Corporation Contact: TINA HUERTA									
						8. Well Name and No. NDDUP UNIT 61 Ross EG Fed- 9. API Well No.				
EO							015-26770-0)0-S1		
	3a. Address 105 SOUTH FOURTH STREE ARTESIA, NM 88210	3b. Phone No. (include area code) Ph: 575-748-4168			10. Field and Pool or Exploratory Area N SEVEN RIVERS-GLOR-YESO					
	4. Location of Well (Footage, Sec., T	FEB 08 2019			11. County or Parish, State EDDY COUNTY, NM					
	Sec 20 T19S R25E SWNW 19									
	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE RATURE OF NOTICE, REPORT, OR OTHER						ER DATA			
	TYPE OF SUBMISSION	TYPE OF ACTION								
	Notice of Intent	Alter Casing		epen	Production (Start/Resume			□ Water Shut-Off		
	🛛 Subsequent Report			Hydraulic Fracturing		Reclamation		U Well Integrity		
	☐ Final Abandonment Notice	Casing Repair Change Plans	Belug and Abandon		Recomplete Temporarily Abandon		andon	Other		
		Convert to Injection			U Water E	•				
	3. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.									
	12/5/18 - MIRU and pumped 80 bbls brine. NU BOP. RIH with GR/JB to 2350 ft. Set a CIBP at 2350 ft. RIH with gyro survey to 2350 ft. Tagged CIBP									
×										
:										
	14. I hereby certify that the foregoing is true and correct. Electronic Submission #448542 verified by the BLM Well Information System For YATES PETROLEUM CORPORATION, sent to the Carlsbad Committed to AFMSS for processing by DEBORAH MCKINNEY on 12/20/2018 (19DLM0241SE)									
-	Name (Printed/Typed) TINA HUERTA			Title REGUL	ECIALIST					
· .	Signature (Electronic Submission)			Date 12/19/20	ACCEPTED FOR RECORD					
:		R FEDER	AL OR STATE (SE						
-	Approved By		Title			JAN	3 0 2019			
0	Conditions of approval, if any, are attached ertify that the applicant holds legal or equivalent would entitle the applicant to condu-	oot warrant or subject lease Office			BL	JREAU OF LA	NO MANAGEME			
7	Fitle 18 U.S.C. Section 1001 and Title 43 1 States any false, fictitious or fraudulent s	J.S.C. Section 1212, make it a tatements or representations as	crime for any p to any matter w	erson knowingly and vithin its jurisdiction.	willfully to ma	ike to any	department of	agency of the Uni	ted	
=	(Instructions on page 2) ** BLM REVISED **									



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

-6