

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMNM0440087

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 27. If Unit or CA/Agreement, Name and/or No.
RNM085

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other8. Well Name and No.
FEDERAL CX 22. Name of Operator
EOG Y RESOURCES INCContact: TINA HUERTA
E-Mail: tina_huerta@eogresources.com9. API Well No.
30-015-22128-00-S13a. Address
104 S 4TH STREET
ARTESIA, NM 882103b. Phone No. (include area code)
Ph: 575-748-416810. Field and Pool or Exploratory Area
EAGLE CREEK

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 7 T18S R25E NWSW 1980FSL 660FWL

FEB 14 2019

11. County or Parish, State
EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

EOG Resources, Inc. plans to plug and abandon this well as follows:

1. MIRU all safety equipment as needed. POOH with production equipment.
2. RIH with GR/JB to 6467 ft.
3. Set a CIBP at 6442 ft and dump bail 35 ft Class H on top. This will cover the top of Penn and the Penn perforations. Tag TOC.
4. Pump a 25 sx Class C cement plug from 5166 ft ? 5046 ft covering the top of the Wolfcamp.
5. Perforate at 4021 ft. Attempt to establish circulation between the 4-1/2 inch and 8-5/8 inch casing and pump a 60 sx Class C cement plug from 4021 ft ? 3881 ft covering the top of the Abo inside/outside the 4-1/2 inch casing.
6. Perforate at 1970 ft. Attempt to establish circulation between the 4-1/2 inch and 8-5/8 inch casing. Pump a 50 sx Class C cement plug from 1970 ft ? 1850 ft covering the top of the Glorieta

GC 2/21/19
Accepted for record - NMOCD

6419 (Top perf 6425).

5041 - 4891

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #453786 verified by the BLM Well Information System
For EOG Y RESOURCES INC, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 02/11/2019 (19PP1015SE)

Name (Printed/Typed) TINA HUERTA

Title REGULATORY SPECIALIST

Signature (Electronic Submission)

Date 02/07/2019

ENTERED
by 2-22-19

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #453786 that would not fit on the form

32. Additional remarks, continued

inside/outside the 4-1/2 inch casing.

7. Perforate at 1100 ft. Attempt to establish circulation between the 4-1/2 inch and 8-5/8 inch casing. Spot a 50 sx Class C cement plug from 1100 ft ? 990 ft covering the 8-5/8 inch casing shoe. WOC. Tag TOC.

8. Perforate at 670 ft. Attempt to establish circulation between the 4-1/2 inch and 8-5/8 inch casing. Pump a 30 sx Class C cement plug from 670 ft ? 570 ft inside/outside the 4-1/2 inch casing covering the San Andres.

9. Perforate at 370 ft. Attempt to establish circulation between the 4-1/2 inch and 8-5/8 inch casing. Pump a 100 sx Class C cement plug from 370 ft up to surface inside/outside the 4-1/2 inch casing covering the 13-3/8 inch casing shoe and the surface plug.

10. Back fill with quikcrete as necessary.

11. Cut off wellhead and install dry hole marker. Clean location as per regulated.

Wellbore schematics attached

WELL NAME: Federal CX Com #2 FIELD: _____
 LOCATION: 1980' FSL & 660' FWL Sec.7 - 18S-25E
 GL: 3646' ZERO: _____ KB: _____
 COMMENTS: API No.: 30-015-22128


Before

Casing Program

Surface	13-3/8" 61# @ 320'
Intermediate	8-5/8" 24# @ 1050'
Production	4-1/2" 11.6# & 10.5# @ 7185'

Formations

Tops	Depths (ft)
San Andres	620 ✓
Glorieta	1910 ✓
Abo	3951 ✓
Wolfcamp	5091 ✓
Penn	6419 ✓
Canyon	7249 ✓
Strawn	7755 ✓
Atoka	8040 ✓
Morrow	8235 ✓
Chester	8385 ✓



Perfs 5095 - 5101

Omitted Perfs 6425 - 6434
 6454 - 6456

TD: 8417'
 PBTD: 6885'

Not to Scale
 2/6/2019
 SAA

WELL NAME: Federal CX Com #2 FIELD: _____
 LOCATION: 1980' FSL & 660' FWL Sec.7 - 18S- 25E
 GL: 3646' ZERO: _____ KB: _____
 COMMENTS: API No.: 30-015-22128


After

Casing Program

Surface	13-3/8" 61# @ 320'
Intermediate	8-5/8" 24# @ 1050'
Production	4-1/2" 11.6# & 10.5# @ 7185'

Formations

Tops	Depths (ft)
San Andres	620
Glorieta	1910
Abo	3951
Wolfcamp	5091
Penn	6419
Canyon	7249
Strawn	7755
Atoka	8040
Morrow	8235
Chester	8385



TD: 8417'
 PBTD: 6885'

Not to Scale
 2/6/2019
 SAA

BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972

Permanent Abandonment of Federal Wells
Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety (90)** days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. **Notification:** Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. **Blowout Preventers:** A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. **Mud Requirement:** Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. **Cement Requirement:** Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.**

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.