

Form 3160-5 (June 2015)		UNITED STATES PARTMENT OF THE IN JREAU OF LAND MANAG	ITERIOR			FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2						7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Coll Well Gas Well Other						8. Well Name and No. S CULEBRA BLUFF 1	
2. Name of Operator Contact: NICK GLANN						9. API Well No.	
CHEVRON USA INCORPORATED E-Mail: nglann@chevron.com						30-015-26347-00-S1	
3a. Address 6301 DEAU\ MIDLAND, T	3b. Phone No (includ Oras CRVATION Ph: doi 15015000 ARTESIA DISTRICT			10. Field and Pool or Exploratory Area E LOVING			
4. Location of We	FEB 1 4 2019		11. County or Parish, State				
Sec 14 T23S R28E NENE			EDDY COUNTY, NM				
RECEIVED						<u> </u>	
12.	CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE (OF NOTICE	, REPORT, OR OTHI	ER DATA
TYPE OF SU	TYPE OF SUBMISSION TYPE OF ACTION						
Notice of In	ntent	🗖 Acidize	🗖 Deej	oen	Produc	tion (Start/Resume)	Uwater Shut-Off
_		Alter Casing	🗖 Hyd	raulic Fracturing	🗖 Reclam	nation	Well Integrity
Subsequent	Report	Casing Repair	🗖 New	Construction	🗖 Recom	plete	Other
🗖 Final Aban	donment Notice	Change Plans		and Abandon	_	rarily Abandon	
		Convert to Injection	Plug Back Water I ent details, including estimated starting date of any			-	
If the proposal i Attach the Bond following comp testing has been	is to deepen direction d under which the wo detion of the involved	ally or recomplete horizontally, rk will be performed or provide operations. If the operation resonant of the performance of th	give subsurface the Bond No. or sults in a multipl	locations and meas file with BLM/Bl e completion or re	A. Required su completion in a ading reclamation	ertical depths of all pertinen absequent reports must be finew interval, a Form 3160 on, have been completed an	nt markers and zones. iled within 30 days -4 must be filed once d the operator has
Provide 24 hour notice to BLM prior to MIRU, in accordance with				e COA		Q C 2/21/19 Accepted for record NMOCD	
1. MIRU, test tubing t/ 1000 psi for 5 minutes, pull rods, N/U BOP, pull tubing 2. Set CIBP @ 5900', spot 25 sx CL C cmt f/ 5900' t/ 5673' (BC Perfs), WOC, & tag 3. Set CIBP @ 4700', circulate 9.5 ppg MLF, pressure test casing t/ 1000 psi for 10 minutes, spot 24 sx CL C cmt f/ 4700' t/ 4473' (Pardue Perfs), WOC & tag if pressure test failed 4. Spot 25 sx CL C cmt f/ 3561' t/ 3334' (DV Tool) 49 c 5. Spot 45 sx CL C cmt f/ 2665' t/ 2295' (Delaware, B. Salt) 6. Spot 70 sx CL C cmt f/ 612' t/ surface (Shoe, T. Salt, Fresh Water) 7. Verify cement to surface and turn over to surface group for site reclamation 5. Spot 45 sx CL C cmt f/ 612' t/ surface (Shoe, T. Salt, Fresh Water) 7. Verify cement to surface and turn over to surface group for site reclamation 5. Spot 45 sx CL C cmt f/ 612' t/ surface (Shoe, T. Salt, Fresh Water) 7. Verify cement to surface and turn over to surface group for site reclamation 5. Spot 45 sx CL C cmt f/ 612' t/ surface (Shoe, T. Salt, Fresh Water) 7. Verify cement to surface and turn over to surface group for site reclamation 5. Spot 45 sx CL C cmt f/ 612' t/ surface (Shoe, T. Salt, Fresh Water) 7. Verify cement to surface and turn over to surface group for site reclamation 5. Spot 45 sx CL C cmt f/ 612' t/ surface (Shoe, T. Salt, Fresh Water) 7. Verify cement to surface and turn over to surface group for site reclamation 5. Spot 45 sx CL C cmt f/ 612' t/ surface (Shoe, T. Salt, Fresh Water) 7. Verify cement to surface and turn over to surface group for site reclamation 5. Spot 6. Spot 6. Spot 7. Salt for the surface for the surf							
						COMPLIANS	OF APPROVAL
							TEREN
14. I hereby certif Name (Printed/		#Electronic Submission For CHEVRON L itted to AFMSS for process	ISA INCORPO	RATED, sent to RAH MCKINNEY	o the Carlsbac on 02/12/201	d 0	2-22-19
Signature (Electronic Submission) Date 02/11/2019 THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
							2-13-19
_Approved By	°	Title 🛫	SAET	· · · · · · · · · · · · · · · · · · ·	Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.							
Title 18 U.S.C. Secti States ony false, fit	ion 1001 and Title 43 ctitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any pe to any matter w	rson knowingly ar ithin its jurisdiction	nd willfully to n n.	nake to any department or a	gency of the United
(Instructions on page	^{e 2)} ** BLM REV	ISED ** BLM REVISE	D ** BLM RE	EVISED ** BL	M REVISE	D ** BLM REVISED) **





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

. . .

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.