

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.

30-005-63507

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

VO-6241

7. Lease Name or Unit Agreement Name:

Ethan BAW State

8. Well No.

9. Pool name or Wildcat

Undes. Comanche Springs Pre-Permian

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 South 4th Street, Artesia, NM 88210

4. Well Location

Unit Letter J : 660 feet from the North line and 1980 feet from the East line

Section 4 Township 11S Range 27E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

3695' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Completion operation ☒

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/7/03 - Run GR/CCL/CBL TOC 3870'. Perforate Silurian 6300'-6304' (16).

7/8/03 - Acidize Silurian with 400g 20% IC acid.

7/9/03 - Set CIBP at 6280' with 35' cement. Perforate Wolfcamp 5728'-5738' (40). Set ASI packer 2.25" on/off tool at 5680'.

7/10/03 - Acidize Wolfcamp with 1000g 15% IC acid and 60 balls.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sina Huerta TITLE Regulatory Compliance Supervisor DATE July 17, 2003

Type or print name Sina Huerta

Telephone No. 505-748-1471

(This space for State use)

APPROVED BY Jim W. Green TITLE District Supervisor DATE JUL 18 2003

Conditions of approval, if any: