Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 201

SUNDRY NOTICES AND REPORTS ON WELLS A

Do not use thi	s form for proposals to d ll. Use form 3160-3 (APD)	rill or to re-e	nter all OIL	ESADIST	60 Windian! Allottee or	Tribe Name	
	TRIPLICATE - Other instru		17		If Unit or CA/Agree		
Type of Well ☐ Gas Well ☐ Oth		<u> </u>		RECEIVE	3. Well Name and No. Multiple—See Attac	thed	
Name of Operator OXY USA INCORPORATED		ARAH CHAP APMAN@OXY			9. API Well No. MultipleSee Att	ached	
3a. Address 5 GREENWAY PLAZA SUITE HOUSTON, TX 77046-0521		3b. Phone No. (Ph: 713-350	include area code) 4997		10. Field and Pool or E PURPLE SAGE-	xploratory Area WOLFCAMP (GAS)	
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)	 			11. County or Parish, S	tate	
Multiple-See Attached					EDDY COUNTY	, NM	
12. CHECK THE AF	PPROPRIATE BOX(ES) T	O INDICAT	E NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION			TYPE OF	F ACTION			
Notice of Intent	☐ Acidize	☐ Deepe	en .	☐ Product	ion (Start/Resume)	■ Water Shut-Off	
_	☐ Acidize ☐ Alter Casing ☐ Casing Repair		ulic Fracturing	□ Reclam	ation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	□ New (Construction	☐ Recomp	olete	Other Change to Original A	
☐ Final Abandonment Notice	_ •		nd Abandon		arily Abandon	PD PD	
	<u> </u>	Plug I			Disposal		
following completion of the involved testing has been completed. Final Al determined that the site is ready for f Oxy respectfully requests app This is a bulk sundry request cementing program. The wells	pandonment Notices must be filed inal inspection. roval for the following chan for 3 wells in Sand Dunes to	only after all reges from the omodify the l	quirements, includ approved perm 3OP system, c	ling reclamatio	new interval, a Form 316t n, have been completed a	nd the operator has	
Sunrise MDP1 8-5 Fed Com 1 Sunrise MDP1 8-5 Fed Com 1 Sunrise MDP1 8-5 Fed Com 1	174H (30-015-45112) 175H (30-015-45152)			COM	EE ATTACHE DITIONS OF /	PPROVAL	
Please see attached updated	Drill Plan and connection s	pecs for your	review.	Acce	epted For Re	ecord 19	
14. I hereby certify that the foregoing is	Electronic Submission #45	INCORPORAT	EĎ, sent to the	II Information Carlsbad	n System	2.1	
Name (Printed/Typed) DAVID ST	rewart .		Title REGUL	ATORY AD	VISOR		
Signature (Electronic S	Submission)		Date 01/16/2	019			
	THIS SPACE FOI	R FEDERAL	OR STATE	OFFICE U	SE		
Approved By MUSTAFA HAQUE			TitlePETROLE	UM ENGIN	EER	Date 01/23/2019	
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to condu	d. Approval of this notice does nuitable title to those rights in the s	not warrant or subject lease	Office Carlsba	d		-	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a createments or representations as to	rime for any person	son knowingly and	willfully to m	ake to any department or	agency of the United	

Additional data for EC transaction #450787 that would not fit on the form

Wells/Facilities, continued

ر

Agreement NMNM89172	Lease	Well/Fac Name, Number API Number	Location
	NMNM89172	SUNRISE MDP1 8-5 FEDERAL COM - 07/49-415112-00-X1	Sec 17 T24S R31E NWNE 592FNL 1369FEL 32.222969 N Lat, 103.795731 W Lon
NMNM89172	NMNM89172	SUNRISE MDP1 8-5 FEDERAL COM/-07/59-45152-00-X1	Sec 17 T24S R31E NWNE 592FNL 1334FEL 32.222969 N Lat, 103.795616 W Lon
NMNM89172	NMNM89172	SUNRISE MDP1 8-5 FEDERAL CO38-07/69-45153-00-X1	Sec 17 T24S R31E NENE 592FNL 1299FEL 32.222969 N Lat. 103.795502 W Lon

Oxy USA Inc. – Sunrise MDP1 8/5 Federal Com 174H-176H Bulk Sundry

Oxy requests the following changes to the BOP system, intermediate tail cement excess and production casing connection type. The wells related to this bulk sundry request are:

API#	Well Name	Lease Serial #
30-015-45112	Sunrise MDP1 8-5 Fed Com 174H	NMNM089172
30-015-45152	Sunrise MDP1 8-5 Fed Com 175H	NMNM089172
30-015-45153	Sunrise MDP1 8-5 Fed Com 176H	NMNM089172

1. Casing Program

Oxy requests the option to run DQX or SF-Torque connections for the 5.5" 20# P-110 production casing. The SF-Torque connection spec sheet is included.

2. Cementing Program

Casing String	# Sks	Wt.	Yld (ft3/sack)	H20 (gal/sk)	500# Comp. Strength (hours)	Slurry Description
Surface (Lead)	N/A	N/A	N/A	N/A	N/A	N/A
Surface (Tail)	617	14.8	1.33	6.365	5:26	Class C Cement, Accelerator
Intermediate 1st Stage (Lead)	576	10.2	2.58	11.568	6:59	Pozzolan Cement, Retarder
Intermediate 1st Stage (Tail)	154	13.2	1.61	7.804	7:11	Class H Cement, Retarder, Dispersant, Salt
DV/ECP Tool @ 4444 (We re	quest the opt	tion to cancel	the second stag	ge if cement is	circulated to	surface during the first stage of cement
Intermediate 2nd Stage (Lead)	N/A	N/A	N/A	N/A	N/A	N/A
Intermediate 2nd Stage (Tail)	628	13.6	1.67	8.765	7:32	Class C Cement, Accelerator, Retarder
Production (Lead)	N/A	N/A	N/A	N/A	N/A	N/A
Production (Tail)	827	13.2	1.38	6.686	3:39	Class H Cement, Retarder, Dispersant, Salt

Casing String	Top (ft)	Bottom (ft)	% Excess
Surface (Lead)	N/A	N/A	N/A
Surface (Tail)	0	753	100%
Intermediate 1st Stage (Lead)	4344	10100	20%
Intermediate 1st Stage (Tail)	10100	11100	10%
Intermediate 2nd Stage (Lead)	N/A	N/A	N/A
Intermediate 2nd Stage (Tail)	0	4444	10%
Production (Lead)	N/A	N/A	N/A
Production (Tail)	10600	21871	20%

Oxy USA Inc. – Sunrise MDP1 8/5 Federal Com 174H-176H Bulk Sundry

3. Pressure Control Equipment

BOP installed and tested before drilling which hole?	Size?	Min. Required WP	Туре	~	Tested to:
9.875" Hole		5M	Annular	*	70% of working pressure
	12.5/02		Blind Ram	✓	
	13-5/8"	******	Pipe Ram		350/5000:
		5M.	Double Ram	1	250/5000psi
			Other*	T	

Attachments

_x__ Premium Connection Specs

PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

OPERATOR'S NAME: OXY USA Incorporated

LEASE NO.: | NMNM089172

WELL NAME & NO.: | Sunrise MDP1 8-5 Fed Com 174H

SURFACE HOLE FOOTAGE: 592'/N & 1369'/E BOTTOM HOLE FOOTAGE 180'/N & 2200'/E

LOCATION: | Section 17, T.24 S., R.31 E., NMPM

COUNTY: Eddy County, New Mexico

All previous COAs still apply, except for the following:

A. PRESSURE CONTROL

1. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 5000 (5M) psi.

MHH 01232019

GENERAL REQUIREMENTS

The BLM is to be notified in advance for a representative to witness:

- a. Spudding well (minimum of 24 hours)
- b. Setting and/or Cementing of all casing strings (minimum of 4 hours)
- c. BOPE tests (minimum of 4 hours)
 - Chaves and Roosevelt Counties
 Call the Roswell Field Office, 2909 West Second St., Roswell NM 88201.
 During office hours call (575) 627-0272.
 After office hours call (575)
 - Eddy County
 Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822
 - ✓ Lea CountyCall the Hobbs Field Station, 414 West Taylor, Hobbs NM 88240, (575)393-3612

A. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. If a variance is approved for a flexible hose to be installed from the BOP to the choke manifold, the following requirements apply: Check condition of flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends and is to be anchored according to Manufacturer's requirements. The flexible hose can be exchanged with a hose of equal size and equal or greater pressure rating. Anchor requirements, specification sheet and hydrostatic pressure test certification matching the hose in service, to be onsite for review. These documents shall be posted in the company man's trailer and on the rig floor.
- 3. 5M or higher system requires an HCR valve, remote kill line and annular to match. The remote kill line is to be installed prior to testing the system and tested to stack pressure.
- 4. If the operator has proposed a multi-bowl wellhead assembly in the APD. The following requirements must be met:

- a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
- b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
- c. Manufacturer representative shall install the test plug for the initial BOP test.
- d. Whenever any seal subject to test pressure is broken, all the tests in OOGO2.III.A.2.i must be followed.
- e. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.
- 5. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
 - a. In a water basin, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. The casing cut-off and BOP installation can be initiated four hours after installing the slips, which will be approximately six hours after bumping the plug. For those casing strings not using slips, the minimum wait time before cut-off is eight hours after bumping the plug. BOP/BOPE testing can begin after cut-off or once cement reaches 500 psi compressive strength (including lead when specified), whichever is greater. However, if the float does not hold, cut-off cannot be initiated until cement reaches 500 psi compressive strength (including lead when specified).
 - b. In potash areas, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. For all casing strings, casing cut-off and BOP installation can be initiated at twelve hours after bumping the plug. However, **no tests** shall commence until the cement has had a minimum of 24 hours setup time.
 - c. The tests shall be done by an independent service company utilizing a test plug not a cup or J-packer. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (8 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).
 - d. The test shall be run on a 5000 psi chart for a 2-3M BOP/BOP, on a 10000 psi chart for a 5M BOP/BOPE and on a 15000 psi chart for a 10M BOP/BOPE. If a linear chart is used, it shall be a one hour chart. A circular chart shall

- have a maximum 2 hour clock. If a twelve hour or twenty-four hour chart is used, tester shall make a notation that it is run with a two hour clock.
- e. The results of the test shall be reported to the appropriate BLM office.
- f. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- g. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug. This test shall be performed prior to the test at full stack pressure.
- h. BOP/BOPE must be tested by an independent service company within 500 feet of the top of the Wolfcamp formation if the time between the setting of the intermediate casing and reaching this depth exceeds 20 days. This test does not exclude the test prior to drilling out the casing shoe as per Onshore Order No. 2.