	2015) UNITED STATES DEPARTMENT OF THE INTERIOR OCD Arte			FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			 Lease Serial No. NMLC029338A If Indian, Allottee of 			
SUBMIT IN TRIPLICATE - Other instructions on page 2						7. If Unit or CA/Agree
 Type of Well ☑ Oil Well ☑ Other 						8. Well Name and No. GB_JACKSON SA
2. Name of Operator Contact: LESLIE GARVIS BURNETT OIL COMPANY INC E-Mail: LGARVIS@BURNETTOIL.COM				9. API Well No.	9. API Well No. 30-015-04152-00-S1	
3a. Address 3b. Phone No 801 CHERRY STREET UNIT 9 SUITE 1500 Ph: 817-58 FORT WORTH, TX 76102-6881 Fx: 817-33			rea code)	10. Field and Pool or Exploratory Area GRAYBURG		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 14 T17S R30E SWSE 330FSL 2310FEL				11. County or Parish, State EDDY COUNTY, NM		
Sec 14 TTYS NOLE SWSE SOUTHE STOPEL						
12. CHECK THE AP	PROPRIATE BOX(ES)	O INDICATE NAT	URE OF NOTI	CE, REPORT, OR OŤH	IER DATA	
TYPE OF SUBMISSION		Т 	YPE OF ACTIO	N		
□ Notice of Intent			—	duction (Start/Resume)	U Water Shut-Off	
Subsequent Report	Alter Casing Casing Repair	Hydraulic Fra New Construct	ē —	lamation	Well Integrity Other	
☐ Final Abandonment Notice	Change Plans	Plug and Aba	—	nporarily Abandon		
	Convert to Injection	Plug Back		ter Disposal		
1/10/19 - NU FLANGE & BOP. THEN SET 5" CIBP. <u>SET CIBP</u> 1/11/19 - RIH W/ PERF SUB, T T <u>OC @ 2412</u> ', REVERSE CIRC 1/15/18 - CHECK W <u>ELL FOR</u> PASSED 1026' W/ WL. POOH A.M., QK'D TO PERF 50FT HIG	2 <u>@ 2712</u> '. [<u>AG 5" CIBP @ 2712'.</u> CI C. PRESSURE, 0 PSI. TAG W/ 29 STANDS. PERF @	RC WELL W/ SALT (GEL <u>BRINE &</u> M	UD <u>CAP BP</u> W/ 25SXS <u>RU WL</u> , COULD NOT G <u>HASE MESSER W/ B</u> L		
		G C 4	/5/19 record · NMO	DHE	7-22-191 DECEMED	
14. I hereby certify that the foregoing is t Com Name (Printed/Typed) LESLIE GA	Electronic Submission #4 For BURNETT (mitted to AFMSS for proce	DIL COMPANY INC, se ssing by PRISCILLA P	ent to the Carlsh:	ad 019 (19PP1324SE)	APR 0 1 2019	
Signature (Electronic Su	ubmission)	Date	03/08/2019	DIST	RICT II-ARTESIA O.C.	
	THIS SPACE FO	R FEDERAL OR S	TATE OFFICE	ACCEPTED FO	K KECOKD	
Approved By		Title		MAR 1.4	2019Date	
Conditions of approval, if any, are attached, certify that the applicant holds legal or equi which would entitle the applicant to conduc	table title to those rights in the	ot warrant or subject lease Office		BUREAU OF LAND	LIE	
Title 18 U.S.C. Section 1001 and Title 43 U. States any false, fictitious or fraudulent st	J.S.C. Section 1212, make it a c atements or representations as t	rime for any person know o any matter within its jur	ingly and willfully isdiction.	make to OARESBADIFIE	DOFFIC The United	
(Instructions on page 2) ** BLM REVIS	SED ** BLM REVISED	** BLM REVISED	** BLM REVIS	SED ** BLM REVISE	D **	

ц,

Additional data for EC transaction #457474 that would not fit on the form

32. Additional remarks, continued

1/16/19 - <u>SET PKR, RIH, PERE @ 2195</u>', PRESSURED UP. <u>BLM OK'D TO SPOT 30</u> SXS @ 2295'. WOC, TAG @ 2118'. RIH W/ 7" PKR, PERF @ 1364', PRESSURED UP. <u>BLM OK'D TO SPOT 35 SXS @ 143</u>2'. WOC.

1/17/19 - TAG TO 1257' PERF @ 603', SET PKR @ 130', SQZ 60 SXS, TOC @ 400'. WOC. TAG @ 336', PERF @ 225', SQZ 35 SXS. TOC @ 74', WOC.

1/18/19 - TAG @ 336'. RIH W/ 7" PKR. BLM OK'D TO RESQUEEZE ANOTHER 45 SXS, DISP TO 100'. TAG 336'. BLM OK'D TO REAQUEEZE ANOTHER 45 SXS, DISP TO 100'. WOC.

1/21/19 - TAG TOC @ 225'. SET PKR @ 30', GET RATE 1 1/2 BPM @ 0 PSI W/ NO CIRC. CONTACT CHASE <u>MESSER W/ BLM @ 9:22 A.</u>M. SOZ 45 SXS CMT W/ 2% CACL, DISP TOC TO 100'. TAG @ 150'. PERF @ 150', ATTEMPT PMP RATE, <u>PRESSURED UP TO 500 PSI</u>, HELD. CONTACT JEREMY PORTTER W/ BLM @ 4:53 P.M. ADVISE TO PERF @ 100', GET RATE 1 1/2 <u>BPM</u> @ 300 P<u>SI W/</u>NO CIRC UP 8 5/8. CONTACT JEREMY PORTTER @ 5:30 PM., OK TO FILL TO SURFACE IN THE A.M.

1/22/19 PULL PKR, ND BOP. RIH W/ 5 JTS TO 150', PMP 355XS CMT TO SURFACE. POOH, CMT FALLING. TOP OFF WELL, STILL FALLING. CONTACT CHASE MESSER W/ BLM @ 11:00 A.M. WOC TAG. TAG @ 102'. PMP 20 SXS CMT TO SURFACE W/ 2% CACL. TXT RESULTS TO CHASE MESSER OF TAG & SURFACE PLUG @ NOON.

1/23/19 - WELL P & A. WELDER CUT & CAPPED CSG 4' BELOW SURFACE. INSTALLED PLATE W/ LEGALS ON IT. 1/24/19 CONTACTED CHASE MESSER W/ BLM & SENT PICTURES @ 6:30 A.M. BLM OK'D. COVERED PLATE, PULLED UP ANCHORS & BACK DRAGGED LCTN. Install below ground market as per BLM/OCD Requirements.

*

1

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1 The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3 The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7 At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos

Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612