

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88203

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87401

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico

Energy, Minerals and Natural Resources

CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-103

Revised July 18, 2013

WELL API NO.

30-015-39118

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

EO 7811

7. Lease Name or Unit Agreement Name

Smokey Bits State Com

8. Well Number

3H

9. OGRID Number

192463

10. Pool name or Wildcat

Benson Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

OXY USA WTP LP

3. Address of Operator

P.O. Box 50250, Midland, TX 79710

4. Well Location

Unit Letter L : 1750 feet from the South line and 330 feet from the West line

Section 36 Township 18S Range 30E NMPM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3521 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

DOWNHOLE COMMINGLE ☐

CLOSED-LOOP SYSTEM ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☐

CASING/CEMENT JOB ☐

OTHER: Recompletion ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

RU PU 8/31/2016. POOH w/ rods, rod pump and tbq, and RIH w/ scraper and cleanout to 9226'. RIH w/ tbq, composite BP, set @ 9223' and pressure test to 1000#, which held. RUWL and perf @ 9211-9015, 8951-8755, 8691-8495', Total 72 holes. Frac in 3 stages w/ Weatherford Trufac plugs set @ 8983' and 8722' w/ 6000 gal 7.5% HCL + 1194140 gals SW + 1017729# sand. RIH and drill out Weatherford Trufac plugs @ 8722' and 8875' and clean out to 9224'. RIH w/ tbq and set tbq anchor @ 7777'. RIH w/ 1" x 25' rod and 7/8" x 25' rod pump, rod pump, and polished rod, swab well, pressure test tbq to 500 psi, good test. RD 10/10/16.

3/21/17 RU PU. POOH w/ rods, rod pump, and tbq, and RIH w/ scraper, clean out and drill out CBP @ 9216'. Continue cleaning out wellbore to PBD @ 12547'. RIH w/ tbq and set TAC @ 7783'. NU wellhead then RIH w/ 1" x 25' rods, 7/8" x 25' rod, rod pump, and polished rod. Pressure test tbq to 500 psi, good test. RD 3/27/18.

Spud Date: 8/31/2016

3/21/17

Rig Release Date: 10/10/2016

3/28/17

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sarah Mitchell TITLE Regulatory Specialist DATE 4/20/18

Type or print name Sarah Mitchell E-mail address: sarah_mitchell@oxy.com PHONE: 432-699-4318

For State Use Only

APPROVED BY: [Signature] TITLE Staff mg DATE 5-2-18

Conditions of Approval (if any):