

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTRECEIVED  
OCD ArtesiaFORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

JUN 25 2019

SUBMIT IN TRIPLICATE - Other instructions on page 1

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well Name and No. GISSLER B 14
2. Name of Operator EOG Y RESOURCES INC		9. API Well No. 30-015-22004-00-S1
3a. Address 104 S 4TH STREET ARTESIA, NM 88210		10. Field and Pool or Exploratory Area SQUARE LAKE
3b. Phone No. (include area code) Ph: 575-748-4311		11. County or Parish, State EDDY COUNTY, NM
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 12 T17S R30E NENW 660FNL 1980FWL		

## 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

1. JSA
2. MIRU WOR
3. NU Rod BOP
4. TOOH w/Rod String and pump
5. ND Tree/NU BOPs
6. POOH with tubing
7. Run Casing scraper, gauge ring with junk basket to top perf

Plug from Btm to Top:

Set CIBP at 2844 ft with 35 ft of CLS C on top. or spot 25 sx.

Perforate at 673 ft. Attempt to establish circulation. Spot a 25 sx (562 ft) CLS C cement plug 211

- Surf. Note. CSF repair. Perforated @ 600 SQZ cement surface..

GC 6/26/19  
Accepted for record - NMOCDAdd Plug, Perf @ 1350, SQZ  
cut to 1250. 1000 Ton (13.5M)SEE ATTACHED FOR  
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct.	
Electronic Submission #466218 verified by the BLM Well Information System For EOG Y RESOURCES INC, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 05/21/2019 (19PP2198SE)	
Name (Printed/Typed) JEREMY HAASS	Title REGULATORY SPECIALIST
Signature (Electronic Submission)	Date 05/21/2019

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By <u>James C. Amos</u>	Title <u>SAET</u>	Date <u>5-26-19</u>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office <u>CFD</u>	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

**Additional data for EC transaction #466218 that would not fit on the form**

**32. Additional remarks, continued**

~~ft -573 ft. WOC & Tag Plug. This will plug the 8-625 inch casing shoe and Saldado.  
Spot a 10 sx (145 ft) CLS Cement plug 0 ft - 145 ft. WOC & Tag Plug. This will plug the Top.~~

8. RDMO Workover Rig

9. PXA Marker

10. Cut off wellhead and weld on dry hole marker. Clean location as per regulation.

Below ground level dry hole marker  
required

# Gissler B #14

Sec-TWN-RNG: 12-17S-30E  
FOOTAGES: 660 FNL 1980 FWL

API: 30-015-22004  
GL: 3740

## COMMENTS

### Plug #3

8 5/8" 24# LT&C J55 22' to surf.

80054  
Remdial cement work 326' to surf

Circ  
2nd SQZ  
450 SX

### Plug #2

2nd stage  
200 SX  
100 SX

DV tool @ 2858'

100 SX  
1st stage

### Plug #1

Perforations 2894-2901

2906-11

2940-52

3044-78

3193-3210

PBTD: 3,223 MD  
TD: 3,240 MD

## CASING DETAIL

#	HOLE SIZE	SIZE	WGHT	GRADE	Top	Bottom	Sx Cmt	Circ/TOC	TOC Method
A	12 1/4	8 5/8	24		0	523	250	Circ	
B	7 7/8	4 1/2	10.5		0	3,235	500		

## FORMATION TOPS

	FORMATION	TOP							
	Salado	600							
	Grayburg	2894							
	San Adres	3193							

## TUBING DETAIL

#									
---	--	--	--	--	--	--	--	--	--

## ROD DETAIL

#									
---	--	--	--	--	--	--	--	--	--

## Plugs

#	SX	CMT Class	Top	BTM	Description
1	25	Class C	2859	2844	Set CIBP at 2844 ft with 35 ft of CLS C on top.
2	25	Class C	211	573	Perforate at 573 ft. Attempt to establish Circulation. Spot a 25 SX (362 ft) CLS C cement plug 211 ft - 573 ft. WOC & Tag Plug. This will plug the 8.625 inch casing shoe and Saldado.
3	25	Class C	0	145	Spot a 10 SX (145 ft) CLS C cement plug 0 ft - 145 ft. WOC & Tag Plug. This will plug the Top.
4					
5					
6					

Prepared by: MJM

Date: 20-May-2019

Tan: 1 1270 GB 2780  
Yates 1470 SA 3079  
Qu 2370

**BUREAU OF LAND MANAGEMENT  
Carlsbad Field Office  
620 East Greene Street  
Carlsbad, New Mexico 88220  
575-234-5972**

**Permanent Abandonment of Federal Wells  
Conditions of Approval (LPC Habitat)**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety (90)** days from the approval date of this Notice of Intent to Abandon.

**If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.**

**The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.**

2. **Notification:** Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. **Blowout Preventers:** A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. **Mud Requirement:** Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. **Cement Requirement:** Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.** Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

**Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:**

From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted