Form 3160 5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Operator

FORM APPROVED OMB NO 1004-0137 Expires January 31, 2018

OMB NO 1004-013 Expires January 31, 20 Lease Serial No NMLC028731B


SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an


6 If Indian Allaman an Tuba Nama

abandoned we	6 If Indian, Allottee of	6 If Indian, Allottee or Tribe Name			
· SUBMIT IN		7 If Unit or CA/Agreement, Name and/or No NMNM111789X			
1 Type of Well		8 Well Name and No DODD FEDERAL UNIT 31			
2 Name of Operator COG OPERATING LLC	9 API Well No 30-015-02976-(
COG OPERATING LLC E-Mail abbym@bcmandassociates com 3a Address 3b Phone No (included)			 	10 Field and Pool or Exploratory Area	
600 W ILLINOIS AVENUE MIDLAND, TX 79701		432-580-7161	GRAYBURG		
4 Location of Well (Footage Sec T R M or Survey Description)			11 County or Parish,	11 County or Parish, State	
Sec 14 T17S R29E SENE 198	EDDY COUNT	Y NM			
12 CHECK THE AI	PPROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION TYPE OF ACTION					
Notice of Intent	☐ Acıdıze	□ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	□ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily Abandon		
	Convert to Injection	☐ Plug Back	☐ Water Disposal		
determined that the site is ready for final inspection 1 Set 4 1/2" CIBP @ 2750' Circulate hole w/ MLF Pressure test csg Spot 25 sx cmt @ 2750-2400' 2 Spot 25 sx cmt @ 2334-2000' WOC & Tag (7" Shoe) 3 Spot 25 sx cmt @ 1100-990' WOC & Tag (B/Salt) 4 Spot 40 sx cmt @ 521-Surface Perf Deep fraction shots 5 Cut off well head verify cement to surface, weld on Below Ground Dry Hole Marker RECEVED JUL 3 1 2019 CONDITION 2 OF					
JUL 3 1 2019 CONDITIONS OF APPROVAL					
	DISTRICTILARTESIAO.C.I).		- VIII.	
	Electronic Submission #4712	ATING LLC, sent to the Ca	nlsbad n 07/01/2019 (19PP2642SE)		
Signature (Electronic		Date 06/28/20			
	THIS SPACE FOR F	EDERAL OR STATE (OFFICE USE	A	
Approved By Approved By	a. amos	Title SP4		7-21-19 Date	
Conditions of approval if any are attache certify that the applicant holds legal or eq which would entitle the applicant to condi	untable title to those rights in the subjuct operations thereon	ect lease Office (FE			
Title 8 U S C Section 1001 and Title 43 States any false fictitious or fraudulent	USC Section 1212, make it a crumo statements or representations as to an	e for any person knowingly and	willfully to make to any department of	r agency of the United	

COG Operating, LLC



COG Operating, LLC



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163 1

1 Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged Failure to do so will result in enforcement action

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer Failure to do so may result in enforcement action

- 2 Notification Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations For wells in Chaves and Roosevelt County, call 575-627-0272, Eddy County, call 575-361-2822, Lea County, call 575-393-3612
- 3 <u>Blowout Preventers</u> A blowout preventer (BOP) as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9 090 feet a 3M system for a well not deeper than 13,636 feet, and a 5M system for a well not deeper than 22 727 feet.
- 4 <u>Mud Requirement</u> Mud shall be placed between all plugs Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of get per 100 barrels of brime water Minimum nine (9) pounds per gatlon
- 5 Cement Requirement Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

in neu of a cement plug across perforations in a cased hole (not for any other plugs) a priege plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a patient is used to cap this plug 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs

6 <u>Dry Hole Marker</u> All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper) The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker—well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds)

- 7 <u>Subsequent Plugging Reporting</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well <u>Show date well was plugged</u>
- 8 <u>Trash</u> All trash, junk and other waste material shall be contained in trash cages of bins to prevent scattering and will be removed and deposited in an approved sanitary landfill Burial on site is not permitted

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives