Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter abandoned well. Use form 3160-3 (APD) for such proposals.

NMLC028775B	
6. If Indian, Allottee or Tribe Name	

		<u> </u>		0010			
SUBMIT IN TRIPLICATE - Other instructions on page AUG 2 1 2019					7. If Unit or CA/Agreement, Name and/or No. 8910123980		
1. Type of Well ☐ Gas Well ☐ Oth	er .		DISTRICTII-ART	iesiao.c.	8. Well Name and No. RJ UNIT 102		
2. Name of Operator Contact: ABIGAIL ANDERSON COG OPERATING LLC E-Mail: abbym@bcmandassociates.com					9. API Well No. 30-015-03140-00-\$1		
3a. Address 3b. Phone No. 600 W ILLINOIS AVENUE Ph: 432-580 MIDLAND, TX 79701			(include area code) 0-7161		10. Field and Pool or Exploratory Area GRAYBURG		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 27 T17S R29E NWNE Tract 2A 660FNL 1980FEL					EDDY COUNTY, NM		
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICA	ΓΕ NATURE OI	F NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize	☐ Deepen		☐ Production (Start/Resume)		■ Water Shut-Off	
		☐ Hyd	Hydraulic Fracturing		ation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	☐ New Construction ☐ Re		☐ Recomp	olete	Other	
☐ Final Abandonment Notice	☐ Change Plans	-		☐ Tempor	arily Abandon		
			ug Back ☐ Water 1		Disposal		
Deep Penedration 5/2" & 7" Cegs Surf. all annul	ot 25 sx cmt on top. Circul ot 25 sx cmt on top. Press 890. WOC & Tag. 178 urface. on Below Ground Dry Hole complete for received Nine Shots for Lat	late hole w/ M ture test csg. S - 162 Marker. J 9 CD	ILF. to 500 psi. Circui 8 (T/On) Add Alag 2 1060.	tate hote-w/ 2243- ss: 4 Spz 8/sa/f	Aerfo 24 2326. US San Andres ent 5/2 & 7 Cont To 6	•	
14. I hereby certify that the foregoing is Commi	Electronic Submission #4	PERATING L	C, sent to the Ca	ırlsbad	•		
Name(Printed/Typed) ABIGAIL ANDERSON		Title AGENT		· · · · · · · · · · · · · · · · · · ·			
Signature (Electronic S	ubmission) THIS SPACE FO	R FEDERA	Date 04/30/20		SE		
				· · · · · · · ·		1000	
Approved By	- 4ms		Title SHE	7		5-5-19 Date	
conditions of approval, if any, are attached ertify that the applicant holds legal or equ which would emitle the applicant to condu	itable title to those rights in the	not warrant or subject lease	Office <i>LFO</i>				
Fithe 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a catalements or representations as	crime for any pe to any matter wi	son knowingly and thin its jurisdiction.	willfully to ma	ake to any department or a	agency of the United	

COG Operating LLC

Lease & Well

RJ Unit # 102

1937

30-015-03140 Elevation - 3550' KB -8 5/8" 24# @ 1010', cmt w/ 50 sx. March, 1937 7" 20# csg @ 2293', cmt w/100 sx March 1937 2670 Top of cmt @ 2600". (Behind pipe) Completed in Open Hole 2293 - 2850'. GB/SA 3236-42, 46-50, 52-56, 58-63, 71-76, 4 spf Acidized w/500 gal 15% NEFE Fraced w/10,000 gai oii, 18,000 # sd. 32.8169932 -104.0604706

PBTD

5 1/2" 11:6# @ 3288', cmi w/100 sx.

1738


2113

2446

COG Operating LLC

Lease & Well # RJ Unit # 102

1937



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 38220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

1

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

 The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.