Form 3160-5 (April 2004)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

M	Ü	مغر
A 20	ŧΔ	cia

FORM APPROVED OM B No. 1004-0137

	Expires: March 31, 2
5.	Lease Serial No.

NM 70402

SUNDRY NOTICES AND REPORTS ON WELLS

SUBMIT IN TRIPLICATE- Other instructions on reverse side.		
	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well ☐ ☐ ☐ Gas Well ☐ ☐ Other	8. Well Name and No.	
2. Name of Operator Hunt Cimarron L.P.	Anchor Deep Unit #2	
	9. API Well No. 30-005-62632	
3a. Address P.O. Box 1592, Roswell, New Mexico 88202-1592 3b. Phone No. (include area code) 575-623-9799	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	King Camp, North (Devonian)	
1980' FSL & 1980' FEL (Unit J), Section 9, T 14-S, R 29-E, NMPM	11. County or Parish, State Chayes County, New Mexico	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION TYPE OF ACTION		
Notice of Intent ☐ Acidize ☐ Deepen ☐ Production (State of Intent) ✓ Subsequent Report ☐ Casing Repair ☐ New Construction ☐ Recomplete ☐ Change Plans ☐ Plug and Abandon ☐ Temporarily Abandon ☐ Convert to Injection ☐ Plug Back ☐ Water Disposal	Well Integrity Other	
following completion of the involved operations. If the operation results in a multiple completion or recompletion is testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclams determined that the site is ready for final inspection.) 06/12/2019: Notify BLM-Roswell. Move in and RU plugging equipment. 06/14/2019: Unflange wellhead and nipple up BOP. Tally in with tubing to RBP at 3265'. Work so 06/25/2019: Finish tally in with tubing and tag CIBP at 9680'. Circulate hole with 9.5# plug mud. 06/25/2019: Plug 1: Spot 25 sx "H" from 9680-9480. WOC and tag at 9465'. 06/26/2019: Plug 2: Spot 25 sx "H" from 8800-8600'. WOC and tag at 6760'. Plug 4: Spot 25 sx "06/28/2019: Plug 3: Spot 25 sx "C" from 7012-6762. WOC and tag at 6760'. Plug 4: Spot 25 sx "06/28/2019: Plug 5: Unable to establish injection to squeeze. BLM approved balanced plug. Spot 2 07/01/2019: Plug 6: Perf & squeeze 30 sx "C" from 2550-2450 WOC and tag at 2411'. 07/02/2019: Plug 7: Perf & squeeze 25 sx "C" from 950-800. WOC and tag at 745'. Plug 8: Perf 07/09/2019: Cut off wellhead and found top plug 8' below surface. Filled to surface with 5 sx "C". Plugging completed	ation, have been completed, and the operator has everal days to wash over & retrieve RBP. C" from 5880-5630. WOC and tag at 5625'. 5 sx "C" at 5200-4950 WOC & tag at 5005'. and squeeze 85 sx "C" from 356' to surface. RD cementers and install dry hole marker.	
Accepted for record NMOCD Accepted for record - NMOCD Approved as to plug well bore. Liability using retained until surface ration is completed.	inder bond ace resto- NM OIL CONSERVATION OF TRICT	
14./I hereby certify that the foregoing is rue and correct	SEP 0 9 2019	
Name (Printed/Typed) Richard C. Gilliland Title President	RECEIVED	
Simples Richard Cilliand Rigitally signed by Richard Gilliland	The state of the s	
	9/04/2019	
THIS SPACE FOR FEDERAL OR STATE OFFICE	USEH HECOHD	
	• • • • • • • • • • • • • • • • • • •	