Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137

Expires: January	
5. Lease Serial No. NMNM41645	

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

abandoned wel	s form for proposals to I. Use form 3160-3 (AP	D) for such proposals.	6. II Indian, Allot	ttee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2		7. If Unit or CA/A	7. If Unit or CA/Agreement, Name and/or No. SCR330	
Type of Well			8. Well Name and	1 No.
Oil Well 🛭 Gas Well 🗖 Oth	er	•	FEDERAL 13	
 Name of Operator CIMAREX ENERGY COMPAN 	Contact: NY OF C O -Mail: DEYLER@	DAVID A EYLER DMILAGRO-RES.COM	9. API Well No. 30-015-365	71-00-C1
3a. Address 600 N MARIENFELD STE 600 MIDLAND, TX 79701)	3b. Phone No. (include area code Ph: 432-687-3033	10. Field and Poo UNKNOWN	ol or Exploratory Area
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description	i) ·	11. County or Par	rish, State
Sec 13 T25S R26E SENW 13 32.133610 N Lat, 104:248568			EDDY COU	NTY, NM
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR	OTHER DATA
TYPE OF SUBMISSION		ТҮРЕ О	F ACTION	
☐ Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume	e) Water Shut-Off
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity
Subsequent Report ∴	□ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
☐ Final Abandonment Notice	□ Change Plans	□ Plug and Abandon	☐ Temporarily Abandon	•
•	Convert to Injection	☐ Plug Back	■ Water Disposal	
13. Describe Proposed or Completed Ope If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi 07/09/19: SET. 5-1/2" CIBP @	eration: Clearly state all pertine illy or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection.	give subsurface locations and measure the Bond No. on file with BLM/BI/sults in a multiple completion or reciled only after all requirements, included	red and true vertical depths of all p A. Required subsequent reports mu ompletion in a new interval, a Form ling reclamation, have been comple RE(pertinent markers and zones. Ist be filed within 30 days In 3160-4 must be filed once eted and the operator has CLAMATION PROCEDURE
If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab	eration: Clearly state all pertine tilly or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. 10.100'; DUMP BAIL 4 S 9.150'; CIRC. WELL W. @ 6,059'; WOC X TAG X TAG CMT. @ 1.708' X TAG CMT. @ 1.728' S.CMT. @ 1.121-3'. DIC	give subsurface locations and measure the Bond No. on file with BLM/BI/sults in a multiple completion or reduced only after all requirements, included SXS.CMT. @ 10,100. M.L.E.; PUMP 25 SXS.CMT. CMT. @ 5,196; PUMP 25 SX	red and true vertical depths of all p. A. Required subsequent reports mu ompletion in a new interval, a Form ling reclamation, have been completed by the subsequent of the su	pertinent markers and zones. Ist be filed within 30 days in 3160-4 must be filed once eted and the operator has CLAMATION PROCEDURE ATTACHED IP EEL ECLAMATIO
If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit or 107/09/19: SET 5-1/2" CIBP @ 07/11/19: SET 5-1/2" CIBP @ 07/12/19: PUMP 90 SXS CMT 25 SXS CMT. @ 1,966; OWC 07/13/19 MIX X CIRC. 140 SX PLATE TO CSGS. X INSTALL	eration: Clearly state all pertine filly or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fill fill fill fill fill fill fill fil	give subsurface locations and measure the Bond No. on file with BLM/BLM/Sults in a multiple completion or received only after all requirements, included SXS.CMT. @ 10,100'. M.L.E.; PUMP 25 SXS.CMT. CMT. @ 5,196'; PUMP 25 SYS.CMT.	red and true vertical depths of all p. A. Required subsequent reports mu ompletion in a new interval, a Form ling reclamation, have been completed by the subsequent of the su	pertinent markers and zones. Ist be filed within 30 days in 3160-4 must be filed once etcd and the operator has CLAMATION PROCEDURI ATTACHED IP EEL ECLAMATIO
If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit of 1/10/19 SET 5-1/2" CIBP @ 07/11/19: SET 5-1/2" CIBP @ 07/12/19: PUMP 90 SXS CMT 25 SXS CMT @ 1,966; OWC 07/13/19 MIX X CIRC. 140 SX PLATE TO CSGS. X INSTALL	eration: Clearly state all pertine filly or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fill fill fill fill fill fill fill fil	give subsurface locations and measure the Bond No. on file with BLM/BI/sults in a multiple completion or reduced only after all requirements, included SXS.CMT. @ 10,100. M.L.E.; PUMP 25 SXS.CMT. CMT. @ 5,196; PUMP 25 SX	red and true vertical depths of all p. A. Required subsequent reports mu ompletion in a new interval, a Form ling reclamation, have been completed by the subsequent of the su	pertinent markers and zones. Ist be filed within 30 days in 3160-4 must be filed once eted and the operator has CLAMATION PROCEDURE ATTACHED IP EEL
If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit or fit of the fit	eration: Clearly state all pertine filly or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fill nal inspection. 10.100'; DUMP BAIL 4 S 9.150'; CIRC. WELL W/ @ 6,059'; WOC X TAG X TAG CMT. @ 1.708'. (S.CMT. @ 1.121'-3'; DIG. DRY HOLE MARKER. DONED 07/13/19.	give subsurface locations and meast the Bond No. on file with BLM/BI/Sults in a multiple completion or recised only after all requirements, included SXS.CMT. @ 10,100'. M.L.E.; PUMP 25 SXS.CMT. CMT. @ 5,196'; PUMP 25 SXS.CMT. GOUT X.CUT.OFE.WELLHE.	red and true vertical depths of all p. Required subsequent reports mu mpletion in a new interval, a Form ding reclamation, have been completed by the subsequent reports in the subsequent reports me and the subsequent reports in a red in the subsequent red in a form of the subsequent reports and su	pertinent markers and zones. Ist be filed within 30 days in 3160-4 must be filed once etcd and the operator has CLAMATION PROCEDURE ATTACHED IP EEL ECLAMATIO
If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit or 1/10/19; SET 5-1/2" CIBP @ 07/11/19: SET 5-1/2" CIBP @ 07/12/19: PUMP 90 SXS.CMT 25 SXS.CMT. @ 1,966; OWC 07/13/19 MIX X CIRC. 140 SYPLATE TO CSGS. X INSTALL WELL PLUGGED AND ABANI	eration: Clearly state all pertine tilly or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. 10,100'; DUMP BAIL 4 S 9,150'; CIRC. WELL W/ . @ 6,059'; WQC X TAG X TAG CMT. @ 1,708'; X S.CMT. @ 1,121-3'; DIC DRY HOLE MARKER. DONED 07/13/19.	give subsurface locations and measure the Bond No. on file with BLM/BL/Sults in a multiple completion or received only after all requirements, included only after all requirements, inc	red and true vertical depths of all p. Required subsequent reports mu in preval, a Form ting reclamation, have been completed by the complete subsequent reports in a new interval, a Form ting reclamation, have been completed by the complete subsequent for the Carlsbad subsequent reports and re	pertinent markers and zones. Ist be filed within 30 days in 3160-4 must be filed once etcd and the operator has CLAMATION PROCEDURE ATTACHED IP EEL ECLAMATIO
If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit or 1/10/19; SET 5-1/2" CIBP @ 07/11/19: SET 5-1/2" CIBP @ 07/12/19: PUMP 90 SXS.CMT 25 SXS.CMT. @ 1,966; OWC 07/13/19 MIX X CIRC. 140 SYPLATE TO CSGS. X INSTALL WELL PLUGGED AND ABANI	true and correct. Electronic Submission # For CIMAREX ENE	give subsurface locations and measure the Bond No. on file with BLM/BL sults in a multiple completion or recited only after all requirements, included the substance of the subs	red and true vertical depths of all p. Required subsequent reports mu mpletion in a new interval, a Form ling reclamation, have been completed by the subsequent of the RECOMPT. 4,140'-4,000'; PUM AD 3' B.G.L.; WELD ON STERMAN AD 3' B.G.L.; WELD D	pertinent markers and zones. Ist be filed within 30 days in 3160-4 must be filed once eted and the operator has CLAMATION PROCEDURE ATTACHED IP EEL RECLAMATION OUF 1-13-'29'
If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit or 1/10/19; SET 5-1/2" CIBP @ 07/11/19; SET 5-1/2" CIBP @ 07/12/19; PUMP 90 SXS.CMT 25 SXS.CMT. @ 1,966'; OWC 07/13/19 MIX X CIRC. 140 SY PLATE TO CSGS. X INSTALL WELL PLUGGED AND ABANI	eration: Clearly state all pertine tilly or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fil nal inspection. 10.100'; DUMP BAIL 4 S 9.150'; CIRC. WELL W/ . @ 6,059'; WOC X TAG X TAG CMT. @ 1.708'; X S.CMT. @ 1.121-3'; DIG DRY HOLE MARKER. DONED 07/13/19. Compared to true and correct. Electronic Submission # For CIMAREX ENE itted to AFMSS for processitted.	give subsurface locations and measure the Bond No. on file with BLM/BL sults in a multiple completion or recited only after all requirements, included SXS.CMT. @ 10,100'. M.L.E.; PUMP 25 SXS.CMT. CMT. @ 5,196'; PUMP 25 SXS.CMT. GOUT X CUT OFF WELLHE. 474710 verified by the BLM Weller Company of Co., sent sising by DEBORAH MCKINNEY	AUG 2 1 2019	pertinent markers and zones. Ist be filed within 30 days in 3160-4 must be filed once eted and the operator has CLAMATION PROCEDURE ATTACHED IP EEL RECLAMATION OUF 1-13-'20'
If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit or/09/19; SET_5-1/2" CIBP @ 07/11/19: SET_5-1/2" CIBP @ 07/12/19: PUMP 90 SXS.CMT 25 SXS.CMT @ 1,966; OWC 07/13/19 MIX X CIRC. 140 SY PLATE TO CSGS. X INSTALL WELL PLUGGED AND ABANI	eration: Clearly state all pertine tilly or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fill nal inspection. 10.100'; DUMP BAIL 4 S 9.150'; CIRC. WELL W/ . @ 6,059'; WOC X TAG X TAG CMT. @ 1,708'. X TAG CMT. @ 1,721-3'. DIG. DRY HOLE MARKER. DONED 07/13/19. true and correct. Electronic Submission # For CIMAREX ENE of the complete of the c	give subsurface locations and measure the Bond No. on file with BLM/BL sults in a multiple completion or recited only after all requirements, included the substance of the subs	AUG 2 1 2019	pertinent markers and zones. Ist be filed within 30 days in 3160-4 must be filed once eted and the operator has CLAMATION PROCEDURE ATTACHED IP EEL RECLAMATION OUF 1-13-'29'
If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fit or/09/19; SET_5-1/2" CIBP @ 07/11/19: SET_5-1/2" CIBP @ 07/12/19: PUMP 90 SXS.CMT 25 SXS.CMT @ 1,966; OWC 07/13/19 MIX X CIRC. 140 SY PLATE TO CSGS. X INSTALL WELL PLUGGED AND ABANI	eration: Clearly state all pertine tilly or recomplete horizontally, k will be performed or provide operations. If the operation re andonment Notices must be fill nal inspection. 10.100'; DUMP BAIL 4 S 9.150'; CIRC. WELL W/ . @ 6,059'; WOC X TAG X TAG CMT. @ 1,708'. X TAG CMT. @ 1,721-3'. DIG. DRY HOLE MARKER. DONED 07/13/19. true and correct. Electronic Submission # For CIMAREX ENE of the complete of the c	give subsurface locations and meast the Bond No. on file with BLM/BI/Sults in a multiple completion or recited only after all requirements, included SXS.CMT. @ 10,100'. M.L.E.; PUMP 25 SXS.CMT. CMT. @ 5,196'; PUMP 25 SXS.CMT. GOUT X CUT OFF WELLHE. 474710 verified by the BLM Weller Company of Co., sent is sing by DEBORAH MCKINNEY. Title AGENT. Date 07/23/2	AUG 2 1 2019	Dertinent markers and zones. Is the filed within 30 days in 3160-4 must be filed once eted and the operator has CLAMATION PROCEDURE ATTACHED IP EEL RECLAMATION OR RECORD ANALYSIS OF THE PROCEDURE ATTACHED MANAGEVIENT

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **





United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612