Form 3160-5

# UNITED STATES

FORM APPROVED

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			Expir	MB NO. 1004-0137 res: January 31, 2018
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				6. 84A
				ttee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2				Agreement, Name and/or No. 25X
1. Type of Well ☐ Gas Well ☐ Other				ł No. LY UNIT 85
2. Name of Operator Contact: ABIGAIL ANDERSON COG OPERATING LLC E-Mail: abbym@bcmandassociates.com			9. API Well No. 30-015-21663-00-S1	
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701		3b. Phone No. (include area code) Ph: 432-580-7161	10. Field and Poo GRAYBUR	ol or Exploratory Area G
4. Location of Well (Footage, Sec., T		11. County or Parish, State		
Sec 24 T17S R29E NWSW 20		EDDY COU	INTY, NM	
	·		· · · · · · · · · · · · · · · · · · ·	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATURE OF	F NOTICE, REPORT, OR	OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
☑ Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resum	e) Water Shut-Off
	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamation	■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f	ally or recomplete horizontally, it will be performed or provide doperations. If the operation respondent Notices must be file	give subsurface locations and measur the Bond No. on file with BLM/BIA sults in a multiple completion or reco	red and true vertical depths of all Required subsequent reports mumpletion in a new interval, a Form	pertinent markers and zones.  In the filed within 30 days  In 3160-4 must be filed once  In the operator has
1. Set 4 1/2" CIBP @ 2290'. C 2. Perf & Sqz 50 sx cmt @ 90 3. Perf & Sqz 30 sx cmt @ 45 4. Perf & Sqz 25 sx cmt @ 10 5. Cut off well head, verify cm	0-700'. WOC & Tag (B/Sa 3-300'. WOC & Tag (T/Sa 0' to surface.	ilt) lt & 8 5/8" Shoe)		or record NMOCD
•	•	,	Verify Cont 5	un lus
	SEE	ATTACHED FOR		
	COI	<b>NDITIONS OF APPR</b>	OVAL	
Below ground	level dry	hole marker	require ann	OIL CONSERVATIO
14. I hereby certify that the foregoing is	true and correct.	180955 verified by the BLM Wel	Information System	
Comm	For COG O	PERATING LLC, sent to the Ca ing by DEBORAH MCKINNEY of	rlsbad	OCT 0 2 2019
Name(Printed/Typed) ABIGAIL	Title REGUL		RECEIVED	
			REGENVEL!	
Signature (Electronic Submission)		Date 08/29/20	)19	

Conditions of approval of any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title

Approved By





## COG Operating, LLC

Lease & Well #

**Burch Keely Unit 85** 

3001521663 Spud date 11-2-75 Completion date 12/3-75 Elevation - 3595 Sec 24 Unit F T17S R29E, 2615 FSL & 1295 FWL EDDY CO., NM

Calculated TOC @ 163'

.

4. Perf & Sqz 25 sx cmt @ 100' to surface.

10 1/4 bolo

8 5/8" 24# @ 403, Cmt w/100 sx.

- 3. Perf & Sqz 30 sx cmt @ 453-300'. WOC & Tag (T/Salt & 8 5/8" Shoe)
- 2. Perf & Sqz 50 sx cmt @ 900-700'. WOC & Tag (B/Salt)

Calculated TOC @ 2042'.

1. Set 4 1/2" CIBP @ 2290'. Circulate hole w/ MLF. Pressure test csg. Spot 35 sx cmt @ 2290-1940'.

In 1991 added perfs:

2360, 2383, 2424, 2415, 2445, 2456, 2466, 2470, 2480, 2510,

2831, 40, 61, 66, 87, 2902, 24,

2942, 45, 3178,80, 3512, 3534.

Loco Hills

2340-2350 frac w/20,000 gal GW, 20,000# sd

Premier

2526-2530 Acidized w/2,500 gal 15% HCL

2604-2607 Acidized w/1,500 gal 15% Jackson

2872-2877 Acidized w/4,000 gal 15%

2910-2915 Acidized w/3,500 gal 15%

3194-3200 Frac w/10,000 gal GW, 10,000# sd

3358-3365 Frac 2/20,000 gal GW, 20,000 # sd **Sub Keely** 

3500-3510 Frac w/20,000 gal GW, 20,000# sd

IP 45 BO, 115 MCFG, & 60 BLW 12/7/1975

PBTD - 3544'

Cmt w/350 sx CL H, 10#;sd/sk, 5# salt/sk 4 1/2" 9.5/10.5 # csg @ 3550'.

## **COG Operating, LLC**

Lease & Well # **Burch Keely Unit 85** 3001521663 Sec 24 Unit F T17S R29E, 2615 FSL & 1295 FWI Spud date 11-2-75 EDDY CO., NM T/Latt - 405 = Completion date 12/3-75 B/Salt - 816± Queen-1876 San Andres-2563' Elevation - 3595 Calculated TOC @ 163' 12 1/4 hole / dovington - 2666' 8 5/8" 24# @ 403, Cmt w/100 sx. Casing cementing calculations 8 5/8" 24# 12.25" Surface hole Cement volume. = 100 X 1.32 CF/SK = 132 cu. Ft. slurry 132 - 25% slurry loss for shoe joint & hole loss = 99.0 CF 99 CF X ann. Vol. of 2.4229 FT/CF = 240' 403 - 240 =163' estimated (calculated) top of cement. Calculated TOC @ 2042'. 4.5" 9.5/10.5 # 7 7/8" hole Cement volume = 400 X 1.20 CF/SK = 480 cu.ft. slurry. 480 - 30% slurry loss for shoe joint & hole loss =336 CF 336 CF X ann. Vol. of 4.4899 FT/CF =1508' 3550 - 1508 = 2042' estimated (calculated) top of cement. 2340-2350 frac w/20,000 gal GW, 20,000# sq In 1991 added perfs: 2526-2530 Acidized w/2.500 gal 15% HCL/ 2360, 2383, 2424, 2415, 2445, 2456, 2466, 2470, 2480, 2510, 2604-2607 Acidized w/1,500 gal 15% 2831, 40, 61, 66, 87, 2902, 24, Jackson 2942, 45, 3178,80, 3512, 3534, 2872-2877 Acidized w/4,000 gai 15% / 2910-2915 Acidized w/3,500 gal 15% 3194-3200 Frac w/10,000 gal GW, 10,000# sd 3358-3365 Frac 2/20,000 gal GW. 20,000 # sd 🔑 Sub Keely 3500-3510 Frac w/20,000 gai GW, 20,000# sd IP 45 BO, 115 MCFG, & 60 BLW 12/7/1975 Cmt w/350 sx CL H. 10# :sd/sk, 5# salt/sk PBTD - 3544 4 1/2" 9.5/10.5 # csg @ 3550'. 32.8199959 -104.0326309

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs:

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:

From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted