

DISTRICT I

1625 N. French Drive, Hobbs, NM 88240

DISTRICT II

1301 Grand, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, New Mexico 87505

RECEIVED

JUN 22 2006

UN-ARTESIA

WELL API NO.

30-015-25454

5. Indicate Type of Lease

STATE: ☒ FEE ☐

6. State Oil & Gas Lease No.

E-5229

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Forty Niner Ridge

1. Type of Well:

OIL ☐ GAS ☐
WELL ☒ WELL ☐ OTHER ☐

2. Name of Operator

STRATA PRODUCTION COMPANY

8. Well No.

#3

3. Address of Operator

P.O. BOX 1030, ROSWELL, NEW MEXICO 88202-1030

9. Pool Name or Wildcat

Forty Niner Ridge Delaware

4. Well Location

Unit Letter **F** : **2310'** Feet From The **North** Line and **1980** Feet From The **West** Line
Section **16** Township **23 South** Range **30 East** NMPM **Eddy** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3124' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

REMEDIAL WORK ☐ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: Recompletion ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103

MIRU. Lower rods. SI well. TIH. TOH w/rods. TIH w/fishing tool. Fish sub. Unseat pump. TOH w/rods. RU swab. PU new pump. TIH w/rods & seated pump. Hung well back on. SD. RU. TOH w/rods, pump & tbg. SISD. Prep to test upper zones. TIH w/pkr & plug. Acidize. RU swab. Swab well. SISD. Rel pkr & TOH. Prep to put well on pump. GIH w/production string. Set TA. Flange up wellhead. TIH w/pump & rods. Hang well on. Prep to move up hole. TOH w/rods & pump. NUBOP. TOH w/production string. TIH w/ret tool. Latch on to RBP. TOH w/tools. TIH w/guns. Perforate as follows: 6989', 90, 7014', 15, 16, 26, 31, 46 & 47'. RD. PU, GIH w/RBP & pkr. RU & GIH. Acidize. RU swab. Swab well. Rel pkr. Prep to TOH. GIH w/tools. PU frac string. SISD. Prep to frac. SISD. WO frac crew. Frac. Prep to perf. TIH w/guns. Perforate as follows: 6682', 83, 84, 85 & 86'. RD. SISD. TIH w/pkr & RBP. Acidize. RU swab. Swab well. SISD. WO frac crew. Release pkr. TOH w/tbg. PU pkr. TIH w/tbg. SISD. RU. Frac. Release pkr. TOH w/tbg. TIH w/production string. Set anchor & NUWH. PU pump. TIH w/rods. Seated pump & hung well on. SD rig.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly M. Britt TITLE Production Records DATE 06/20/06

TYPE OR PRINT NAME Kelly M. Britt TELEPHONE NO. 505-622-1127 Ext 15

(This space for State Use)

FOR RECORDS ONLY

APPROVED BY _____ TITLE _____ DATE JUL 01 2006
CONDITIONS OF APPROVAL, IF ANY: _____