

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised May 08, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-34857
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator LCX Energy, LLC		6. State Oil & Gas Lease No.
3. Address of Operator 110 N. Marienfeld, Ste. 200, Midland, TX 79701		7. Lease Name or Unit Agreement Name: 1823 NICHOLS
4. Well Location Unit Letter <u>M</u> : <u>760</u> feet from the <u>SOUTH</u> line and <u>660</u> feet from the <u>WEST</u> line Section <u>2</u> Township <u>18S</u> Range <u>23E</u> NMPM County <u>EDDY</u>		8. Well Number 21
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3915' GR		9. OGRID Number 218885
		10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/5/06 - 9/7/06 MIRU PULLING UNIT. PICK UP AND RIH W/ 4 3/4" BIT AND 2 7/8" DRILL PIPE. TAG AT 7718'. CLEAN WELL OUT TO 7750', FLOAT COLLAR AT 7740'. POOH W/ TUBING. RIH W/ 4 3/4" BIT AND 5 1/2" CASING SCRAPER. TEST CASING TO 5000#. HELD OK. PICKLE TUBING AND CASING W/ 1000 GALS PICKLE ACID. SPOT 5000 GALS 15% HCL ACID. POOH.

9/8/06 TIH W/ TCP GUN ASSEMBLY. SPACE OUT. PRESSURE UP ON GUNS TO SHOOT. SHOOT HOLES AT 7740' (14H), 7510' (13H), 7275' (12H), 7040' (11H), 6850' (10). ACIDIZE PERFS W/ 5000 GALS 15% HCL ACID AT 16 BPM AND 3500#. ISDP 1200#. POOH W/ TUBING AND GUN ASSEMBLY. SWFN.

9/10/06 LAY DOWN TUBING, SET FRAC VALVE. WELL READY TO FRAC.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kanicia David TITLE Regulatory Agent DATE 9/13/06

Type or print name KANICIA DAVID

Telephone No. 432-848-0214

(This space for State use)

FOR RECORDS ONLY

SEP 18 2006

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any: