Form 3160-5 (September 2001)

Oil Cons. N.M. DIV-Dist. 2 **UNITED STATES**

FORM APPROVED OMB No. 1004-0135 Expires: January 31, 2004

DEPARTMENT OF THE INTERIOR O1 W. Grand Avenue
BUREAU OF LAND MANAGEMENT Artesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

LC-067858

abanuoneu we	iii. U3	· ·	, 10	n sach propos	ais.			Ess	DI	_		
SUBMIT N TRIPLICATE - Other instruc				ons on rever	7.	7. If Unit of CAASTO ABO ALL NUTS NO. NM-70945						
1. Type of Well	-		***	2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.								
☑ Oil Well ☐ Gas Well ☐ Other				\$3031-123456 \$3031-123456 \$3031-123456				8. Well Name and No.				
2. Name of Operator BP America Production Company								Empire Abo Unit "M" 151 9. API Well No.				
3a. Address				3b. Phone No. (include area code)				30.015.22568				
P.O. Box 1089, Eunice, NM 88231				505.394.1000 DECEIVED				10. Field and Pool, or Exploratory Area				
4. Location of Well (Footage, Sec., T, R., M., or Survey Description)				16 MEDELLER 10				Empire Add				
Unit Letter B, 400' FNL & 1450' FEL				\% OCD - ARTESIA ಪ				/ 11. County or Parish, State				
Section 11, T18S, R27E				(character) of the				Eddy, NM				
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA												
TYPE OF SUBMISSION		TYPE OF ACTION										
		Acidize		Deepen		Production (St	art/Res	ume)	O w	ater Shut-Off		
☑ Notice of Intent	ō	Alter Casing	ō	Fracture Treat	ō	Reclamation		,	o w	ell Integrity		
Subsequent Report		Casing Repair		New Construction		Recomplete			0 0	ther		
		Change Plans	\square	Plug and Abandon	n 🔲	Temporarily A	bando	n	_			_
Final Abandonment Notice		Convert to Injection		Plug Back		Water Disposa	1		_			_
Attach the Bond under which the following completion of the investing has been completed. Find determined that the site is ready in the following that the following t	olved o al Abai for fina 6084 to 300 lorietta 66'. RI elow 8- ce 50 sp	#. 13354-3454'. WOC. RI H w/tbg & spot 25 sxs a -5/8" esg). Ks cmt 100' outside & 10 W/60' tbg & circ 10 sxs RDPU. A generation.) A G	IH & acros	alts in a multiple cond only after all required tag top of plug. ss Yates 356-456 nside. WOC. Ta	mpletion uirements '(100' in ag top of & outsid BJECT JIREM	or recompletions, including recompletions, inc	csg).	AU L NOTE: 1	PROPERTY OF THE PROPERTY OF TH	m 3160-4 shanpleted, and the OVED 2003	Il be filed onche operator ha	ce
14. 1 hereby certify that the foregoin	g is tru			MAL SHPU	L/\ H 6	NS ATTA	CHE	D				=
Name (PrintedlTyped) Kellie D. Murrish				Title 5	Title Sr. Administrative Assistant							_
Signature William W. Maruns Date						ote 08.25.03						
		V BRIES REVVOERS	OR	FEDERAVOR		OFFICE US	Ħ,					
Approved by (Signature)	Credit				Name (Printed/Ty	ped)			Title			
Conditions of approval, if any, are certify that the applicant holds legs which would entitle the applicant to continuous	al or eo	uitable title to those right	e do ts in	the subject lease	Office					Date		_

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

PLUGGING PROCEDURE EAU M-151


- 1. MIRU PULLING UNIT ND WH NU BOP
- 2. PICK UP 2 3/8" WS AND RIH TAG CIBP
- 3. SPOT 25' CMT ON TOP OF CIBP
- 4. CIRCULATE 9.5 KCL TEST CSG TO 300#
- 5. PULL UP HOLE AND SPOT 25 SX CMT ACROSS GLORIETA 3354'- 3454'
- 6. WOC RIH AND TAG TOP OF PLUG
- 7. POOH W/TBG RU WIRELINE AND PERFORATE @ 456'
- 8. RIH W/ TBG AND SPOT 25 SX CMT ACROSS YATES 356' 456'(100' INSIDE & OUTSIDE CSG)
- 9. WOC RIH AND TAG TOP OF PLUG
- 10. POOH W/TBG PERFORATE @ 1050' (50' BELOW 8 5/8" CSG)
- 11. RIH W/ PKR AND SET @ 950' SQUEEZE 50 SX CMT 100' OUTSIDE AND 100' INSIDE
- 12. WOC TAG TOP OF PLUG
- 13. POOH W/ PKR AND TBG PERFORATE CSG @ 60'
- 14. RIH W/ 60' TBG AND CIRCULATE 10 SX CMT TO SURFACE INSIDE AND OUTSIDE.
- 15. WOC 24 HRS AND TAG
- 16. CUT OFF WELL HEAD AND ACHORS CLEAN LOCATION RD

WELLBORE SCHEMATIC

10 SX CMT 60' TO SURF.



8-5/8" casing @ 1000' **Cmt Circulated to surface**



5-1/2" csg @ 6310' cmt circlulated to surface

PBD @ 6239'