Submit 3 Copies To Appropriate District Office	State of New	Mexico		Form C-103
District I	Energy, Minerals and Natural Resources			Feb 7, 2007
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO.	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-27676 5. Indicate Type of I	ease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. F	rancis Dr.	STATE	FEE Federal
District IV	Santa Fe, NM	87505	6. State Oil & Gas L	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	CES AND REPORTS ON WEI	LLS	7. Lease Name or Ur	nit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)			EAST SHUGART U	
1. Type of Well: Oil Well	Gas Well 🛛 Other – <b>Injectio</b> n	n well	8. Well Number #0	41
Name of Operator     America	Energy Resources, LLC	Morth - 1007	9. OGRID Number 228051	
3. Address of Operator 7575 San Felipe, Suite 200, Houston		MONTH 2 2007 FEB 1 3 2007 OCD - ARTESIA 184	10. Pool name or Wi Shugart Y-SR-QN-G	
4. Well Location	, 17/1003	oco	Shugart 1-5K-Q14-0	
	1650_feet from the North		feet from the East_	line
Section 34	Township 18 South Ran	nge 31 East	NMPM Eddy	County
1995年中国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国共和国	11. Elevation (Show whether I 3634 GL	DR, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application or				
Pit typeDepth to Groundwate				vater
Pit Liner Thickness: mil			nstruction Material	
12. Check Ap	opropriate Box to Indicate	Nature of Notice, 1	Report or Other Da	ta
NOTICE OF INT			SEQUENT REPO	
PERFORM REMEDIAL WORK		REMEDIAL WORK	<del></del>	TERING CASING
TEMPORARILY ABANDON				
FOLL OR ALTER CASING	MOLTIFIL COMFL []	CASING/CLIVILINI	30B	
OTHER:		OTHER:		
13. Describe proposed or comple	ted operations. (Clearly state a	ill pertinent details, and	give pertinent dates, i	ncluding estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or re-completion.				
Notice of Intention to Remedial Work:				
- Inform "OCD" 505-748-1283 EXT 102 103				
- MIRU service rig, kill well, N/D tree, N/U bop's.				
<ul> <li>Release on/off tool, and pooh with 2-3/8" tubing. Re-dress on/off overshot.</li> <li>Pick up on/off tool, testing 2-3/8" in hole. Space out &amp; latch on packer.</li> </ul>				
- Pick up on/off tool, testing 2-3/8" in hole. Space out & latch on packer Inform "OCD" 24 hrs before conduct formal testing Install X-MAS tree. Test 5-1/2" casing 500 psig for 30 minutes using pressure chart.				
- Install X-MAS tree	. Test 5-1/2" casing 500 psig f	or 30 minutes using pre	essure chart.	
<ul> <li>If testing casing is st</li> </ul>	accessful . Install wellhead equ	ipment and put well on	injection.	
- Provide C-103 Subse	equent report along with press	sure chart.		
I hereby certify that the information ab grade tank has been/will be constructed or clo				
SIGNATURE ALLE M.	La TITLE	Land Manager	_DATE_2/9/07	
	$\supset$			004.0700
Type or print name Robert M. Gray For State Use Only	E-mail address: don.gra		•	984-9700 1 2007
Round	Jung	Gerry Guy Deputy Field Ins		FEB 1 4 2007
ATTROVED BI.	TITLE	District II - Art	i . 1) A	ATE
Conditions of Approval (if any):			<del>= =: =</del>	