Form 3160-5 (February 2005)



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD - ARTESIA

FORM APPROVED
OMB No 1004-0137
Expires: March 31, 200

Expires: March 31, 2007

5.	Lea	se S	erial	No.	
N	M-1	722	5-R		

SUNDRY N Do not use this f abandoned well.	6. If Indian, Allottee or Tribe Name						
SUBMIT	7. If Unit of CA/Agreement, Name and/or No.						
1. Type of Well				1			
✓ Oil Well Gas W	DEC 2 0 2007		8 Well Name and No. ABBY FEDERAL #5				
2. Name of Operator RKI EXPLORATION & PRODUCTION	DN, LLC	OCD-AKIE	SIA	9. API Well No. 30-015-29308			
3a. Address P.O BOX 370, CARLSBAD, NM 88221	3b. Phone No (include area code)		10. Field and Pool or Exploratory Area				
		505-885-1313		ROSS DRAW; DELAWARE, WEST			
4. Location of Well <i>(Footage, Sec., T.,I)</i> P 28-26S-30E, 967' FSL & 330' FEL	11 Country or Parish, EDDY, NM			State			
12. CHEC	K THE APPROPRIATE BO	OX(ES) TO INDICATE NAT	URE OF NOTIO	CE, REPORT OR OTHE	ER DATA		
TYPE OF SUBMISSION		O To Company of the C	TYPE OF ACT	TION			
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat		luction (Start/Resume) amation	Water Shu Well Integ	rity	
✓ Subsequent Report	Casing Repair	New Construction	Reco	omplete		DED PERFS IN	
<u> </u>	Change Plans	Plug and Abandon	Tem	porarily Abandon	DELA	WARE ZONE	
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Wate	er Disposal			
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)							
ADD DELAWARE ZONE							
Work commenced on 11-7-07. Pulled rods & insert pump. Pulled to Perforated Delaware zone 6266'-629 via 2-7/8" tubing at 21 bpm with 18,0 plug @ 6,390' and cleaned out to 6,0 Placed well on production. Work completed on 11-15-07.	92' and 6295'-6315' (47 ho 000 gals. SilverStim LT Ba	oles). Acidized with 2000 gasic (21) with 35,000# 16/3	gals. 7-1/2% N 0 white sand a	EFE HCl acid using 7°	1 ball sealers. Fin-coated sand.	rac'd Delaware	
				DEC 18 20 0 ALEXIS C. SWOB PETROLEUM ENGI	ODA		
14 I hereby certify that the foregoing is to	rue and correct						

	PRODUCTION SUPERINTENDENT									
12/07/2007										
Signature Date 12/07/2007 THIS SPACE FOR FEDERAL OR STATE OFFICE USE										
ritle	Date									
Office										
T:	OR STATE OFFICE USE									

Title 18 U S C Section 1001 and Title 43 U S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Name (Printed/Typed)