Form 3160-5 (April 2004)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

EST	OM B No 1004-0137 Expires: March 31, 2007

EODM ADDROVED

BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					<ul><li>5. Lease Serial No. NMLC029339A</li><li>6. If Indian, Allottee or Tribe Name</li></ul>		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.  8. Well Name and No.  JACKSON A #3  9. API Well No.  30-015-04132 S2  10. Field and Pool, or Exploratory Area  GRAYBURG JACKSON			
2. Name of Operator BURN a. Address 801 CHERRY ST UNIT #9 FORT WORTH b. Location of Well (Footage, Sec., 2)							
UNIT J, 1980' FSL, 2000' FEL, SEC 13,T17S,R30E  12CHECK_APPROPRIATE BOX(ES) TO INDICATE NATURE_OF NOTICE,_RI					11. County or Parish, State Eddy County, N.M.		
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent Subsequent Report Final Attandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Star Reclamation Recomplete Temporarily Aba Water Disposal	,	Water Shut-Off Well Integrity Other		
	ctionally or recomplete horizont	ally, give subsurface location	s and measured and true rith BLM/BIA. Require	e vertical depths d subsequent re	of all pertinent markers and zones. ports shall be filed within 30 days		

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

9/04/2007 Notify BLM's Terry Carpenter to start P&A work on this well. 9/05/2007 MIRU. Perf. four(4) squeeze @ 2820'. Run 7" pkr & pump into perfs @ 2BPM @ 340 PSI. POOH w/ pkr. RIH w/7" cmt retainer & set @ 2723'. Pump 50 sks Class C cement below retainer, left 50' of cement on top of retainer. POOH, Perforate @ 613' w/ith four(4) holes. RIH w/7" pkr, pump into holes @ 2 BPM @ 240 PSI. POOH, RIH w/cmt ret set @ 492', pump 50 sks Class C cement below retainer- left 50' of cmt on top of retainer. POOH. Perforate @ four(4) holes @ 100'. Pump down csg, circulate w/14 bbls water, well down on vacuum. Pump 80 sks Class C cement down bradenhead. Circulated cmt to surface. Shut in well for the night. 9/06/2007 Cement down 60' in casing. RDMO.9/07/2007 9/07/2007 Filled 7" csg with1-1/2 yards cement to surface. Witnessed by BLM's Terry Cartwrigh@ 1:30 PM. 9/10/2007 Found cement @ surface in 7" casing. Well bore is plugged and abandoned. Dry hole marker installed. Cut anchors below ground. All witnessed by Terry Cartwright w/ BLM. 12/22/2007 All equipment has been moved

This location has been restored to its normal look and is ready for BLM inspection before reseeding.

**NMOCD** 

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) MARK A. JACOBY		Title ENGINEERING MANAGER							
Signature Marle A. Jaroley	Date	6/	NAC.	POWSFNF	RECORD				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE LITTLE TOTAL TOTAL COMP									
Approved by		Title		Date 10	2008				
Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon.	1	Office		1 ams	2000				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make the any department of agency for the full hited States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.									
(Instructions on page 2) Accepted for record				A WAY SKATT ETEL	<u></u>				