Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

AUG 1 4 2008

DCD. Artesia

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

~	If Indian	Allotten or Triba Nama
	NMNM.	77042
J	TOTAL SOLN	I NO.

		•	•				
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well Oil Well □ □	8. Well Name and No. Grandview Fed. #1 9. API Well No.						
Name of Operator Primero Ope							
3a. Address 3b. Phone No. (include area code)					30-015-26004		
PO Box 1433, Roswell, NM 88 4. Location of Well (Footage, Sec.,	10. Field and Pool, or Exploratory Area Sq Lake, Grayburg/SA 11. County or Parish, State Eddy, NM						
1980' FN&EL Sec 20, T16S, R31E							
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
✓ Notice of Intent Subsequent Report Final Abandonment Notice	Report Casing Repair New Construction Recomplete Change Plans Plug and Abandon Temporarily				Water Shut-Off Well Integrity Other		
13. Describe Promosed or Completed Operation (clearly state all pertinent details including entire testing date of any proposed week and execution thereof							

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Persuant to conversation with Jim Amos, Primero Operating, Inc. plans to P&A this well as follows:

Set a 5 1/2" CIBP w/ 35' cement @ 2900' ~ Perforate 5 1/2" casing @ 750' and 60'

load hole with 9 lb mud and pump the following plugs

1. 25 sx @ 1675' WOL Tay No Lower th

2. 80 sx @ 750', Plug to be tagged No Lower than

3. 60 sanget to be tagged No Lower than ¥ 1. 25 sx @ 1675' ~ ₩ 0 C

2. 80 sx @ 750', Plug to be tagged No Lower Han 3. Cement to be pumped @ 60' to fill 5 1/2" and 8 5/8" to surface. 354

The location will be cleaned of junk and a dry hole marker will be installed.

★ SEE ATTACHED FOR CONDITIONS OF APPROVAL

APPROVED						
	AUG 1 1 2008					
JAMES A. AMOS SUPERVISOR-EPS						

14. Ihereby certi Name (Print	ify that the foregoing is true and correct ted/Typed)	3			
Ph	aclps White	Title President			
Signature	1.	Date 8-8	OS ACCEPTED FOR RECORD		
	THIS SPACE FOR FEDERAL	OR STATE OFF	ICE USE		
Approved by Conditions of appro	oval, if any, are attached. Approval of this notice does not warrar	Title	Date AUG 1 4 2008		
which would entitle	licant holds legal or equitable title to those rights in the subject lead the applicant to conduct operations thereon.	Office	Gerry Guye, Deputy Field Inspector		
Title 18 U.S.C. Sect	non 1001 and Title 43 U.S.C. Section 1212, make it a crime for any	person knowingly and will	fully to make to any department of agency to the Rail ESIA		

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.