(Instructions on page 2)

OCD-ARTESIA

UNITEDSTATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT -

AUG 25 2009

FORMAPPROVED	
OM B No 1004-0137	
Evnires March 31	2007

SUNDRY NOTICES AND REPORTS ON WELLS

5 Lease Serial No NMLC067144

	is form for proposals ell. Use Form 3160 - 3			6 If India	in, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7 If Unit or CA/Agreement, Name and/or No			
1 Type of Well Oil Well	☐ Gas Well ☐ Other			8 Well N	Iame and No	
2.14				Big Eddy #66		
2. Name of Operator BOPCO, L.P.				9. API W		
3a Address		3b. Phone No (inc	lude area code)	l l	5-22682	
P.O. Box 2760 Midland T	X 79702	(432)683-		10 Field	and Pool, or Exploratory Ar	ea
4 Location of Well (Footage, Sec	c., T, R, M., or Survey Desc	ription)		Indian	Flats (Atoka)	
UL K, SEC 25, T21S, R2	28E, 1980' FSL, 2130'	FWL		11 Coun Eddy NM	nty or Parish, State	
12 CHECK AF	PPROPRIATE BOX(ES)T	O INDICATE NAT	URE OF NOTICE,	REPORT, C	OR OTHER DATA	
TYPE OF SUBMISSION		-	TYPEOF ACTION			
	X Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
Notice of Intent	AlterCasing	FractureTreat	Reclamation		Well Integrity	
X Subsequent Report	Casing Repair	New Constructi	on Recomplete		X OtherSwab well	
	Change Plans	Plug and Aband	on Temporarily	Abandon	& return well	
Final Abandonment Notice	Convert to Injection	PlugBack	☐ Water Dispos	al	to production	
	ly wishes to report we co swab unit. MIRU B additives. Drop total o NU swab. Swab to "Fnipple @ 11,364' after runs from SN @ 11,30,900' FS. Make 5 to 20,500' FS. Make 15 to recover no fluid. St. Waiting for connectito production.	be filed only after all recommendations with the filed only after all recommendations. J. Services. Load f. 120.1.3 ball ser 7 runs. Make to 366'. The filed swab runs to 3 total swab runs. D. Swab. SI well. on to the pipeling with the filed swap.	and the return of the the the the the the the the the the	lamation, have the well to s w/ 0.50 b 5000 gals a Make tota recover 20 ols.	been completed, and the operator production: Solls 2% KCI. Load the acid @ 5950 psi. Flusted to recove the soll of 18 runs to recove the bolls fluid.	ator has g w/ 31 sh acid w/
14. I hereby certify that the foregoname (Printed/Typed)	going is true and correct	1				
Valerie Truax		Title	Regulatory A	dmin-Assis	tant	
Signature Meleu	Suay	Date	08/17/2009	ACCE	PTED FOR RE	CORD
	THIS SPACE FOR	FEDERAL OR	STATE OFFIC	E USE		T
Approved by			Title		Date UG 1 9 2009	
Conditions of approval, if any, are certify that the applicant holds lega which would entitle the applicant	al or equitable title to those righ	its in the subject lease	Office	RIIP	FALL OF LAND MANAGE	MENT
Title 18 U.S.C Section 1001 and Title States any false, fictitious or frauc	tle 43 U S C Section 1212, maldulent statements or represent	te it a crime for any pers	on knowingly and willfu within its jurisdiction	Ily to make to	मंभ्रिवकुष्ठिम्मिना १ ह ब्रह्मिण्डिनि	EUnited