OCD-ARTESIA

Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SFP	2	2	20	09	
ארר	_	<u>_</u>	LU		

FORM APPROVED OMB No 1004-0137 Expires March 31, 2007

M APPROVED No 1004-0137	

_		·
5	Lease Senal No	
	NM 033647	
_		

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6 If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7 If Unit or CA/Agreement, Name and/or No 8. Well Name and No.		
1. Type of Well					
2 Name of Operator Apache Corp	ooration			Bogle F 9 API We	lats Unit # 13
Ba Address 3300 N. "A" Ste. 7-150 Midla	3b Phone No (include area code) 432-683-6511		30-015- 10 Field and	28827 1 Pool. or Exploratory Area	
4 Location of Well (Footage, Sec., 1020' FNL & 750' FEL, Section 12. CHECK Al	on 17, T-22-S, R-23-E	TO INDICATE NATUR	RE OF NOTICE. I	11 County of Eddy, N	Basin Upper Penn or Parish, State New Mexico OTHER DATA
TYPE OF SUBMISSION			PE OF ACTION	· · · · · · · · · · · · · · · · · · ·	
Notice of Intent ✓ Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Standarding Reclamation Recomplete Temporarily A Water Disposal	bandon	Water Shut-Off Well Integrity Other
					rk and approximate duration thereof s of all pertinent markers and zones

Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)

8/11/2009 Spot 35sxs cmt @ 6319'-6110'

8/11/2009 Perf @ 4600' Sqz 50sxs cmt @ 4600' tag plug @ 4411'

8/12/2009 Perf @ 2810' Sqz 50 sxs cmt @ 2810' tag plug @ 2633'

8/13/2009 Spot 35sxs cmt over hole in casing from 2633'-2424' tag plug @ 2520'

8/13/2009 Perf @ 1920' Sqz 50sxs cmt @ 1920' tag plug @ 1770'

8/13/2009 Perf @ 1920' Sqz 50sxs cmt @ 1920' tag plug @ 1770'
8/14/2009 Perf @ 1300' Sqz 150sxs cmt @ 1300' tag plug @ 772'
8/17/2009 Perf @ 482' Sqz 150sxs cmt from 482' to surface out of 9 5/8" casing leave 7" full of cmt _ R D m O. Cuf off whth anchors.



accepted as to plugging of the well bore. Liability under bond is retained until Surface restoration is completed.

14 Thereby certify that the foregoing is true and correct Name (Printed/Typed)	T.d.		
Larry Winn.	Title Area Manager, P&A Basic Energy Services 432-530-0907		
Signature ////	Date	08/25/2009PTFD FOR RECORD	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by	Title	Date p 1 9 2009	
Conditions of approval, if any, are attached Approval of this notice does not warran certify that the applicant holds legal or equitable title to those rights in the subject lear which would entitle the applicant to conduct operations thereon	1	Almo	
Title 18 USC Section 1001 and Title 43 USC Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter	person knowingly and will within its jurisdiction.	If July to make REAN GEAN GENERAL CARL SHAD FIFT DOFFICE	
(Instructions on page 2)		John Loon of Tell Office	