Form 3160-5	<b>OCI</b> UNITED STATE	s l	CEIVED	FORM APPROVED OM B No. 1004-0137
April 2004)	DEPARTMENT OF THE BUREAU OF LAND MAN	EINTERIOR N	DV 132009	Expires March 31, 2007
SUNDRY	Y NOTICES AND RE			5 Lease Senal No LC-029420-B
Do not use t	this form for proposals vell. Use Form 3160-3 (	to drill or to re	-enter an	6 If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7 If Unit or CA/Agreement, Name and/or No
				8 Well Name and No.
2 Name of Operator Yeso Energ	Dow "B" 28 Federal #1   9 API Well No			
Ba Address P.O. Box 2248 Roswell, NM	88202	3b Phone No (inclu 575-622-7355	ide area code)	30-015-28676
Location of Well (Footage, Sec	5/5-022-7555		10 Field and Pool, or Exploratory Area WildcatCedar Lake Mississippian	
1028' FSL & 1227' FEL				11 County or Parish, State
Sec. 28-T17S-R31E				Eddy County, NM
12. CHECK A	APPROPRIATE BOX(ES) TO	) INDICATE NATU	JRE OF NOTICE, RI	EPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent		Deepen	Production (Star	
	Alter Casing	Fracture Treat	n Recomplete	Well Integrity
Subsequent Report	Change Plans	Plug and Abandon		
Final Abandonment Notice	Convert to Injection	✓ Plug Back	Water Disposal	
C 11 1	1 1 1 101			d subsequent reports shall be filed within 30 days
testing has been completed 1 determined that the site is rea The Dow "B" 28 Fed #1 permanently plug back t depth of 8584'9580' ov Set blanking plug in p Set CIBP at 11,750'. Set CIBP at 11,750'. Set CIBP at 11,100'. Test 5.5'' casing to 25 Perforate Wolfcamp froi the proper well completi	Final Abandonment Notices shall be dy for final inspection ) is currently completed in the V the Mississippian (12,118'12,1 erall. The plug back will be pe packer at 12,024'. Test plug to Cap with 35' cement on top of Cap with 35' cement on top of Cap with 35' cement on top of 00 psi. Chart pressure test to i m 8584'9580' and test for con ion form. Work planned to sta	n results in a multiple coi e filed only after all requi- Wildcat Cedar Lake N 80') and the Morrow rformed as follows: 5000 psi. Pull tubin CIBP to cover Morro CIBP to cover Morro CIBP to cover top of insure casing integrity nmercial production. wrt immediately upon	mpletion or recompletion in irements, including reclama (11,764'11,792') and or of hole. Dump 35 ow perforations. (No ot Penn (Cisco) (per NMC y of 5.5" casing from 97 Results of test to be re	a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has r Lake Morrow pools. Operator proposes to perforate the Wolfcamp formation from a 5' cement on top of packer w/ blanking plug. her perfs currently exist above this point.) OCD tops) 760' to surface. ported on subsequent Sundry Notice and/or
testing has been completed I determined that the site is real The Dow "B" 28 Fed #1 permanently plug back to depth of 8584'9580' over Set blanking plug in p Set CIBP at 11,750'. Set CIBP at 11,750'. Set CIBP at 11,760'. Test 5.5'' casing to 25 Perforate Wolfcamp from the proper well completion the proper well completion the proper well completion the proper well completion the proper well completion the proper well completion the proper well completion the proper well compl	Final Abandonment Notices shall be dy for final inspection ) is currently completed in the V the Mississippian (12,118'12,1 erall. The plug back will be pe packer at 12,024'. Test plug to Cap with 35' cement on top of Cap with 35' cement on top of Cap with 35' cement on top of 00 psi. Chart pressure test to i m 8584'9580' and test for con ion form. Work planned to sta	n results in a multiple coi e filed only after all requi- Wildcat Cedar Lake M 180') and the Morrow rformed as follows: 5000 psi. Pull tubin CIBP to cover Morro CIBP to cover Morro CIBP to cover Atoka. CIBP to cover Atoka. CIBP to cover top of insure casing integrity numercial production. art immediately upon	mpletion or recompletion in irements, including reclama (11,764'11,792') and ing out of hole. Dump 35 ow perforations. (No ot Penn (Cisco) (per NMC y of 5.5" casing from 97 Results of test to be re approval.	a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has r Lake Morrow pools. Operator proposes to perforate the Wolfcamp formation from a 5' cement on top of packer w/ blanking plug. her perfs currently exist above this point.) OCD tops) 760' to surface. ported on subsequent Sundry Notice and/or
testing has been completed 1 determined that the site is real The Dow "B" 28 Fed #1 permanently plug back to depth of 8584'9580' over Set blanking plug in p Set CIBP at 11,750'. Set CIBP at 11,750'. Set CIBP at 11,760'. Test 5.5'' casing to 25 Perforate Wolfcamp from the proper well completing 14 Thereby certify that the for Name (Printed/Typed) Gene Lee	Final Abandonment Notices shall be dy for final inspection ) is currently completed in the V the Mississippian (12,118'12,1 erall. The plug back will be pe packer at 12,024'. Test plug to Cap with 35' cement on top of Cap with 35' cement on top of Cap with 35' cement on top of 00 psi. Chart pressure test to i m 8584'9580' and test for con ion form. Work planned to sta	n results in a multiple coi e filed only after all requi- Wildcat Cedar Lake M 180') and the Morrow rformed as follows: 5000 psi. Pull tubin CIBP to cover Morro CIBP to cover Morro CIBP to cover Atoka. CIBP to cover Atoka. CIBP to cover top of insure casing integrity numercial production. art immediately upon	Mississippian and Cedar Mississippian and Cedar (11,764'11,792') and ag out of hole. Dump 35 bow perforations. (No ot Penn (Cisco) (per NMC y of 5.5" casing from 97 Results of test to be re- approval.	a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has r Lake Morrow pools. Operator proposes to perforate the Wolfcamp formation from a 5' cement on top of packer w/ blanking plug. her perfs currently exist above this point.) OCD tops) '60' to surface. ported on subsequent Sundry Notice and/or DENIED
testing has been completed I determined that the site is real The Dow "B" 28 Fed #1 permanently plug back to depth of 8584'9580' over Set blanking plug in p Set CIBP at 11,750'. Set CIBP at 11,750'. Set CIBP at 11,750'. Set CIBP at 11,750'. Test 5.5'' casing to 25 Perforate Wolfcamp from the proper well completion the proper well completion the proper well completion Name (Printed/Typed)	Final Abandonment Notices shall be idy for final inspection ) is currently completed in the V the Mississippian (12,118'12,1 erall. The plug back will be pe packer at 12,024'. Test plug to Cap with 35' cement on top of Cap with 35' cement on top of Cap with 35' cement on top of Go psi. Chart pressure test to i m 8584'9580' and test for con ion form. Work planned to sta	n results in a multiple coi e filed only after all requi- Wildcat Cedar Lake N 80') and the Morrow rformed as follows: 5000 psi. Pull tubin CIBP to cover Morro CIBP to cover Atoka CIBP to cover Atoka CIBP to cover top of insure casing integrity insure casing integrity inmercial production. art immediately upon	Mississippian and Cedar (11,764'11,792') and ing out of hole. Dump 35 ow perforations. (No ot Penn (Cisco) (per NMC y of 5.5" casing from 97 Results of test to be re- approval. CTED, OR I Agent	a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has r Lake Morrow pools. Operator proposes to perforate the Wolfcamp formation from a 5' cement on top of packer w/ blanking plug. her perfs currently exist above this point.) DCD tops) '60' to surface. ported on subsequent Sundry Notice and/or DENIED DENIED 11-10-09 8/10/2009
testing has been completed 1 determined that the site is real The Dow "B" 28 Fed #1 permanently plug back to depth of 8584'9580' over Set blanking plug in p Set CIBP at 11,750'. Set CIBP at 11,750'. Set CIBP at 11,760'. Test 5.5'' casing to 25 Perforate Wolfcamp from the proper well completing 14 Thereby certify that the for Name (Printed/Typed) Gene Lee	Final Abandonment Notices shall be dy for final inspection ) is currently completed in the V the Mississippian (12,118'12,1 erall. The plug back will be pe packer at 12,024'. Test plug to Cap with 35' cement on top of Cap with 35' cement on top of Cap with 35' cement on top of 00 psi. Chart pressure test to i m 8584'9580' and test for con ion form. Work planned to sta	n results in a multiple coi e filed only after all requi- Wildcat Cedar Lake N 80') and the Morrow rformed as follows: 5000 psi. Pull tubin CIBP to cover Morro CIBP to cover Atoka CIBP to cover Atoka CIBP to cover top of insure casing integrity insure casing integrity inmercial production. art immediately upon	Mississippian and Cedar (11,764'11,792') and ing out of hole. Dump 35 ow perforations. (No ot Penn (Cisco) (per NMC y of 5.5" casing from 97 Results of test to be re- approval. CTED, OR I Agent	a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has r Lake Morrow pools. Operator proposes to perforate the Wolfcamp formation from a 5' cement on top of packer w/ blanking plug. her perfs currently exist above this point.) DCD tops) '60' to surface. ported on subsequent Sundry Notice and/or DENIED DENIED 11-10-09 8/10/2009
testing has been completed 1 determined that the site is real The Dow "B" 28 Fed #1 permanently plug back to depth of 8584'9580' over Set blanking plug in p Set CIBP at 11,750'. Set CIBP at 11,750'. Set CIBP at 11,760'. Test 5.5'' casing to 25 Perforate Wolfcamp from the proper well completing 14 Thereby certify that the for Name (Printed/Typed) Gene Lee	Final Abandonment Notices shall be idy for final inspection ) is currently completed in the V the Mississippian (12,118'12,1 erall. The plug back will be pe packer at 12,024'. Test plug to Cap with 35' cement on top of Cap with 35' cement on top of Cap with 35' cement on top of Go psi. Chart pressure test to i m 8584'9580' and test for con ion form. Work planned to sta	n results in a multiple coi e filed only after all requi- Wildcat Cedar Lake N 80') and the Morrow rformed as follows: 5000 psi. Pull tubin CIBP to cover Morro CIBP to cover Atoka CIBP to cover Atoka CIBP to cover top of insure casing integrity insure casing integrity inmercial production. art immediately upon	Mississippian and Cedar (11,764'11,792') and ing out of hole. Dump 35 ow perforations. (No ot Penn (Cisco) (per NMC y of 5.5" casing from 97 Results of test to be re- approval. CTED, OR I Agent	a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has r Lake Morrow pools. Operator proposes to perforate the Wolfcamp formation from a 5' cement on top of packer w/ blanking plug. her perfs currently exist above this point.) DCD tops) '60' to surface. ported on subsequent Sundry Notice and/or DENIED DENIED 11-10-09 8/10/2009
testing has been completed 1 determined that the site is real The Dow "B" 28 Fed #1 permanently plug back to depth of 8584'9580' over Set blanking plug in p Set CIBP at 11,750'. Set CIBP at 11,750'. Set CIBP at 9,760'. Test 5.5'' casing to 25 Perforate Wolfcamp from the proper well completing 14 Thereby certify that the for Name ( <i>Printed/Typed</i> ) Gene Lee Signature	Final Abandonment Notices shall be dy for final inspection ) is currently completed in the V the Mississippian (12,118'12,1 erall. The plug back will be pe packer at 12,024'. Test plug to Cap with 35' cement on top of Cap with 35' cement on top of Cap with 35' cement on top of 00 psi. Chart pressure test to i m 8584'9580' and test for con ion form. Work planned to sta	n results in a multiple coi e filed only after all requi- Wildcat Cedar Lake M 180') and the Morrow rformed as follows: 5000 psi. Pull tubin CIBP to cover Morro CIBP to cover Morro CIBP to cover Atoka CIBP to cover top of insure casing integrity nercial production. ort immediately upon NWN, REJE Title Date FEDERAL OR	Agent	a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has r Lake Morrow pools. Operator proposes to perforate the Wolfcamp formation from a 5' cement on top of packer w/ blanking plug. her perfs currently exist above this point.) DCD tops) 160' to surface. ported on subsequent Sundry Notice and/or DENIED DENIED 8/10/2009 USE

÷.

	(	1
$\left( \right)$	N	~

ſ





Yeso Energy Inc. NMLC-029420-B: Dow "B" 28 Federal #1 API: 30-015-248676 Eddy County, New Mexico

RE: Plug Back and Recompletion, Conditions of Approval

REJECTED due to NMOCD Order No. R-12930-A & B.

Submit Sundry for the Notice of Intent to Plug and Abandon by November 30, 2009.

DHW 111009