

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Oil Cons.
N.M. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210

FORM APPROVED
OMB No. 1004-0135
Expires: January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELL ABANDONMENT
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NMNM-0144698

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.
33244

8. Well Name and No.
Colt 5 Federal #1

9. API Well No.
30-015-33151

10. Field and Pool, or Exploratory Area
East Burton Flat Morrow

11. County or Parish, State
Eddy County, NM

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Mewbourne Oil Company 14744

3a. Address
PO Box 5270 Hobbs, NM 88240

3b. Phone No. (include area code)
505-393-5905

4. Location of Well (Footage, Sec., T, R., M., or Survey Description)
1650' FNL & 1650' FEL, Unit Letter G of Sec 5-T20S-R29E

RECEIVED

JAN 21 2004


OCD-ARTESIA

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other Spud & Csg Job
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

01/05/04...MI & spud 26" hole. TD'd hole @ 322'. Ran 322' 20" 94# K55 BT&C csg. Cemented w/ 200 sks Thixsad "H" w/ additives. Mixed @ 14.6 #/g w/ 1.51 yd. Followed w/ 500 sks 35:65:6 Poz "C" w/ additives. Mixed @ 12.5 #/g w/ 1.98 yd. Tail w/200 sks Class C w/2% CaCl2. Mixed @ 14.8 #/g w/ 1.34 yd. WOC 6 hrs and ran Temp Survey. TOC @ 225'. 1" in 13 stages as listed on attached sheet.



14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed) Kristi Green Title Hobbs Production Analysts

Signature *Kristi Green* Date 01/14/04

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by (Signature) _____ Name (Printed/Typed) _____ Title _____

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office _____ Date _____

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Continued on next page)

Page 2---01/13/04
Colt 5 Federal Com #1
Lease Number: NMNM-0144698
API 30-015-33151
1650' FNL & 1650' FEL
Sec 5-T20S-R29E

(20" 94# K55 BT&C csg) 1" in 13 stages:

Cmt w/25 sks C Neat w/6% CaCl₂. WOC. Tag @ 215'.
Cmt @ 205' w/25 sks C Neat w/5% CaCl₂. WOC. Tag @ 211'.
Cmt @ 205' w/50 sks C Neat w/5% CaCl₂. WOC. Tag @ 211'.
Cmt @ 120' w/50 sks C Neat w/5% CaCl₂. WOC. Tag @ 120'.
Cmt @ 120' w/50 sks C Neat w/5% CaCl₂. WOC. Tag @ 90'.
Cmt @ 90' w/50 sks C Neat w/5% CaCl₂. WOC. Tag @ 90'.
Cmt @ 60' w/50 sks C Neat w/5% CaCl₂. Tag @ 90'.
Cmt @ 60' w/50 sks C Neat w/5% CaCl₂. Tag @ 90'.
Cmt @ 60' w/50 sks C Neat w/5% CaCl₂. Tag @ 80'.
Cmt @ 60' w/50 sks C Neat w/5% CaCl₂. Tag @ 80'.
Cmt @ 60' w/50 sks C Neat w/5% CaCl₂. Tag @ 75'.
Cmt @ 60' w/50 sks C Neat w/5% CaCl₂. Tag @ 65'.
Cmt @ 60' w/50 sks C Neat w/5% CaCl₂. Circ 10 sks to pit.