

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-26990
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Dahlia ALA Corn
8. Well Number 1
9. OGRID Number 025575
10. Pool name or Wildcat Dagger Draw Upper Penn South

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	<b>RECEIVED</b> <b>FEB 16 2010</b> <b>NMOCD ARTESIA</b>
2. Name of Operator Yates Petroleum Corporation	
3. Address of Operator 105 South Fourth Street, Artesia, NM 88210	
4. Well Location Unit Letter <u>L</u> : <u>1980</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>West</u> line Section <u>25</u> Township <u>20S</u> Range <u>24E</u> NMPM <u>Eddy</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3614'GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL. ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A. ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

2/1/10 – NU BOP. Pulled tubing to fish. POOH with tubing.

2/2/10 – Set a CIBP at 7605' with 35' cement on top. Circulated 280 bbls gelled brine mud. Tested casing to 500 psi, good.

2/5-7/10 – Spotted 35 sx Class "C" cement plug from 5917'-6125' across Wolfcamp and Abo. Spotted 25 sx Class "C" cement plug from 5488'-5637' across DV tool. Spotted 25 sx Class "C" cement plug from 3570'-3720' across Bone Spring. Spotted 25 sx Class "C" cement plug from 1010'-1147' across surface shoe. WOC. Tagged at 1010'. Spotted cement from 102' up to surface.

2/10/10 – Dug up cellar. Cut off all wellheads. Installed dry hole marker as per OCD. Cut off anchors and cover cellar. **WELL IS PLUGGED AND ABANDONED.**

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Tina Huerta*

TITLE Regulatory Compliance Supervisor

DATE February 12, 2010

Type or print name  
**For State Use Only**

Tina Huerta

E-mail address

Received for plugging of well bore only.  
Liability under Federal Resource Conservation and Recovery Act of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms. www.cmnrd.state.nm.us/oecd.

PHONE: 575-748-4168

APPROVED BY:

*[Signature]*

TITLE

DATE 2/15/2010

Conditions of Approval (if any):